

MTC / REPORT / 01
REPORT NO. 35 / 2015



Wholly owned by Cooperatives

KALOL UNIT



PLANT TURNAROUND REPORT

(MARCH – APRIL – 2015)

INDIAN FARMERS FERTILISER CO – OPERATIVE LIMITED

INDEX

1	<u>PREFACE</u>		I	-	V
2	<u>GENERAL DETAILS</u>		VI	-	X
	<u>SECTION</u>	<u>PLANT</u>	<u>PAGE NOS.</u>		
3	<u>MECHANICAL</u>	<ul style="list-style-type: none">• Ammonia Plant• Urea Plant• Offsite & Utility Plant• B&MH Plant	1	-	61
			62	-	113
			114	-	141
			142	-	145
4	<u>INSPECTION</u>	<ul style="list-style-type: none">• Ammonia Plant• Urea Plant• Utility Plant	146	-	200
			201	-	246
			247	-	249
5	<u>INSTRUMENTATION</u>	<ul style="list-style-type: none">• Ammonia Plant• Urea Plant• Offsites & Utility Plant• B&MH Plant	250	-	259
			260	-	267
			268	-	273
			274	-	277
6	<u>ELECTRICAL</u>	<ul style="list-style-type: none">• Ammonia Plant• Urea Plant• Offsites & Utility Plant• B&MH Plant	278	-	280
			281	-	282
			283	-	299
			300	-	301
7	<u>CIVIL</u>	<ul style="list-style-type: none">• Ammonia Plant• Urea Plant• Offsites & Utility Plant• B&MH Plant	302	-	-
			303	-	304
			305	-	306
			307	-	308
8	<u>TECHNICAL</u>	<ul style="list-style-type: none">• Ammonia Plant• Urea Plant• Utility Plant• B&MH Plant	309	-	315
			316	-	317
			318	-	319
			320	-	322

PREFACE

The Annual Plant Turnaround for the year 2015 was taken from 01st of April, 2015 to 12th of April, 2015. In addition to routine Preventive maintenance jobs of Static & Rotary equipments, Statutory IBR inspection, maintenance of Electrical & Instrument systems, Civil related jobs, several major Retrofitting and Replacement jobs in plant were carried out during shutdown.

After ensuring availability of all the required material for shutdown and awarding contracts for various shutdown jobs, it was decided to stop Ammonia Plant and Urea Plant on 01st April 2015. This shutdown report contains Plant wise and section wise details of the jobs carried out. Ammonia plant was re started and regular production was lined up at 15.30 Hrs. on 12th April, 2015. Similarly Urea plant was restarted and production was resumed at 21.50 Hrs. on 12th April, 2015.

Major jobs like overhauling of 101-J Air compressor HP case, 103-JAT Turbine, 115-JB pump , 115-JBT Pump drive Turbine, 107-J/JT and preventive maintenance of other rotary equipment was carried out in Ammonia Plant. Heat exchanger 101-CA Tube Bundle was replaced. In Urea plant preventive Maintenance of Hitachi compressor train was carried out. In LP Carbamate condenser (H-1205) IRIS inspection was carried out, Baffle locking arrangement is provided to arrest flow induced vibrations resulting in tube leakages and leaky tubes were plugged. In Offsite/Utility plants, IBR inspection of BHEL Boiler (GT-2068) was done.

The Turnaround was carried out smoothly due to meticulous planning of all activities like planning of manpower, material and other resources. Due to exemplary efforts put in by all Personnel at all levels, turnaround jobs could be completed before the scheduled period for Ammonia Plant and Urea Plant.

Safety was one of the major aspects, which was given top most priority during the execution of various jobs. All the jobs were carried out considering all safety aspects and the use of safety equipments was ensured during execution of jobs. Necessary training for safe working in the Plant was given to the Manpower employed by all Contractors and strict vigilance was kept by Fire & Safety section during execution of Critical jobs.

Major jobs carried out during shutdown are as under.

MECHANICAL

❖ AMMONIA

- Major overhauling of Syn gas compressor drive turbine 103 JAT
- Major overhauling of Semi lean solution pump drive turbine and Pump (115- JBT & 115-JB)
- Major Overhauling of 101-JHP Air compressor
- Replacement of tube bundle of 101-CA Waste heat boiler.
- Replacement of common minimum flow line of semi lean solution pumps, 115 J & 115 JA and split stream solution pumps, 116 J & 116 JA.
- Major overhauling of Re-cycle gas compressor, 117-J.
- Auxiliary boiler West side wall refractory replaced.

❖ UREA

- Preventive maintenance of LP Case (K-1801-1), HP case (K-1801-2), drive turbine (Q-1801) & Gear box (M-1801) were carried out
- Overhauling of Pilot valve of main steam (60 ata), extraction steam (23 ata) and induction steam (4 ata) and NRV (23 ata).
- Major overhauling of lube oil turbine (Q-1814)
- Replacement of shaft of exhaust air fan, K-1702
- Helium leak detection and repairing of Autoclave V-1201 was carried out.
- Eddy current testing of tubes of H-1201.
- Air testing and Eddy current testing of HP Condenser H-1202 was carried out.
- IRIS inspection of LP Carbamate condenser (H-1205) tubes & Baffle locking.
- Replacement of steam Condensate lines (up to elevation of 75.0 mtr.) in Urea Plant.
- Replacement of existing corroded CS steam tracing lines of High Pressure Lines.
- Replacement and modification in CCS-I line at First Floor.
- Modification in Ammonia Supply Line Loop at 1st Floor.
- Modification in Off Gas RV Platform and Platform behind the HP Scrubber.
- Replacement of both bearing of Prill tower ID Fan (K-1401/1, K-1401/2 and K-1401/4).
- IBR inspection of 4 ata steam drum V-1501.
- LP Vessels inspection was carried out and necessary repairs were undertaken as per inspection findings.

❖ OFFSITE & UTILITY

- Preventive Maintenance of Cooling Water Pumps and Turbines, BFW Pumps and Turbines.
- Preventive Maintenance of FD Fan (K-5113) Train
- Checking & overhauling of FD Fan Dampers.
- IBR inspection of BHEL Boiler (GT-2068)
- Overhauling of 900 MM Discharge I/V of P-4403 and P-4401/C.
- Overhauling of all cooling tower distribution valves.
- Inspection & Repairing of 52" inch CW interconnection tunnel.
- Overhauling of check valve for cooling water pump, P-4411 E
- Insitu refurbishment of gate valve, 900mm NB x 150#, at Pump P-4403 common discharge line (towards Urea plant) and gate valve, 700mm NB x 150#, at Pump P-4403 common discharge line (towards ammonia plant)
- Replacement of Sintex make partition wall in Ammonia 4-5 & 5-6 cooling tower cells.
- Repairing of structural members of cooling towers.
- Welding of SS304 Patch Plate on Jump over line of CW supply header to ammonia CW circuit
- Rerubber lining of stripped process condensate (SPC) unit

❖ **B&MH**

Following jobs were carried out in B&MH.

- Replaced the Complete length of conveyor belt with new oil & heat resistance Conveyor belt in M 2121.
- Installation of tru trac trough rollers for arresting off centering of conveyor belt in M-2110 and M-2112 conveyor.
- Preventive maintenance of all the conveyor gear boxes, weighing machines, packer scales, stitching machines & New Reclaim machine.

INSTRUMENTATION

❖ **AMMONIA**

- Major Instrumentation jobs were carried out for MCC-5 replacement. Junction boxes were installed inside MCC-5, Multi-pair cables were laid & terminated with lugging & ferruling from MCC to DCS Marshalling cabinet & contactor box. Finally checking with operation of Motors was done from Control Room & was found functionally ok.
- Two new transmitters PT-79B & PT-79C were installed with new impulse line tapping to provide 2003 Low surface condenser vacuum turbine trip logic for 101-J/103-J/105-J. Trip logic was modified as per requirement.
- Replaced old control valves MICV-10, TRCV-142A, LCV-16, LCV-18, LCV-19, FICV-20, HICV-435A & VS-203A with new control valves of contemporary design.
- AMC service of DCS/PLC/UPSS and UPSS Batteries were carried out with the help of suppliers' service engineers. Preventive maintenance of CH₄, CO₂ NDIR Analyzer, and H₂ Analyzer was done. Preventive maintenance of control valves and calibration of all quality affecting instruments was carried out.

❖ **UREA**

- Plug and seat of Control valve LICV-1201 having MOC Safurex was replaced with that of MOC HVD1.
- Motor Current Indications were provided on DCS for Scrapper motor M-1402-1 and M-1402-2 and Conveyer motor M-1403-1 as per EWR U-257. Necessary current to current convertors were installed in a Junction Box in MCC-6 and same were connected with DCS with multi-pair signal cable.
- AMC Services of DCS and Nucleonic Level gauges were carried out with the help of supplier's service engineers.
- Calibration of FS-1101 (Ammonia Mass flow meter) was carried out at EQDC, Gandhinagar, as per ISO & CDM requirement.
- Servicing & overhauling of the control valves was done. FICV-1202, FICV-1435 and PICV-1502B control valves were replaced with new control valves of contemporary design. Calibration of all quality affecting instruments was carried out.

❖ **UTILITY AND OFFSITE**

- Major Instrumentation jobs were carried out in Boiler plant for replacement of old MCC interface relay box with new one.
- Liquid Ammonia flow to Rail Gantry line control valve FICV-3101 was installed in Ammonia storage area as a part of EWR / Suggestions implementation.
- Replaced old control valves LCV-01, LCV-02, pHICV-4401& pHICV-4402 (Cooling Tower Plant), BTV-1-4A & BTV-1-4B (Boiler Plant), PICV-5401, MICV-5501 & MICV-5502 (IG Plant) with new control valves of contemporary design.
- AMC service of DCS/PLC/UPSS and UPSS Batteries were carried out with the help of supplier's service engineers. Preventive maintenance of control valves was done. Calibration of all quality affecting instruments was carried out.

❖ **BAGGING PLANT**

- ❖ Road Weigh Bridges and weighing machines were overhauled and calibrated.

ELECTRICAL

• **Critical job/ new installation**

- Replacement of MCC-5
- Replacement of DG set Battery
- Replacement of busbar chamber in MCC-4

• **Scheduled preventive maintenance and modification work**

- Servicing of Jyoti make 11 KV HT Vacuum circuit breaker (VCB) (Total: Nos 30)
- Testing of protective relays in plant & township
- Servicing of Chhabi make battery charger
- Servicing of Rotork make valve actuators(Total: Nos 47)
- Maintenance of transformers(Total: Nos 32)
- Overhauling of critical motors (Total: Nos78)
- Maintenance of Motor control centre MCCs
- Maintenance of 66 KV switch yard
- Servicing of TMG make LT Air circuit breaker (ACB)
- Provision of emergency power to actuators in urea plant
- Provision of current indication at DCS for M-1402/1&2 and M-1403/1
- PGR heater replacement and checking
- Installation of emergency stop PB in M-1402/1 &2 motor
- Maintenance of VFD panels
- Checking of Rope switches in conveyors

CIVIL

❖ AMMONIA PLANT

- Refractory repairing jobs in primary reformer, Secondary reformer & Primary waste heat exchanger. The casting of auxiliary boiler side panels was carried out.

❖ UREA PLANT

- Rehabilitation of Lift room (outside) & stair case at prill tower top by providing elastomeric lining.
- Repairing of prill tower top floor by providing elastomeric lining & replacing acid/ alkali proof bricks carried out.
- Demolishing job of floor behind urea plant for crane approach was carried out to replace LPCC in urea plant.
- Retrofitting of the existing foundations and construction of the additional supports on Ammonia pump line in urea plant.

❖ OFFSITES & UTILITY PLANT

- Replacement of marine plywood sheet in cooling tower deck
- Damaged plywood sheets of the cooling tower deck were replaced with new marine plywood sheets.
- The cooling tower basin outside walls are badly damage and prone to seepage. The outside brickwork & plaster was carried out during the shutdown.
- Excavation of cooling tower header for wrapping & coating of the pipe lines & backfilling including PCC of the header.

❖ B & MH PLANT

- IP Net coating was provided as a rehabilitation measures in Silo, transfer tower & reclaim conveyor gallery (M-2117).
- Rehabilitation of wagon floor (beams, columns & soffit) & dust dissolving tank area of B & MH plant by providing elastomeric lining
- Job of providing Kota stone in transfer tower floors in B& MH after removing old bitumastic lining was carried out.

TECHNICAL

The annual turnaround of about 12 days, provide opportunity to Technical Department to undertake execution of jobs related to EWRs and various modification schemes which require isolation.

Various modification jobs were carried out by Technical Department in Ammonia, Urea and Utility Plants in Annual Turnaround-2015.

All modifications jobs have also resulted in tangible/ in- tangible benefits.

Jobs have been completed within stipulated time because of meticulous planning, procurement of material at right time and also completion of major prefabrication work well before start of the shut down.

As lots of rigging work was involved during execution of above jobs, safety was given top most priority and thus jobs were completed with no unsafe act occurrence.

PLANT TURNAROUND APRIL - 2015

GENERAL - DETAILS

SR. NO. CATEGORY QUANTITY

(A) EQUIPMENT UTILIZED :

IFFCO :

135 T Kobelco	01 No
100 T Kobelco	01 No
55 T TIL RT-760 Tyre mounted mobile Crane	01 No
10 T Escort Lift-N-Shift	01 No
14 T Escort Lift-N-Shift	01 No
03 T Forklift	03 Nos.
05 T Forklift	01 No.
909 Tata (Mini Truck)	01 No

(B) MANPOWER UTILIZED :

(I) IFFCO MANPOWER :

1	Mechanical	}	
2	Mechanical Services	}	Existing
3	Electrical	}	strength
4	Instrument	}	
5	Inspection	}	
6	Civil	}	
7	Kandla (Crane Operator)	}	2 Person

(II) HIRED - CONTRACT MANPOWER :

<u>Sr.</u>	<u>No.</u>	<u>Category</u>	<u>Man days</u>
	1	General Fitter	611
	3	Rigger	741
	4	S.S. Rigger	1548
	5	Fabricator	87
	6	Grinder	122
	7	Gas Cutter	75
	8	IBR Welder	20
	9	Non-IBR Welder	88
	10	Carpenter	44
	11	Mason	44

THE PLANT TURNAROUNDS AT A GLANCE										
SR. NO.	YEAR	PERIOD FROM PRODUCTION TO PRODUCTION								REASON IF ANY
		AMMONIA PLANT				UREA PLANT				
		FROM	TO	DOWN TIME		FROM	TO	DOWN TIME		
				DAYS	HRS			DAYS	HRS	
01	1975	06-05-75	21-05-75	16.00	-	06-05-75	21-05-75	16.00	-	Planned
02	1976	26-03-76	20-04-76	26.00	-	26-03-76	20-04-76	26.00	-	Planned
03	76-77	05-12-76	22-01-77	49.00	-	05-12-76	24-02-77	51.00	-	101-JT B/D
04	1978	21-02-78	15-03-78	23.00	-	21-02-78	25-03-78	31.00	-	101-BJ B/D
05	1979	21-05-79	30-06-79	41.00	-	10-05-79	01-08-79	82.00	-	K-1101/2, 3rd Stage Cylinder
06	1981	12-04-81	10-05-81	29.00	-	08-04-81	12-05-81	35.00	-	101-B Headers Planned
07	1984	01-01-84	25-01-84	25.00	-	01-01-84	25-01-84	25.00	-	Planned
08	1986	19-03-86	03-05-86	45.00	-	04-03-86	01-05-86	59.00	-	Reformer Revamping / HP Scrubber B/D
09	1987	12-04-87	03-05-87	21.00	-	12-04-87	02-05-87	20.00	-	Planned
10	1988	18-04-88	14-05-88	27.00	-	18-04-88	13-05-88	26.00	-	Planned
11	1990	05-02-90	05-03-90	29.00	688.67	31-01-90	07-03-90	35.00	829.00	Planned
12	1991	24-02-91	13-03-91	18.00	429.08	23-02-91	14-03-91	20.00	459.25	Planned
13	1992	03-11-92	03-12-92	30.60	734.91	03-11-92	04-12-92	31.00	744.75	Planned
14	1993	12-09-93	23-10-93	42.00	986.50	12-09-93	29-10-93	47.00	1120.58	Revamp-II
15	1995	14-01-95	27-01-95	14.00	311.34	11-01-95	26-01-95	16.00	352.18	Scrubber H-1203 -B/D
16	1996	14-06-96	13-07-96	30.00	712.00	13-06-96	13-07-96	30.00	694.25	Autoclave V-1201 Leakage
17	1997	12-05-97	17-06-97	35.60	875.00	12-05-97	17-06-97	36.20	870.50	Planned
18	1998	22-04-98	19-05-98	27.50	660.00	20-04-98	19-05-98	30.00	720.00	Planned
19	1999	12-04-99	30-04-99	18.00	434.50	11-04-99	28-04-99	17.00	409.75	Planned
20	2000	03-04-00	27-04-00	24.42	586.25	03-04-00	28-04-00	25.43	610.50	Planned
21	2001	25-03-01	14-04-01	20.90	501.50	25-03-01	15-04-01	21.26	510.25	Planned
22	2002	20-03-02	22-04-02	33.40	801.58	20-03-02	23-04-02	34.31	823.50	Planned
23	2003	28-05-03	25-06-03	28.04	673.00	28-05-03	25-06-03	28.33	679.83	Planned
24	2004	20-05-04	09-06-04	20.00	495.17	20-05-04	09-06-04	20.00	480.25	Planned
25	2005	22-05-05	29-06-05	38.75	930.50	22-05-05	24-06-05	33.85	812.50	Planned
26	2006	31-03-06	06-05-06	35.93	862.42	29-03-06	06-05-06	37.06	889.50	Planned
27	2007	14-04-07	08-05-07	23.72	569.25	14-04-07	05-05-07	21.38	513.0	Planned
28	2008	24-03-08	14-04-08	20.26	486.25	24-03-08	14-04-08	20.40	489.50	Planned
29	2009	16-03-09	10-04-09	25.31	607.33	16-03-09	09-04-09	24.63	591.00	Planned
30	2010	21.03.10	05-04-10	15.07	361.50	21-03-10	05-04-10	15.25	366.00	Planned
31	2011	25-03-11	07-04-11	13.25	318.00	25-03-11	07-04-11	13.12	314.92	Planned
32	2012	28-03-12	13-04-12	16.33	392.00	28-03-12	12-04-12	15.34	368.25	Planned
33	2013	29-03-13	10-04-13	11.88	285	29-03-13	10-04-13	11.91	285.92	Planned
34	2014	26-03-14	28-04-14	33.34	800.25	26-03-14	24-04-14	28.75	689.92	Planned
35	2015	01-04-15	13-04-15	11.95	286.83	01-04-15	12-04-15	11.69	280.50	Planned

SHUT DOWN RELATED CONTRACTS

SR. NO	PLANT	WO NO. & DATE	DESCRIPTION OF JOB	VENDOR'S NAME
1	Mechanical Ammonia	201004151427 10/03/2015	Overhauling and Preventive Maintenance of Rotating Equipments	M/s. Ovi Power Systems Pvt. Ltd, Hyderabad
2	Mechanical Ammonia	201004151148 05/01/2015	Overhauling of Re-cycle Gas compressor, 117-J	M/s. Malhan Enterprises Pvt. Ltd., Ahmedabad
3	Mechanical Ammonia	201004151471 10/03/2015	Critical Fabrication jobs in Ammonia and Offsite Plant	M/s. J&J Engineers, Shertha
4	Mechanical Ammonia	201004151375 26/02/2015	Scaffolding & Blinding/De-blinding jobs during Shut Down-2015	M/s. Shiv Engineering, Vadodara
5	Mechanical Urea	201004151419 07/03/2015	Various Fabrication Jobs during Shutdown	M/s Shree Ganesh Engg
6	Mechanical Urea	201004151418 05/03/2015	Overhauling and Reconditioning of Gate/Globe Valves	M/s Flotec Techno smart
7	Mechanical Urea	201004150965 08/12/2014	Specialised Painting on Structures of Urea Plant	M/s Mohan Paints
8	Mechanical Offsite	201004150938 29/11/2014	Removal of Old Rubber Lining & Making New Rubber Lining	M/s Conveyor Rubber Industries, Ahmedabad
9	Mechanical Offsite	20100415279 03/02/2015	Services for In-situ gland re-packing of valves during annual shutdown-2015	M/s Amrutha Engineering, Mumbai
10	Mechanical Offsite	201004151202 28/01/2015	Insitu Overhauling/Repairing of Gate Valve.	M/s Flotec Technosmart (India) Pvt. Ltd., Surat
11	Mechanical Offsite	201004151204 02/02/2015	Specialised services for Repair & Maintenance of "PAHARPUR" make Cooling Towers	M/s Paharpur Cooling Towers Ltd. Vadodara
12	Mechanical Offsite	201004150939 02/12/2014	Supply and installation of Sintex Make PVC Panel in Cooling Tower Partition wall	M/s Abhay Fabricators, Kalol
13	Mechanical Offsite	201004151080 27/12/2014	Servicing/Repairing of Jash make Sluice Gates	M/s Jash Engg Ltd, Indore
14	Mechanical B&MH	201004141314 04.03.2014	ARC for overhauling of Gabbar make stitching machines	M/s Gabbar Engineering Works, Ahmedabad
15	Mechanical B&MH	201004151289 04.02.2015	Splising and vulcanizing of conveyor belts	M/s J.K.Ruuber works, Ahmedabad
16	Mechanical B&MH	201004150761 31.10.2014	Requirement of skilled Engineer and Technician for Reclaim machine	M/s Elecon EPC Projects Ltd., Vadodara
17	Mechanical B&MH	201004150817 14.11.2014	ARC for providing rubber lining on belt conveyor pulleys	M/s J.K.Ruuber Works, Ahmedabad
18	Inspection	201004150853 14-11-14	ECT of HP Stripper and HP Condenser	M/s Testex NDT(I) Pvt. Ltd., Mumbai

SR. NO	PLANT	WO NO. & DATE	DESCRIPTION OF JOB	VENDOR'S NAME
19	Inspection	201004150874 15-11-14	Insitu-Metallography Work during S/D and as and when required	M/s TCR advanced Engg., Vadodara
20	Inspection	201004130578 15-09-12	Radiography work	M/s NDT Services, Ahmmedabad
21	Inspection	201004140590 11-09-13	NDT Teams for DP Test	M/s S.R. Technical Services, Mumbai
22	Inspection	201004140794 19-10-13	NDT Teams for Thickness Measurement	M/s S.R. Technical Services, Mumbai
23	Inspection	201004140793 18-10-13	NDT Team for Ultrasonic Flaw Detection work	M/s S.R. Technical Services, Mumbai
24	Inspection	201004140767 12-10-13	NDT Team for Magnetic Particle Inspection	M/s NDT Services, Ahmmedabad
25	Inspection	201004160018 15-04-15	ARTIS Inspection of Primary Reformer Tubes	M/s TCR advanced Engg., Vadodara
26	Inspection	201004150877 25-11-14	IRIS Inspection of LPCC(H-1205)	M/s Testex NDT(I) Pvt. Ltd., Mumbai
27	Inspection	201004116011 3 28-04-15	Helium Leak Testing of Autoclave Liner and its weldjoints	M/s Gulachi Engrs, Gaziabad
28	Instrument	201004151185 09/01/2015	Maintenance of Control Valves	M/s Flotec Technosmart (India) Private Limited, Surat
29	Instrument	201004140992 02/12/2013	Hiring of Skilled Instrument manpower for shutdown.	A-Z Instruments Services, Vadodara
37	Electrical Ammonia	201004150920	Installation of MCC-5	M/s A N Electrical
38	Electrical	201004151159	Servicing of Jyoti VCB	M/S Jyoti
39	Electrical	201004150942	Servicing of TMG ACB	M/S Heatex
40	Electrical	201004150954	Servicing of rotork MOV	M/S Rotork
41	Electrical	201004151172	Servicing of chhabi battery charger	M/S Chhabi
42	Electrical 66kv Yard	201004151186	Maint. Of 66KV Yard/11KV SS/	M/S Akron
43	Electrical	201004151477	Relay Testing	M/S Elcon
44	Electrical	201004151173	Maint. Of Transformer	M/S Unique Transformer
45	Electrical	201004140891	Overhauling of LT motors	M/S A N Electrical
46	Electrical	201004150852	Replacement of DG set Battery	M/S Amco shaft
47	Electrical B&MH	201004151271	Installation of Vibro screen	M/s PARIKH ELECTRIC
48	Planning	201004151497 19/03/2015	Assisting IFFCO during plant turnaround / Breakdown jobs	M/s General engg works Bharuch
49	Planning	201004151438 05/03/2015	Opening & Boxed up of heat exchangers	M/s General engg works Bharuch
50	Planning	201004151474 11/03/2015	Hydrojetting Cleaning of Heat Exchangers tubes	M/s Hydro jetting services Ahmedabad
51	Planning	201004151133	Overhauling & Testing of	M/s Flotec technosmart

SR. NO	PLANT	WO NO. & DATE	DESCRIPTION OF JOB	VENDOR'S NAME
		29/01/2015	Safety valves/Relief valves/Pilot operated valves	(india) private limited Surat
52	Planning	201004141309 13/02/2014	Arc for on line leak Sealing Job.	M/s Dynamic meta sealing engineers, Thane
53	Planning	201004150549 08/09/2014	Arc for Painting Jobs.	M/s B chauhan & co Kalol
54	Planning	201004141171 24/JAN/2014	Arc for Carrying out Various hot & cold Insulation Jobs	M/s Khandelwal Insulations Pvt ltd Mumbai - 400083
55	Planning	201004141170 24/01/2014	Arc for Carrying out Various Hot & cold Insulation Jobs	M/s Balaji Insulation India Pvt ltd Thane-west - 400607
56	Planning	201004151074 20/12/2014	Arc For Various Fabrication Work In Plant	M/s Aneesh engineers Kalol
57	Planning	201004151075 20/12/2014	Arc For Various Fabrication Work In Plant	M/s J&J engineers Shertha
58	Planning	201004131192 25/01/2013	Arc for Petty Maint. Jobs.	M/s J&J engineers Shertha
59	Civil Urea plant	201004141515 27/03/2014	Repairing of the scrapper floor of prill-tower by providing elastomeric lining and replacement of acid / alkali proof bricks.	M/s Greensboro Polychem Pvt Ltd.
60	Civil B & MH Plant	201004141517 27/03/2014	Repairing of damaged RCC structure of B & MH plant .	M/s Greensboro Polychem Pvt Ltd.
61	Civil B & MH Plant	201004141486 24/03/2014	Providing and applying IP net protective coating on RCC structures of Silo, B & MH plant area, Conveyor Gallery, Prill-Tower and others area in plant	M/s Krishna Conchem Products Pvt Ltd.
62	Civil Utility Plant	201004141512 27/03/2014	Maintenance of damaged water proof plywood sheet in cooling tower deck .	M/s Sudama Furniture Products Pvt. Ltd
63	Civil	201004141397 15/03/2014	Miscellaneous Civil work in plant during shutdown 2014-15	M/s Rakesh S. Prajapati
64	Civil Urea & Offsite	201004141363 13-02-2014	Fixing charges of HILTI made anchor fastners for the strengthening of platform in urea plant .	M/s Nine Projects Pvt. Ltd.
65	Technical	201004151348 16/02/2015	Supply and installation of Urea feeding system in Silo	M/s Thermal Alliance
66	Technical	201004151494 13/03/2015	Erection of vibrating screens and Fabrication job of structure & Piping	M/s Shiv Engg

MECHANICAL

AMMONIA PLANT

(MECHANICAL)

AIR COMPRESSOR TRAIN (101-J)

101-JT, Air Compressor Drive Turbine

Turbine was decoupled and both end Journal bearings and Thrust bearing were removed for inspection. The bearings were visually inspected & found in good condition. Gauss readings of the bearing pads & shaft journal were measured and found within limits. Bearing clearances were taken and found within the design range.

Governor of 101 JT was remaining hot during normal operation. Governor was opened for overhauling. It was observed that the bearing (No 7309 BECBJ, #2) was rubbing with Governor Valve Body (#5) due to which groove was found in Governor valve body. The new bearings were assembled as per drawing. Governor Valve Body was also replaced with new one.



Groove was found
in Governor valve
body

Turbine hydraulic trip assembly was opened and cleaned. O-ring (#21) was replaced. Linkage of Governing valve was opened and overhauled. Bushing of Governing valve lever was replaced with new one.

Parts replaced in 101 JT				
Sr. No.	Part No.	Part Name	Qty.	Store Code
1	2	ND Ball bearing (7309 BECBJ) Bottom bearing	1	2010112510402600
2	5	GOVERNER BODY HC.250LX3 P.NO 5, D.NO:01-AK-08018, 8-1/2 CM GOV OF 101-JT	1	2010112510405400
3	21	O-RING, SYM. NO:11 021(329328) , P.NO :21,D.NO : F-10761, FOR HYDRAULIC TRIP ASSY, FOR 101-JT	1	2010112510739500
4	687	BUSHING, SYM. NO.HJ-215E NOZZLE VALVE AND OPERATING GEAR ASSY	2	2010112510307340

101-JLP, Air Compressor

101-JLP was decoupled from both ends. Journal bearings and Thrust bearings were visually inspected and Dye penetration was also carried out. Gauss reading of the bearing pads and base rings were measured and found within limits. Bearing clearances were taken and found within the design range. The entire bag filters as well as Roll-O-Matic filters were replaced by new one during start up.

101-JR, Gear Box

101-JR was decoupled at both ends. All the bearings were inspected and found in good condition. Both the gear as well as Pinion were inspected and found to be O.K. Gauss measurement of gear shaft and bearings carried out and found within limit. Bearing clearances were taken and found within the design range.

101-JHP ,Air Compressor Major overhauling


The compressor was taken for major overhauling due to air leakage from both ends. The compressor was decoupled and the piping removed. The top casing was removed and all axial and diametrical clearances were measured and noted. The rotor assembly was lifted and taken for cleaning & inspection. Thick deposits were observed on both end seals.

The complete rotor assembly was cleaned by hydro jetting and dye penetration test was performed and no defects were observed. The top and bottom casing were cleaned by hydro jetting followed by drying by plant air. The diaphragms were not removed.

Clearance of both shaft end seals and one no. diaphragm seal of intermediate discharge end (4th wheel) were higher and hence replaced with new one.



After removal of Top half of casing



End seal at coupling end



101 JHP Compressor rotor after cleaning

Parts replaced in 105 JHP			
Sr. No.	Store Code	Description	Qty
1	2010112010247800	CASE SEAL,P.NO:11,SYM. NO:AF 2041-CZ, FOR 101 JHP(MODIFIED)	1
2	2010112010247810	CASE SEAL.P.NO 12,SYM. NO: AF 2041 CS, FOR 101 JHP(MODIFIED)	1
3	2010112010247831	DIAPHRAGM SHAFT SEAL, P.NO : 15, SYMBOL NO CG 4006 E ,FOR 101 JHP COMP. (MODIFIED,AF-4004-R)	1

The journal bearing clearances were measured on mandrel and found within the design range. The journal & thrust bearing pads and their base rings were dye penetration checked and no defects were found. Gauss measurement was carried out on the complete rotor assembly as well as the bearings and the values obtained were within limit.

The rotor assembly was lifted and placed inside the bottom casing with bearing in place. The axial and diametrical clearances were measured and noted. The top casing was boxed up and the rotor end float was measured and found within limit.

Couplings Inspection

All the couplings were visually inspected. Wherever coupling hub locknuts have been provided, the nuts were found intact. The flexible elements were also found to be in good condition.

CLEARANCE CHART -101-JT

Description	Position	Dwg. Ref	Design Clearances (Inch)	Before (Inch)	After (mm)
JLP End					
Journal Bearing	Mandrel	B	0.007-0.009		0.19
	Filler / lead wire				
Oil Guard (For Jr. Brg Housing)	South	C	0.015-0.021		0.40
	North	G	0.058-0.097		0.40
Oil Guard (For Seal Housing)	---	D	0.077-0.109		0.20
Shaft Diameter	Jr. Brg.	---	4.993		-
Bearing Pinch	Jr. Brg.	---	---		0.02
Governor End					
Journal Bearing	Mandrel	B	0.007-0.009		0.19
	Filler / lead wire				
Oil Guard (For Brg. Housing	South	---	---	---	--
	North	C	0.015-0.021		0.20
Axial Thrust.	With Top Housing	---	0.008-0.012	0.36	0.36
	Without top Housing	---			
Bearing Pinch	Jr. bearing	---	---		0.01

Journal Bearing Pads Thickness - 101 – JT

PAD	NORTH SIDE BEARING	SOUTH SIDE BEARING
No 1	0.8113	0.8138
No 2	0.8114	0.8138
No 3	0.8114	0.8146
No 4	0.8114	0.8146
No 5	0.8114	0.8134

Thrust Bearing Pad Thickness - 101 – JT

Pad	ACTIVE	INACTIVE
No 1	0.498	0.916
No 2	0.5004	0.913
No 3	-	0.914
No 4	-	0.911
No 5	-	0.916

CLEARANCE CHART - 101 – JLP

Description	Position	Design Clearances (Inch)	Before (Inch)	After (mm)
101-JT END				
Journal Bearing Clearance	Mandrel	0.005-0.008		0.19
Bearing Pinch				0.01
Oil Guard (For Journal Bearing)	North	0.013-0.015		0.20
	South	0.013-0.015		0.20
Oil Guard (For Outer Housing)	North	0.021-0.027		-
	South	0.021-0.027		-
Gear Box End				
Journal Bearing Clearance	Mandrel	0.005-0.008		0.28
Oil Guard (For Journal Bearing)	North	0.013-0.015		0.20
	South	0.013-0.015		0.20
Oil Guard (For Thrust bearing)	North	0.002-0.004		0.10
	South	0.002-0.04		0.10
Axial Thrust	With Top Housing	0.010 - 0.015		0.45

Journal Bearing Pads Thickness - 101 – JLP

Pad	NORTH SIDE BEARING	SOUTH SIDE BEARING
No 1	0.751	0.750
No 2	0.752	0.751
No 3	0.752	0.750
No 4	0.752	0.751
No 5	0.752	0.750

Thrust Bearing Pad Thickness - 101 – JLP

Pad	ACTIVE	INACTIVE
No 1	0.781	0.781
No 2	0.781	0.781
No 3	0.782	0.781
No 4	0.781	0.781
No 5	0.783	0.781
No 6	0.781	0.781
No 7	0.781	0.781
No 8	0.781	0.781

CLEARANCE CHART - 101-JR

Description	Position	Design Clearances (Inch)	Before (mm)	After (mm)
Journal Bearing (Low Speed drive gear)	North	0.008-0.010		0.27
	South	0.008-0.010		0.27
Axial Thrust	---	0.014-0.024	0.35	0.32
Journal Bearing (High Speed driven Pinion)	North	0.009-0.011		0.26
	South	0.009-0.011		0.24
Backlash	---	---	0.50	0.50
Shaft Diameter (Low Speed drive Gear)	---	---		114.10
Shaft Diameter (High Speed drive Gear)				88.74

CLEARANCE RECORDS – 101JHP-

Description	Position	Design Clearances (Inch)	Before (mm)	After (mm)
GB End				
Journal Bearing Clearance	Mandrel	0.004-0.007		0.21
Bearing Pinch				0.02
Shaft Dia.	Journal Bearing	2.996		76.0
Oil Guard (For Journal Bearing)	North	0.013-0.016	0.15	0.15
	South	0.013-0.016	0.10	0.10
Oil Guard (For Top Housing)	North	0.015-0.022		-
	South	0.015-0.022		-
Non Drive End				
Journal Bearing Clearance	Mandrel	0.004-0.007	0.17	0.17
Bearing Pinch				0.02
Shaft Dia	Journal bearing	2.996	76.0	76.0
Oil Guard (For Journal Bearing)	North	0.013-0.016	0.20	0.20
	South	0.013-0.016	0.15	0.15
Oil Guard (For Thrust bearing)	North	0.002-0.004		
	South	0.002-0.04		
Oil Guard (For Top Housing)	North	-----		
	South	0.015-0.022		
Axial Thrust	With Top Housing	0.008 - 0.012	0.32	0.32
Total Float		2.779-3.571		2.859"


Journal Bearing Pads Thickness - 101 – JHP

PAD	NORTH SIDE BEARING (inch)	SOUTH SIDE BEARING (inch)
No 1	0.5614	0.5614
No 2	0.5614	0.5614
No 3	0.5614	0.5614
No 4	0.5614	0.5614
No 5	0.5614	0.5614

Thrust Bearing Pad Thickness - 101 – JHP

Pad	ACTIVE	INACTIVE
No 1	0.499	0.498
No 2	0.500	0.496
No 3	0.499	0.498
No 4	0.498	0.498
No 5	0.500	0.498
No 6	0.500	0.498

101-JT TO 101-JLP





NOTE : Fixture mounted on JT, Dial reading on JLP, All Readings are in mm.



101-JLP TO 101-JR

Silo side

CT **BEFORE**



AFTER






NOTE: Fixture mounted on JLP, Dial reading on Gearbox, All Readings in mm.

101-JR TO 101-JHP

Silo side

CT **BEFORE**





NOTE : Fixture mounted on JHP, Dial reading on Gearbox, All Readings in mm.

SYNTHESIS GAS COMPRESSOR TRAIN, 103-J

103-JBT, Condensing turbine

The turbine was decoupled. Thrust bearing and both end Journal bearing were visually inspected and found O.K. Magnetism level of both end journal bearing pad and base ring, shaft journal area, thrust bearing and thrust collar was measured and found within limit. All pads were Dye Penetration tested and no cracks were found. The governor linkages were greased.

103-JLP, Synthesis Gas Compressor

The non thrust end journal bearing was removed and the clearance was measured and found to be within limit.

The axial thrust measured and found at 0.26 mm. Magnetism level check of the removed bearings was carried out and found to be satisfactory. Dye penetration test was performed and the result was found to be OK.

103-JHP, Synthesis Gas Compressor

The compressor was decoupled. Coupling end Journal bearing was removed and visually inspected and found O.K. Thrust bearing ring at Free end was removed and cleaned. Thrust was checked. Magnetism level of the bearings were checked and found within limit. All the removed pads were Dye Penetration tested and found to be OK.

103-JAT (Back Pressure Turbine) Overhauling

Turbine was taken for overhauling as per schedule. There was also leakage through steam chest cover which was also to be attended.

Dismantling of Turbine

Turbine was decoupled at both ends. Both journal bearing clearances and axial thrust was recorded and alignment readings were taken. Turbine steam outlet pipe and steam chest valve was removed. Turbine casing was removed and labyrinth clearances were noted. (Data sheet is attached). Rotor along with inner casing was removed. Then rotor was removed from inner casing by keeping it horizontal.. HP gland clearances were above design value.

Gauss measurement of casing, inner casing, rotor and bearings were carried out.

Re assembly of Turbine

Turbine parting plane was cleaned and polished by oil stone. Rotor was assembled in inner casing with new HP Gland labyrinth rings (#146, #148, #149). Rotor along with inner casing kept in the bottom half and clearances were noted. Guard (#296) was replaced as it ends were damaged. Casing was assembled and tightened. Thrust ring was replaced with new one

Steam chest Valve

Steam chest valve was opened to attend leakage through cover. Steam chest cover and flange was cleaned, and then Blue match was checked by assembling. It was found OK.

Both Bearing (2 nos) and end plates (4 nos) of Governing valve lever was replaced with new one.



Assembly of top casing

Parts replaced in 103 JAT			
Sr. No.	Store Code	Description	Qty
1	2010112540204100	SHOES (SET OF 6) ,SYM. NO:PM-1031AB, FOR103-JAT	1
2	2010112540234200	LABY.RING SYM.NO: GJ-141 AZ X1,P. NO:146, FOR 103-JAT	1
3	2010112540234220	LABY.RING SYM.NO: GJ-141 AZ X 3,P. NO:148, FOR 103-JAT	1
4	2010112540234230	LABY.RING SYM.NO: GJ-141 AZ X 4,,P. NO:149, FOR 103-JAT	1
5	2010112540245240	RING BEARING GJ-1189P,P.NO:288 FOR 103-JAT	1

6	2010112540403400	BRG, P.NO:648 SYMBOL 315519 FOR 103-JAT	2
7	2010112540407320	BUSHING, SYM.:KJ-215E,P.NO :646 D.NO :F-9162,FOR NOZ VALVE & OPT GEAR ASSY 103-JAT	4
8	2010112540624710	GASKET ANNEALED COPPER PLAIN RING GASKET OD :342MM, ID:307MM X THK.:1.5MM , SPARES FOR STRAINER OF 103-JAT	1
9	2010112549947530	ALLEN HEADED F/T BOLT FOR THURST & J BRG D.NO. P1-ES-20010, 3/4" DIA X 10 TPI X 58 L FOR 103 JAT	10
10	2010112549947530	ALLEN HEADED F/T BOLT FOR THURST & J BRG D.NO. P1-ES-20010, 3/4" DIA X 10 TPI X 58 L FOR 103 JAT	10

PREVENTIVE MAINTENANCE RECORDS: 103 – JBT

Description	Position	Clr. Chart Ref	Design Clearances (Inch)	Actual (inch)
JAT End				
Journal Bearing	Lead Wire	A	0.010-0.012	0.01102
Oil Guard (For Jr. Brg Housing)	South	C	0.008-0.014	0.00590
Bearing Pinch	Journal Brg.			0.00078
Governor End				
Journal Bearing	Lead Wire	A	0.010-0.012	0.00984
Oil Guard (For Brg. Housing)	North	C	0.008-0.014	0.00590
Axial Thrust.	With Top Housing		0.008-0.012	0.00984
Bearing Pinch	Journal Brg.			0.00039

THRUST BEARING PAD THICKNESS

DESCRIPTION	ACTIVE	NON-ACTIVE
PAD NO. 1	0.624	0.500
PAD NO. 2	0.625	0.500
PAD NO. 3	0.624	0.500
PAD NO. 4	0.625	0.500
PAD NO. 5	0.625	0.500

PREVENTIVE MAINTENANCE RECORDS: 103 - JAT

Description	Position	Clr. Chart Ref	Design Clearances (Inch)	After (Inch)
JLP End				
Journal Bearing	Lead Wire	N	0.006-0.008	0.00669
Oil Guard (For Jr. Brg Housing)	South	C	0.015-0.021	0.00590
	North			0.00393
Bearing Pinch	Journal Brg.			0.00078
JBT End				
Journal Bearing	Lead Wire	B	0.010-0.012	0.0098
Oil Guard (For Brg. Housing)	North	C	0.015-0.021	***
Axial Thrust.	Without Top Housing	---	0.008-0.012	0.0118
Total Float				0.1811
Bearing Pinch	Journal Brg.			0.00078
Oil Guard (For Thrust Bearing)	North	A	0.002-0.004	***
	South	A	0.002-0.004	***

THRUST BEARING PAD THICKNESS

DESCRIPTION	ACTIVE	NON-ACTIVE
PAD NO. 1	0.998	0.624
PAD NO. 2	0.998	0.624
PAD NO. 3	0.997	0.624
PAD NO. 4	0.997	0.624
PAD NO. 5	0.998	0.624
PAD NO. 6	0.998	0.624


PREVENTIVE MAINTENANCE RECORDS: 103 – JLP

Description	Position	Clr. Chart Ref.	Design Clearances (Inch)	Before (Inch)	After (mm)
NON THRUST END					
Journal Bearing Clearance	Mandrill	C1	0.002"-0.004"		0.08
Oil Guard (For Journal Bearing)	North	C2	0.008"- 0.013"		
	South	C2	0.008"- 0.013"		
THRUST END					
Journal Bearing Clearance	Mandrill	C1	0.002"-0.004"		
Axial Thrust	With Top Housing		0.015"-0.022"	0.25	0.25

PREVENTIVE MAINTENANCE RECORDS: 103 – JHP


Description	Position	Clr. Chart Ref.	Design Clearances (Inch)	Before (Inch)	After (mm)
NON THRUST END					
Journal Bearing Clearance	Mandrill	A1	0.0023"-0.0033"		0.09
Oil Guard (For Bearing)	North	A2	0.0085"- 0.0115"		
	South	A2	0.0085"- 0.0115"		
THRUST END					
Journal Bearing Clearance	Mandrill	A1	0.0023"-0.0033"		
Axial Thrust	With Top Housing		0.015" - 0.022"	0.40	0.40

ALIGNMENT VALUE 103 JBT TO 103 JAT




Note: Fixture mounted on JBT, Dial mounted on JAT, All Readings are in mm.

103 JAT TO JLP



Note: Fixture mounted on JAT, Dial mounted on JLP, All Readings are in mm.

103 JLP TO JHP



Note: Fixture mounted on JLP, Dial reading on JHP, All Readings are in mm.

REFRIGERATION COMPRESSOR TRAIN 105-J

105-JT, Refrigeration Compressor Drive Turbine Preventive Maintenance

Turbine was decoupled and both ends Journal bearings and Thrust bearings were taken for inspection. Gauss readings of the bearing pads were measured and found within limits. The pads were visually inspected as well as dye penetration tested and found OK. Bearing clearances were taken and found within the design range.

105-JLP Refrigeration Compressor

105-JLP, gear box end was decoupled. Axial thrust was measured (0.27 mm) and found within limit.

105-JR Gear Box

After decoupling the top cover was removed. All the bearings were inspected and found in good condition. Both the gear as well as Pinion were inspected and found to be O.K. Magnetism level of gear/pinion shaft and their bearings was carried out and found within limit. Bearing clearances were taken and found within the design range.

105-JHP Refrigeration Compressor Preventive Maintenance

105-JHP, gear box end was decoupled. Axial thrust was measured (0.46 mm).

All couplings were visually inspected. No damage in flexible elements was observed all the hubs were found to be in their position intact.

105-JT CLEARANCES

Description	Position	Design clearance	Actual Clearance
JLP End			
Journal Bearing	Lead wire	0.007"-0.009"	0.0094"
Oil Guard (For Jr. Brg Housing)	South	0.015"-0.021"	0.0039"
	North	0.058"-0.097"	0.0039"

Oil Guard (For Seal Housing)	***	0.077"-0.109"	
Governor End			
Journal Bearing	Lead wire	0.007"-0.009"	0.0086"
Oil Guard (For Seal Housing)	***	0.077"-0.109"	0.0059"
Axial thrust	With Top Housing	0.008"-0.012"	0.011"

Journal Bearing Pad Thickness

Pad	North Side Brg.	South Side Brg.
No.1	0.811811"	0.811811"
No.2	0.811023"	0.811417"
No.3	0.811417"	0.811023"
No.4	0.811811"	0.811811"
No.5	0.811811"	0.811417"

Thrust Bearing Pad Thickness


Pad	Active	Inactive
No.1	0.7511"	0.62755"
No.2	0.7511"	0.62716"
No.3	0.7507"	0.62716"
No.4	0.7507"	0.62755"
No.5	0.7818"	0.62716"
No.6	0.7507"	0.62716"

105-JR CLEARANCES


Description	Position	Design clearance	Actual Clearance
Journal Bearing	North	0.014"-0.016"	0.0133"
	South	-do-	0.0133"
Axial thrust		0.014"-0.024"	0.0153"
Journal Bearing	North	0.013"	0.0165"
	South	-do-	0.0165"
Free Float		--	0.059"
Backlash		--	0.49/0.50mm
Shaft diameter	North	--	4.9921"
	South	--	4.9921"
Shaft diameter	North	--	4.4937"
	South	--	4.4937"
Thrust Float.		--	

ALIGNMENT VALUES – 105-JT TO 105-JLP

BEFORE




AFTER




Note: Fixture mounted on Turbine Rotor, Dial reading on JLP, All Readings are in mm.

105-JLP TO 105-JR

BEFORE




AFTER




Note: Fixture mounted on LP Rotor, Dial reading on JR, All Readings are in mm.

105-JR TO 101-JHP

BEFORE



AFTER



Note : Fixture mounted on JR, Dial reading JHP, All Readings are in mm.

INDUCED DRAFT FAN 101-BJ TRAIN

101- BJ Fan

Journal bearings and thrust bearings were inspected and found O.K. Gauss reading was taken and found below maximum allowable limit. All the bearing pads were Dye Penetration tested and no cracks were found Bearing clearances were taken and found within the design range. Water was circulated in lines and no leaks were observed. The final bearing clearance was measured and found within design range.

101- BJT

101 BJT and Gear box were taken for PM for the first time after installation. The turbine was decoupled and both ends bearing housing opened. The thrust bearing and both ends radial bearings clearance were measured and found within limit. The bearing pads were visually inspected and DP inspected and found OK. The gauss measurement was taken and found within acceptable limit. The PGPL actuator drive gear was checked and oil was flushed.

101-BJR Gear box

The top cover of GB was removed. The bearings were dye penetraton inspected and no defects were observed. Gauss measurement for the bearings was also carried out and found within limit. Gear backlash and bearing clearance was measured and found within limit.

All couplings were visually inspected and found OK.

Removal of MOP

MOP on Gear box was damaged in May 2014 during normal operation of the Plant and the pump was in operation with failure condition. MOP was removed and it was observed that the internals were broken and pump was worn out badly.

M/s KEPL had supplied new pump on Free of Cost basis. Lock washer was installed on back cover of the new pump to prevent loosening of bolts and it was installed in GB. The pipe lines which were provided for additional motor driven pump during May 2014 was removed and piping was installed as per the original installation. Additional motor driven pump was isolated. Spring in the existing NRV at suction of MOP was removed as per recommendation of M/s KEPL.

However during start up on 11.04.2015 with AOP in line, MOP was getting heated up (Turbine speed – 1000 RPM appx) and the pump was not developing the required Pressure . Temporary tubing was provided from PG tapping at discharge of MOP to LO Tank and the temperature of MOP came down to normal. (AOP Dis Pr – 7.5 Kg/cm²).

Since the operation of MOP was not reliable, it was decided to remove the MOP after stopping turbine. Additional motor driven pump was taken inline and the piping connections were installed back as per requirement.

After start up, abnormal sound was observed from Turbine coupling end bearing. Hence this bearing was opened during this opportunity. It was checked and found OK.

101 BJ Train was again started and found OK.



Damaged internal of MOP

BEARING CLEARANCES : 101-BJT

Description	Position	Design clearance	Clearance After (mm)
GB End			
Journal Bearing	Lead wire	0.18 – 0.25	0.30
Oil Guard (For Jr. Brg Housing)	CT side	0.25 – 0.37	0.15
	Silo side	0.25 – 0.37	0.15
Bearing Pinch	***	***	0.01/0.02
Governor End			
Journal Bearing	Lead wire	0.18 – 0.25	0.25
Oil Guard (For Jr. Brg Housing)	CT side	0.25 – 0.37	0.15
Axial Thrust	w/o top hsg		0.31
Bearing Pinch	***	***	0.01/0.02

Journal Bearing Liner Thickness

Liner	CT Side Brg.	Silo Side Brg.
Top	3.18 mm	3.18 mm
Bottom	3.18 mm	3.18 mm

101-BJR CLEARANCES

Description	Position	Design clearance	Actual Clearance
Journal Bearing (High Speed Shaft)	CT side	0.10-0.14	0.13
	Silo side		0.12


Axial thrust (Low Speed Shaft)		0.20-0.28	0.28
Journal Bearing (Low Speed Shaft)	CT side	0.14-0.19	0.19
	Silo side		0.17
Free Float		--	0.060"
Backlash		0.30-0.50	0.35
Shaft diameter (High Speed drive pinion)	CT side	--	99.93
	Silo side	--	99.90

BEARING CLEARANCES : 101-BJ


Description	Position	Design clearance	Actual Clearance mm
Gear Box End-BJ			
Journal Bearing	Lead wire	0.008"-0.012"	0.35
Free End-BJ			
Journal Bearing	Lead wire	0.008"-0.012"	0.30

ALIGNMENT VALUES – 101-BJT TO 101-BJR

BEFORE




AFTER




Note: Fixture mounted on Turbine Rotor, Dial reading on GB, All Readings are in mm.

101-BJR TO 101-BJ

BEFORE



AFTER



Note : Fixture mounted on GB, Dial reading on Fan, All Readings are in mm.

SEMILEAN SOLUTION PUMP115-JA TRAIN

115-JA Semilean Solution Pump

The pump was decoupled and both ends bearing housing opened. The thrust bearing and both ends radial bearings clearance were measured and found within limit. The bearing pads were visually inspected and DP inspected and found OK. The gauss measurement was taken and found within acceptable limit. The suction strainer was cleaned.

Oil of LO console was removed and filled with new oil as bearing shell & housing were found to be having rust.

115- JAT

The turbine was decoupled and both ends bearing housing opened. The thrust bearing and both ends radial bearings clearance were measured and found within limit. The bearing pads were visually inspected and DP inspected and found OK. The gauss measurement was taken and found within acceptable limit.

The turbine was having problem of speed variation during normal operation. Service Engineer from M/s KEPL was called for attending the problem. Governing valve was opened. The Valve stem was bent (Runout - 0.3 mm) which was straightened and

provided as there was no spare available. Packings were replaced with new one. Actuator filter was cleaned and the actuator was flushed with oil SERVO ULTRA 40. As per KEPL, greasing is to be done only on rod end bearings and greasing is not required to be done on linkages as the turbine is in open area.

The condition of TB woods coupling sleeve was not good and hence replaced with new one issued from Stores. The condition of the existing coupling sleeve of 115 JBT was good and it was reused. The following differences were observed in the coupling sleeves:

Parameter	115 JAT existing sleeve & new sleeve's issued from store	115 JBT
OD(mm)	48	50.5
Width (mm)	25.5	27
Hardness Shore A	80	65

115-JAR Gear Box

Gear Box was opened and all the bearings were inspected and found O.K. Both the gear as well as Pinion were inspected and found to be O.K. Gauss measurement of gear shaft and bearings carried out and found within limit. Bearing clearances and backlash were measured and found within the design range. The main oil pump drive coupling was inspected and found in good condition. The oil pipings were cleaned with air.

Hydraulic Turbine 115-HT

The hydraulic turbine was decoupled. The thrust bearing and both ends radial bearings clearance were measured and found within limit. The bearing pads were visually inspected and DP inspected and found OK. The gauss measurement was taken and found within acceptable limit.

Clutch

Top cover of clutch was opened and cleaned. Sight glass was also cleaned. The hydraulic turbine to clutch alignment readings were measured and recorded. Turbine to clutch coupling was done.

COLD CLEARANCE TOLERANCES – 115-JAT

Sr. No	DESCRIPTION			DESIGN (INCH)		ACTUAL (INCH)	
				MIN	MAX		
1	CARBON RING DIAMETRAL			.0070	0.0085	STM. END	EXT. END
						0.007	0.007
2	JOURNAL BEARING DIAMETRAL			.0035	.0080	STM. END	EXT. END
						0.0098	0.0094
3	OIL GLAND COUPLING SIDE	Inboard	Radial	0.0100	0.0125	0.0047 / 0.0047	
4			Axial	0.040	0.050	0.0748 / 0.0669	
5		Outboard	Radial	0.0100	0.0125	0.0059 / 0.0059	
6			Axial	0.080	0.090	0.1614 / 0.1496	
7	OIL GLAND	Radial		0.0100	0.0125	0.0059 / 0.0047	
8	GOVERNING SIDE	Axial		0.030	0.040	0.0346 / 0.0503	
9	END THRUST			0.010	0.012	0.009	

Journal Bearing Pads Liner Thickness 115-JAT

PAD	NORTH SIDE (Inch)	SOUTH SIDE (Inch)
Upper	0.1157	0.1141
Lower	0.1141	0.1141

Thrust Bearing Pad Thickness: 115-JAT

Pad No.	Active (Inch)	Inactive (Inch)
No. 1	0.687	0.688
No. 2	0.686	0.686
No. 3	0.687	0.687
No. 4	0.687	0.687
No. 5	0.686	0.686
No. 6	0.687	0.687

CLEARANCE RECORD: 115-JA

Description	Design Clearances (Inch)	Actual Clearances (Inch)
Journal bearing (Thrust end)	0.005-0.0098	0.0070
Journal bearing (Non thrust end)	0.005-0.0098	0.0066
Axial Thrust	0.013 – 0.015	0.011

Thrust Bearing Pad Thickness: 115-JA

Pad No.	Active (Inch)	Inactive (Inch)
No. 1	1.2500	1.2500
No. 2	1.2503	1.2496
No. 3	1.2403	1.2492
No. 4	1.2411	1.2496
No. 5	1.2500	1.2500
No. 6	1.2500	1.2500
No. 7	1.2503	1.2496
No. 8	1.2507	1.2500

CLEARANCE CHART: 115-HT


Description	Design Clearances (Inch)	Actual Clearances (Inch)
Thrust end bearing	0.0048-0.0058	0.0051
Opp Thrust end bearing	0.0048-0.0058	0.0062
Axial Thrust	0.010-0.011	0.011

Thrust Bearing Pad Thickness: 115-HT


Pad No.	Active (Inch)	Inactive (Inch)
No. 1	0.742	0.744
No. 2	0.742	0.743
No. 3	0.743	0.743
No. 4	0.742	0.743
No. 5	0.741	0.744
No. 6	0.741	0.743

115-JAT TO 115-GB

BEFORE




AFTER




Note : Fixture mounted on Turbine, Dial reading on Gear box, All Readings are in mm.

115-GB TO 115-JA

BEFORE




AFTER




Note: Fixture mounted on Pump, Dial reading on GB, All Readings are in mm.

115-HT TO CLUTCH:

BEFORE



AFTER



Note: Fixture mounted on pump, Dial reading on Clutch, All Readings are in mm.

SEMILEAN SOLUTION PUMP115-JB TRAIN

Major Overhauling of SEMILEAN PUMP 115-JB


The 115 JB was taken for major overhauling for the first time after its installation on May 2005. The turbine was decoupled and both ends bearing housing opened and bearing clearances measured for records. Both end bearings were removed along with the housing. Both ends mechanical seals were locked and removed. The casing was unbolted and the top casing removed. The bearing shell & housing were found to be having rust. Hence the oil console was cleaned and filled with new oil.

The thrust bearing and both ends radial bearings clearance were measured and found within limit. The bearing pads were visually inspected and DP inspected and found OK. The gauss measurement was taken and found within acceptable limit.

The wear rings and throat bush clearances were measured. The throat bush clearances as well as DE & NDE wear ring clearances were found OK.

The rotor was placed inside the casing. The casing was lowered and a new parting plane gasket was provided. While cutting of gasket care was taken to keep gasket end portion (in contact with mechanical seal & around it) was kept extended by around 5 mm. The casing was tightened and this extended portion of gaskets at both ends was cut using a blade. Both ends new refurbished mechanical seals installed. The mating faces of ring/u cup were available in two materials i.e. durafon & viton. It was observed that on installation durafon seal, the mechanical seals were leaking while being tested in workshop using testing tool. Hence the mechanical seals were assembled with viton seals. The seal were tested using DM water and no leakage was observed.

Both end bearing housing along with housings were also installed. The bearing clearances were measured and noted. The pump to GB alignment readings were measured and recorded.



The bearing shell & housing of pump were found to be having rust



115-JB after removal of top casing

115- JBT Major overhauling

The turbine was taken for major overhauling for the first time after its installation on May 2005. Turbine was decoupled and exhaust line was removed. The top casing was removed and all axial as well as radial clearances were measured. The bearings were removed for inspection. Rotor assembly was taken out and it was observed that the 5th stage blades was having deposits and it was choked badly. Sand blasting of rotor was carried out by M/s B Chauhan. All diaphragms were taken out for cleaning. All inter-stage labyrinths were also taken out and new labyrinths were installed. (Procured from M/s Prabhu Engineering, Hyderabad)

The rotor was reinstalled & all axial as well as radial clearances were measured. New carbon rings installed. The bearing clearance of free end side was on higher side and hence replaced with new one. Bearing liner of coupling end was visually inspected and DP check carried out and found satisfactory. The magnetism level of the bearings and rotor assembly was checked and found within acceptable limit.

An additional flange joint was provided in the Exhaust line of turbine (Fabrication done by M/s J & J Engg.) for easy removal during Overhauling.

Steam inlet pipe, exhaust pipe and all other related piping were boxed up.

Oil of TG13 E actuator was flushed. Coupling sleeve of governor was found in good condition and hence re used.

The turbine was taken for a slow roll . The speed was increased by 1000 RPM , maintained for 5-10 min. Then reduced by 500 RPM and maintained for 5-10 min. Proper care to be taken to speed up the turbine in the range of critical speed. This procedure ensured proper lapping of the carbon rings. The turbine tripped at 5881 RPM.



After removal of casing



5th stage blades was having deposits and it was choked badly



115 JBT rotor after sand blasting

Parts replaced in 115 JBT			
Sr. No.	Part Name	Qty.	Store Code
1	CARBON RING, # 28 CAT NO-604900-49 FOR TURBINE 115 JAT/JBT	10	2010113560109400
2	DIAFRAM SEALS CAT-NO-GY0771-5 T.NO-30,DRG NO ELLIOT:TURBINE-1000177 115 JAT/JBT	5	2010113560117800
3	DIAFRAM SEALS CAT-NO-GY0771-5 T.NO-30,DRG NO ELLIOT:TURBINE-1000177 115 JAT/JBT	1	2010113560117800

4	BEARING LINER BOTTOM , CAT NO.-603360-23, ITEM.NO:60 ,D.NO: WC-00001000177, FOR DRIVE TURBINE (115-JT)	1	2010113560135201
5	BEARING LINER TOP , CAT NO.-603360-42, ITEM.NO:61 , TYPE:ELLIOT-MYR, D.NO : WC-000001000177 FOR DRIVE TURBINE (115-JT)	1	2010113560135211
6	COUPLING SURE-FLEX COUPLING NO 3 J , BORE 1/2 INCH FOR TURBINE TO ACTUATOR Note – for 115 JAT	1	2010113566115000

115-JBR Gear Box

All the bearings were inspected and found O.K. Both the gear as well as Pinion were inspected and found to be O.K. Gauss measurement of gear shaft and bearings carried out and found within limit. Bearing clearances and backlash were measured and found within the design range. The main oil pump drive coupling was inspected and found in good condition.

CLEARANCE RECORDS – 115-JB

Description	Design Clearances (Inch)	Before (Inch)	After (Inch)
Thrust end bearing	0.005-0.0098	0.0082	0.0082
Opp Thrust end bearing	--- do---	0.0074	0.0074
Axial Thrust	0.013 – 0.015	0.0177	0.0177

CLEARANCE RECORDS – 115-JBT

Description		Design Clearances (Inch)	Before (Inch)	After (Inch)
Axial Thrust		0.010 – 0.012	0.0122	0.0110
Coupling side bearing		0.0055-0.008	0.0122	0.0122
Governor side bearing		-- do --	0.0122	0.0122
Oil Guard Coupling side (inboard)	Radial	0.0100-0.0125	0.0047/0.0047	
	Axial	0.040-0.050	0.0425/0.0425	
Oil Guard Coupling side (outboard)	Radial	0.0100-0.0125	0.0059/0.00511	
	Axial	0.080-0.090	0.07283/0.06889	
Oil Guard Governor side	Radial	0.0100-0.0125	0.00059/0.00393	
	Axial	0.030-0.040	0.003149/0.03149	

Journal Bearing Pads Liner Thickness 115-JBT

PAD	NORTH SIDE	SOUTH SIDE
Upper	0.1153	0.1145
Lower	0.1141	0.1141

Thrust Bearing Pad Thickness: 115-JBT

Pad No.	Active	Inactive
No. 1	0.6866	0.6874
No. 2	0.6870	0.6874
No. 3	0.6874	0.6874
No. 4	0.6874	0.6877
No. 5	0.6870	0.6874
No. 6	0.6874	0.6874

COLD CLEARANCE TOLERANCES					
Sr. No.	DESCRIPTION	DESIGN		ACTUAL	
		MIN	MAX		
1.	DIAMETRAL SHAFT SLEEVE SEALS	.0100	0.0125		
2.	RADIAL DIAFRAM SEAL	.0148	0.0165		
3.	CARBON RING DIAMETRAL	.0070	0.0085	STM. END	EXT. END
				0.0066	0.0066
4.	JOURNAL BEARING DIAMETRAL	.0035	.0080	STM. END	EXT. END
				0.0145/0.0010	0.0122
5.	TRIP PIN/ PLUNGER	.0620	.0650		
6.	AXIAL BEARING HOUSING SEAL, STEAM END	.0300	.0400		
7.	AXIAL BEARING HOUSING SEAL, EXHAUST END INBOARD	.0400	.0500		
8.	AXIAL BEARING HOUSING SEAL, EXHAUST END OUTBOARD	.0800	.0900		
9.	NOZZLE RING, AXIAL	.0500	.0720	0.0669	0.0649
10.	BUCKET HOLDER, AXIAL (INLET)	.0500	.0900	0.0669	0.0669
11.	BUCKET HOLDER , AXIAL (OUTLET)	.0700	.1050	0.0925	0.0925
12.	RADIAL , DISK	.0580	.0680		
13.	DIAFRAM , AXIAL (ROW 6)	.0840	.1140	0.0708	0.0708
14.	DIAFRAM , AXIAL (ROW 2)	.0520	.0820	0.0708	0.0708
15.	DIAFRAM , AXIAL (ROW 3)	.0520	.0820	0.0708	0.0708
16.	DIAFRAM , AXIAL (ROW 4)	.0520	.0820	0.0787	0.0787
17.	DIAFRAM , AXIAL (ROW 5)	.0520	.0820		
18.	MAGNETIC IMPULSE SPEED PICK – UP AIR GAP	.0200	.0250		

Thrust Bearing Pad Thickness: 115-JB

Pad No.	Active	Inactive
No. 1	1.2511	1.2492
No. 2	1.2503	1.2496
No. 3	1.2499	1.2492
No. 4	1.2496	1.2496
No. 5	1.2496	1.2499
No. 6	1.2503	1.2496
No. 7	1.2503	1.2496
No. 8	1.2499	1.2499


ALIGNMENT READINGS

Distance Between Flange Faces


115-JBT to 115-JR = 15.902" & 115-JR to 115-JB = 11.881"

115-JBT TO 115-JR

BEFORE




AFTER




Note: Fixture mounted on Turbine, Dial reading on Gear Box, All Readings in mm.

115-JR TO 115-JB

BEFORE





Note: Fixture mounted on Gear box, Dial reading on Pump, All Readings are in mm.

BOILER FEED WATER PUMP, TRAIN 104-JA

104-JA Boiler Feed Water Pump

Both ends journal bearing sleeves were visually inspected and dye penetration tested and found OK. The bearing clearance were measured and found within design range. Magnetism level of the bearings was carried out and found within desired value. The main oil console and its console along with the filters were cleaned and installed. The seal flushing fluid coolers and strainers were cleaned.

104-JAT Drive Turbine

The turbine was taken for preventive maintenance.

CLEARANCE CHART: 104-JAT

Description	Design Clearance (Inch)	Before PM (Inch)	After PM (Inch)
Coupling end			
Journal bearing	0.005 – 0.007	0.0059	0.0059
Oil Guard (For Journal Brg. Housing)		0.0059	0.0059
South			
North		0.0039	0.0039
Bearing Pinch		0.00078/0.0011	0.00078/0.0011
Governor End			
Journal bearing	0.005 – 0.007	0.0066/0.0078	0.0066/0.0078
Oil Guard (For Journal Brg. Housing)		0.0098/0.0059	0.0098/0.0059
South			
Axial Thrust (With Top Housing)	0.011 – 0.016	0.022	0.0216
Total Float			0.0551
Bearing Pinch			0.00039/0.00078

Journal Bearing Sleeve Thickness 104-JAT

PAD	NORTH SIDE (Inch)	SOUTH SIDE (Inch)
Upper	0.3980	0.3996
Lower	0.4051	0.3988

Thrust Bearing Pad Thickness: 104-JAT

Pad No.	Active (Inch)	Inactive (Inch)
No. 1	0.6228	0.6297
No. 2	0.6236	0.6297
No. 3	0.6232	0.6255
No. 4	0.6228	0.6259
No. 5	0.6240	0.6263


CLEARANCE CHART: 104-JA


Description	Design Clearance (Inch)	Before PM (Inch)	After PM (Inch)
104 JA			
Journal bearing (Thrust end bearing)	0.006 - 0.008	0.00748	0.00748
Journal bearing (Opposite thrust end)	0.006 - 0.008	0.00826	0.00826
Axial Thrust	0.014	0.0145	0.0125

Thrust Bearing Pad Thickness: 104-JA

Pad No.	Active (Inch)	Inactive (Inch)
No. 1	0.9992	0.9996
No. 2	0.9984	0.9992
No. 3	0.9992	0.9992
No. 4	0.9988	0.9992
No. 5	0.9992	0.9992
No. 6	0.9984	0.9998

ALIGNMENT : 104-JAT to 104-JA





Note: Fixture mounted on pump, Dial reading on Turbine, All Readings are in mm.
View from Turbine Rear side

a-MDEA PUMP 107-J Train

107-J aMDEA Pump

Both DE & NDE side bearing housing oil flushed.

Major Overhauling of 107-J Drive Turbine, 107-JT

All the pipings were disconnected. The turbine was decoupled and the coupling was inspected and DBSE were noted. Turbine (107-JT) front, rear bearings and thrust pads were thoroughly polished & dimensionally checked and found to be within limits. DP tests were carried out and no damages found. Magnetism level of all bearings was found to be within limit. Clearances were measured and found to be within limit.

Turbine Casing Parting Plane bolts removed & top casing half lifted from position. The steam inlet strainer was found damaged and some portions of blades was having minor damages. The damages were rectified. Top casing half was cleaned properly by hydrojetting. Diaphragm parting plane bolts removed & top portion lifted out of turbine. Turbine Rotor was lifted from bottom casing after recording all internal clearances. Turbine rotor was thoroughly cleaned by sand blasting. Turbine Rotor was placed in bottom casing & all the readings were recorded.

All Carbon Rings i.e. Front & Rear Steam gland & Interstage replaced & clearances made as per design requirement. Turbine Casing final box-up done after ensuring drain passage clean. Lube oil filter cleaned & filter element replaced. Lube oil filter was cleaned by hydrojetting. Alignment between Turbine & Pump was done and final coupling of the turbine to pump done. All the pipings were connected.



Some portions of rotor blades was having minor damages



Ready for keeping top casing


CLEARANCE CHART: 107-JT (MURRY TURBINE)

Description	Design Clearance (Inch)	Before PM (Inch)	After PM (Inch)
Journal bearing Thrust end	0.004 – 0.006	0.0062-0.0070	0.0062-0.0070
Oil Guard Thrust end – Inboard & Outboard	0.011” – 0.017”	0.0059	0.0059
Journal bearing Opposite thrust end	0.004 – 0.006	0.0062-0.0070	0.0062-0.0070
Oil Guard Opposite thrust end - Inboard	0.011” – 0.017”	0.0066-0.0059	0.0066-0.0059
Axial Thrust	0.007 – 0.013	0.0145	0.01338
Nozzle Clearance	0.0625	0.0728-0.0846	0.0728-0.0846


Sr. No.	DESCRIPTION	DESIGN (Inch)	BEFORE (Inch)	AFTER (Inch)
1	Thrust Bearing	0.007-0.0013	0.0145	0.01338
2	Front Bearing	0.004-0.006		0.0062/0.0070
3	Carbon Ring	0.0075-0.0010	0.75-0.81mm	0.0059/0.0078
4	Nozzle to Wheel1	0.0625		0.0728/0.0846
5	Wheel1 to Sector			0.0590
6	Sector to Wheel2			0.098/0.0787
7	Wheel3	0.012-0.016		0.0944/0.0964
8	Wheel4	0.012		0.0944/0.0964
9	Wheel5	0.012		0.0944/0.0964
10	Wheel6	0.012		0.1377/0.1417
11	Carbon Ring	0.0044-0.007	0.75-0.81mm	0.003/0.0051
12	Rear Bearing	0.004-0.006		0.0062/0.0074

ALIGNMENT READINGS: 107-JT to 107-J

BEFORE



AFTER



Note: Fixture mounted on Turbine, Dial reading on Pump, All Readings are in mm.

However after Overhauling and during start up high vibration was observed in 107-JT. The sequence of activities carried out during overhaulin and after observing the Vibration problems are tabulated and given below:

SEQUENCE OF ACTIVITIES OF 107-JT HIGH VIBRATION PROBLEM

Sr . No.	Date	Vib mm/s at 1H	Activities	Remarks
1	1-10 April 2015		Major overhauling of 107-JT done during SD-April 2015. Gland and Interstage Carbon ring were replaced with new one. Bearings were not replaced	
2			Thrust - 0.40 mm, Cplg end Brg Cl- 0.25, Gov End - 0.25. Nozzle ring Clearance -1.85, Diaphragm cl - 2.4 mm min, Carbon ring cl- 0.20 mm, Interstage carbon -0.35	
3			Turbine started in sequence for proper lapping of Carbon ring. OST at 4100 RPM.	
4		5.7	During Start up (while carrying out OST) the vibration at 1H was slightly on higher side.	Normal at 1H -3 mm/s
5	12.04.15	14.3 & reduced to 8	After coupling and taking in line, Vib at 1H increased upto 14.3 mm/s and after running for about an hour, It reduced to 8 mm/s, but still on higher side.	Cyclic Vib. observed
6	12.04.15		Decided to check MOP. The following activites done-	
7	13.04.15		Observed black deposits in MOP and bearings. MOP replaced with spare, Worm wheel replaced, All bearings were replaced.	
8	13.04.15	19.9	Turbine started. On coupled condition, High vibration observed. At 3370 RPM, 1H 19.9 mm/s	Cyclic Vib. observed
9	13.04.15		Decided to check bearings. The following activites done-	
10			Blue match of both bearings checked. Found OK (80%)	
11			However Free end bearing replaced with new one to reduce brg clearance. Clearance reduced from 0.25 to 0.18 mm. Blue match checked.OK	
12			Coupling end brg not replaced. Clearance-0.25	

13			Thrust collar face R/o checked by keeping two dials. Found OK	
14			New thrust brg pads provided. Thrust reduced from 0.4 to 0.30 mm	
15	14.04.15	26.4	High vibration at 3350 RPM in coupled condition at 3350 RPM	Cyclic Vib. observed
16		32.2	Thrust increased to 0.45 mm. However Vibration increased upto 32.2 at 3300 RPM in coupled condition. Turbine stopped	
17	15.04.15		MOP decoupled and turbine was started. Vibration found to be 5.7 mm/s at 3450 RPM in coupled condition However after 1 hr of running vibration increased upto 40.6 mm/s. Turbine stopped	
18			Original MOP, old worm shaft and new bearings installed back and turbine was run with MOP coupled. No improvement found	
19	16.04.15		Decided to open turbine and check rotor. Observed that 3rd, 4th & 5th stage diaphragm partition plane bolts (Control Room side) found loose	
20	to		New steam end carbon rings and old interstage carbon rings provided. Tapping of threads of partition plane bolt hole done. Strainer replaced with new one.	
21			Rotor Runout checked and found ok	
22			Carbon ring clearance, steam end -0.2, Exh end-0.11, Interstage - 0.35, Axial thrust-0.45	
23			J Brg, free end - 0.17, Cplg end - 0.22, New MOP installed back.	
24	18.04.15		Nozzle clearance -1.9 mm, Diaphragm cle- 2.1 mm min	
25			Turbine started for OST. At 3300 RPM 1H - 11 mm/s Vibration increased upto 37.5 mm/s at 3450 RPM, Speed reduced upto 2500 RPM. Support adjusted and vib reduced upto 12 mm/s. OST done at 4367 RPM.	Cyclic Vibration NOT observed
26			Coupled and run. At 2500 RPM 1H- 12mm/s. Reduced upto 7.5 mm/s may be due to support adjustments. Pump changed over. Vibration was continuously increasing above 2900 RPM. Turbine was Stopped when vibration reached 32 mm/s.	
27	20.04.15		Flexibility analysis of steam inlet line done by M/s Tech Emerging Engg. Services, Hyderabad. One no fixed support on inlet line replaced by spring support and othe support adjusted as per their suggestion	No significant improvement observed
28			Steam inlet line flange disconnected and observed offset by 6 mm. Support adjusted and offset removed and connected again. Turbine run. Vibration measured at 2700 rpm, 1H=6.47mm/sec, 3450 rpm 1H 5.5 mm/sec	No significant improvement observed
29	21.04.15		Vibration measured in couple condition in load at 3450 rpm 1H=33.1 mm/sec	
30	22.04.15		Vibration measured in decouple condition at 3400 rpm, 1H= 6.14 mm/sec	

31	24.04.15	4.5	Top Hand nozzle valve which was unable to operate (Valve was in open condition) was removed and closed by providing Plug(Made from W/s).Turbine run. On load at 3530 RPM 1H -4.5	Valve seat was not found
32		28	However after running for 1 hr, vibration was continuously increasing. Turbine was Stopped when vibration reached 28 mm/s at 3500 rpm	
33	25.04.15		Due to seal leak of 107 JA, Plant load was reduced and 107 J was taken on line at 07.30 hrs	
34		4.5	At 2940 RPM (Flow 220 M3/hr) 1H - 7.5mm/s. Vibration increased upto 10.5 mm/s and then reduced to 4.5 mm/s. Turbine was run at 2850 RPM in low load upto 12 hrs. Vibration was constant at 1H-4.5mm/s.	2856 RPM, 190.4 m3/hr, 23.62 Kg/cm2 dis Pr, PRC- 4.18 kg/cm2
35		13.4	After attending seal leakage of 107-JA, load on 107-J was increased. Vibration started to increase at 3150 RPM and vibration was continuously increasing. Turbine was Stopped when vibration reached 13.4 mm/s.	3150 RPM, 200 m3/hr, 26.7 Kg/cm2 dis Pr
36	27.04.15		Decided to open turbine and replace with spare refurbished rotor. Observed that all stage diaphragm partition plane bolts OK	
37	to		Same carbon rings and interstage carbon rings were reused	
38	01.05.15		Rotor R/o checked and found ok. 3rd and 4th stage diaphragm machining was done and button was welded at other end for maintaining the clearance	
39			Carbon ring clearance, steam end -0.2, Exh end-0.11, Interstage - 0.35, Axial thrust-0.30. Turbine side Coupling hub Overhang -4.57 mm	
40			J Brg, free end - 0.23,Cplg end - 0.20	
41			Nozzle clearance -1.79 mm, Diaphragm cle- 1.92 mm min	
42			Bottom Hand nozzle valve which was operatable was opened and found that Valve seat is not provided. It was closed by providing Plug(Made from W/s).Turbine run. On load at 3530 RPM 1H -4.5	Valve seat was not found
43			Turbine started for OST.OST at 4315 RPM. (Spare OST assbly provided) vibration in decouple condition at 3000 rpm , 1H 6.5mm/sec and at 3450 rpm 5.9mm/sec	
44	02.05.15	18.7	After starting coupling Vib at 1H increased upto 18.7 mm/s	
45	04.05.15		Thrust increase to 0.45 mm	
46	TO		Decided to carry out insitu balancing at operating speed. 2 nos M6 X 16 mm bolts provided on coupling hub (At jack bolt). Trial wt 3 g. After trial run, 1.8 g correction wt was provided. Vibration on no load reduced to 3.8 mm/s from 4.5mm/s	No significant improvement on load

47		3.8	Oil inlet temp to brg was increase by reducing the CW flow to oil cooler.Oil temp at HE I/I increased upto 48.5 Deg C (Brg I/I - 44.5) 1H- 3.8 at 3200 RPM. Lube Oil - Servo Prime 68 Normal operation - Oil temp at HE inlet- 40 deg C. At brg i/I - 36 deg C	
48	05.05.15		Oil temp at HE I/I increased upto 48.5 Deg C (Brg I/I - 44.5) 1H- 3.8 at 3200 RPM. (Later CW I/I Valve opened)	No significant improvement on load
49	06.05.15		One tie rod of Expansion bellow was not free. Hence one adjustable tie rod made. On reducing the length of the adjustable tie rod the other two are unable to rotate. Hence Screw jack provided and lifted. All tie rods made free. Exhaust line lifted by 5 mm. Vibration measured in decoupled condition at 3430 rpm, 1H vibration was 4.16 mm/sec. In coupled condition vibration measured at 3400 rpm at low load condition, vibration levels were stable around 5 mm/sec, but after pump change over, vibration level started increasing and reached upto 30 mm/sec . Pump stopped.Later screw jack removed.	No significant improvement on load
50	07.05.15		Brg Lube Oil inlet line is under tension. It was removed by providing flexible SS hose.	
51			LO Cooler inlet and outlet line were under tension. It was cut and welded for removing it	
52	08.05.15	6.5	Turbine started in decoupled condition. Max vibration increased to 14 mm/s at 2400-2600 RPM and then reduced.At 3450 RPM, 1 H 6.5 mm/s.	
53		6	Horizontal supports with Jacking arrangement provided at free end Bearing housing. These supports loaded by tightening.	No significant improvement on load
54	Note		Inlet line and exhaust lines were checked and adjusted for reducing the Vibration. However no significant improvement observed.	
55	10.05.15 to 12.05.15		Free end bearing clearance increase from 0.18 to 0.25/0.33 mm by scraping	OD shaft 101.47, ID of bearing 101.80/101.65 mm
56	13.05.15		Alignment correction done. Pump kept ---- towards Control room side	
57	14.05.15 to		NDE bearing bluematching done and scraping done to improve contact	
58	15.05.15		Ejector opened. Found corroded. Made new one a per drawing of 104 JT ejector and provided in position	
59	16.05.15		Alignment done	

60	18.05.15	2.5-3.55	Run in decoupled condition, Vibration max upto 3.22. In Load Condition, Vibration levels at 1H were maintained between 3.5 to 4.0 mm/sec for 1 Hr. and reduced to min. level of 2.9 mm/sec. Then vibration starts increasing at 1.00 PM, increased up-to 15.0 mm/sec and then reduced even to the lowest value of 1.48 mm/sec. Vibration were cyclic in nature. However, Vibration levels were not increased above 9.0 mm/sec, till the stoppage of machine at 04.30 PM	
61	19.05.15 to 20.05.15	2-7.0	107 JT DE bearing checked ???. Run incoupled condition After changeover, vibration was 3.8 mm/s at 15.30 Hrs on 19.05.15, which reduced to around 2.5-3.0 mm/s within 1 hour. Turbine kept in line. Vibration stable at 2.5-3.0 mm/s. On 20.05.15, 15.00 hrs, Cyclic Vibration at 1H observed from 2.00 mm/sec To 7.20 mm/sec.	
62	21.05.15	0.9-6.8	Vibration levels are maintained as earlier set of readings. Cyclic Vibration at 1H observed from 0.9 mm/sec To 6.8 mm/sec. NDE side bearing replaced. Thrust decreased. DE brg checked NDE brg - 0.2 mm, Thrust 0.29, DE brg -0.14 to 0.17 (0.15 shim for pinch)	
63	22.05.15	21.5	At full load, Vibration levels at 1H increased up to 21.5 mm/sec. NDE side brg increased. Thrust increased NDE brg - 0.27 - 0.34 mm Thrust 0.42	
64	23.05.15		NDE side brg clearance checked. NDE clearance 0.26-.035 mm pinch 0.05. Shim provided	
65	25.05.15	10-14.2	Front turbine Journal bearing clearances were increased in the range of 0.26 to 0.30 mm & Thrust maintained at 0.29mm Vibration levels at 1H maintained at 5.0 to 5.7mm/sec for 2.50 hrs. At 11.45 AM cyclic nature of vibration observed. Vibrn levels were observed in the range of 6-13.0mm/sec then 8-14.0mm/sec & finally 10-15.0 mm/sec. Back Pressure reduced to 25.8 Kg/cm ² , Flow reduced to 322 M ³ /hr & RPM reduced to 3410 but at 16.30 hrs 1H vibration were cyclic in the range of 10-14.2 mm/sec.	Damaged thread of NDE brg repaired, Blue match of NDE brg checked.
66	26.05.15		NDE journal brg increased NDE clearence 0.27-.034 mm pinch. Shim provided Axial thrust 0.42	
67	27.05.15		Turbine run in coupled condition. Vibration increased upto 14 mm/s	
68	28.05.15		DE brg opened. Shim changed. Blue match OK. NDE opened and checked OK. New oil provided in console. (Exhaust BV broken) DE brg -0.14 to 0.17 (0.05 shim for pinch)	
69	29.05.15	4-8 mm/s	Turbine run in decoupled condition. Cyclic Vibration observed. Vibration varying between 4 to 8 mm/s	

70	01.06.15 to 02.06.15		<p>Readings between top & bottom Tie rod support clits measured:</p> <p>Ammonia Maint. side Tie rod - 594mm CT side Tie rod- 592mm Urea side Tie rod - 591mm</p> <p>Steam exhaust line lifted by hydraulic jack to make tie rods free.</p>	
71	03.06.15		<p>Turbine decoupled.</p> <p>Steam exhaust line lifted by hydraulic jack to make tie rods free.</p> <p>Readings between top & bottom Tie rod support clits:</p> <p>Ammonia Maint. side Tie rod - 596mm CT side Tie rod- 595mm Urea side Tie rod - 593mm</p> <p>Turbine run for 30 minutes in decoupled condition at 3430 RPM. Vibration at 1H 5.13 mm/s. & reduced to 1.9mm/s. Additional supports were made to lift the Exhaust line.</p>	
72	04.06.15	3.7 mm/s	<p>Turbine decoupled.</p> <p>One no. tie rod found tight. Hence, Steam exhaust line lifted by hydraulic jack to make it free.</p> <p>Readings between top & bottom Tie rod support clits:</p> <p>Ammonia Maint. side Tie rod - 598mm CT side Tie rod- 597mm Urea side Tie rod - 593mm</p> <p>Turbine run in decoupled condition. Vibration at 1H 2.6 mm/s. & increased to 5.0 mm/s</p> <p>Turbine was stopped & again started after removing condensate from casing & line. Vibration at 1H 3.5 - 4.0 mm/s. & increased to 6.5 mm/s.</p> <p>Considering the condensate formation due to low quantity of steam entering into turbine, it is decided to couple the turbine.</p> <p>Turbine coupled & run on full load. Turbine vibration measured after 15 to 20 min running in coupled condition. 1 H vibration reduced to 2.71 mm/sec from initial reading of 4.1 mm/sec. Further continuous monitoring carried out till 8.30 PM. and vibration value at 1H location found in the range of 3.5 to 3.7 mm/sec.</p>	
73	05.06.15	3.7 mm/s	<p>80.5 mm packing on both sides of steam exhaust pipe inserted to maintain the lift position & removed the hydraulic jacks.</p>	
74	06.06.15	3.8 mm/s	<p>Vibration levels are maintained as earlier set of readings.</p> <p>At 1H observed 3.8 mm/sec.</p>	

RECIPROCATING CO₂-GAS COMPRESSOR TRAIN (117-J)

LP Cylinders Overhauling

The end clearance at TDC and BDC were measured and opened the head of both cylinders to remove the piston assembly. The cylinder liners were inspected and

found OK. The piston assembly of both the cylinders was replaced. Spare refurbished gas packings were reinstalled on both the cylinders. All the valve assemblies were reconditioned.

HP Cylinders Overhauling

The end clearance at TDC and BDC were measured and opened the head of both cylinders to remove the piston assembly. The piston rod assembly of both cylinders was replaced by new one with new gas packing. All the suction and discharge valves were replaced by spare refurbished valves.

Crank case assembly Overhauling

Opened the crank case cover for the inspection of the bearings and other internals. Clearances of all the big end bearings were found on higher side and the white metal lining had worn out. These bearings were replaced by new ones. All other components were visually inspected and found OK. All the clearances were measured and found within limit. All critical nuts were tightened at respective design torque. The AOP was run and oil flow inside the crank case was checked and found OK. The oil scrapper rings were replaced by new one.

The tube bundle of the inter stage cooler was pulled out and cleaned by hydro jetting. The LP and HP flow dampener were checked and found OK. The lube oil strainers were cleaned and reinstalled.




Crank case opened


CLEARANCE CHART : 117-J TRAIN

Description	Position		Design clearance(mm)	Before (mm)	After (mm)
Piston end clr. (Front /TDC)	LP	Urea side	2	2.64	2.78
		Ammonia side	-- do --	2.40	2.7
	HP	Urea side	-- do --	2.40	2.41
		Ammonia side	-- do --	2.30	2.40
Piston end clr. (Intermediate /BDC)	LP	Urea side	1.5	1.12	1.91
		Ammonia side	-- do --	1.00	1.90
	HP	Urea side	-- do --	1.40	1.60
		Ammonia side	-- do --	1.30	1.71
Main bearing	I	Urea side to Ammonia side	0.08-0.15 (0.3 MAX)		0.14
	II		-- do --		0.14
	III		-- do --		0.15
	IV		-- do --		0.14
	V		-- do --		0.16
Big end bearing	LP	Urea side	0.07-0.13 (0.3 MAX)		0.13
		Ammonia side	-- do --		0.14
	HP	Urea side	-- do --		0.14
		Ammonia side	-- do --		0.14
Small end bearing	LP	Urea side	0.05-0.10 (0.2 MAX)		0.08
		Ammonia side	-- do --		0.08
	HP	Urea side	-- do --		0.08
		Ammonia side	-- do --		0.08
Cross head guide	LP	Urea side	0.18-0.26 (0.6 MAX)		0.20
		Ammonia side	-- do --		0.20
	HP	Urea side	-- do --		0.20
		Ammonia side	-- do --		0.20
Side clearance (Crank shaft)	----	Crank shaft	0.45-0.60 (0.9 MAX)		0.50
Side clearance (Connecting rod big end)	LP	Urea side	0.33-0.42 (0.6 MAX)		0.35
		Ammonia side	-- do --		0.35
	HP	Urea side	-- do --		0.35
		Ammonia side	-- do --		0.35

117-JM to Gear Box - (After PM) in “mm”



Gear Box to 117-J - (After PM) in “mm”



COPPUS TURBINES

101 / 105-JLOT

The lube oil pump drive turbines, was taken for replacement of bearings. The radial bearing i.e. deep groove ball bearing as well as the thrust bearing i.e angular contact ball bearing were replaced by new one. The cooling water lines were flushed. The bearing oil cooling water jackets were cleaned. The trip valve spindle was made free for smooth start up of the turbine.

PRIMARY REFORMER, SECONDARY REFORMER & AUXILIARY BOILER JOBS

The Primary Reformer Radiant Zone

Burner blocks were inspected and Nineteen damaged burner blocks were replaced by Unifrax make, Model: Moldafrex BBM 15 burner blocks.

Row No.	Burner Nos.
1	110, 112
2	203, 211, 212
3	Nil
4	405, 414
5	501, 513, 514
6	602
7	703, 708, 709, 710
8	807, 812
9	908, 912

The roof insulations were inspected and damaged / dropped ones were replaced by new ones & gaps were filled.

Gaps in side wall Z-module were observed at peephole elevation and the same was repaired. However, side wall insulation at other locations were intact & in satisfactory condition.

Damaged bottom header insulation were replaced / repaired.

AUS and other NDT of reformer tubes were carried out by M/s TCR Vadodara.(Refer Inspection section Report)

Damaged / broken tunnel slabs were replaced by new ones & damaged wall refractory were repaired.

All spring hangers locked for inspection & catalyst replacement & unlocked after completion of the job.

All burners air resistor overhauling done.

The Primary Reformer Convection Zone

Refractory which was having crack were repaired & fallen ones were replaced at the ceiling after providing new holding clits against burnt off clits at such locations. Insulation of East, West & South wall was found satisfactory.

The LT and HT end panel walls were opened for external cleaning of the coils. External scaling of all HT coils & LT coils was cleaned by hydrojetting except BFW coil in the duct.

Steam Air coil was found sagged up to 300 mm downward direction at south side.

Coil was lifted up & support fabricated from SS310H plate Material inserted & welded.

HT & LT panels were boxed up with new gasket.

The transfer line end cover was opened for inspection and then boxed up.




Steam air
Coil was
found
sagged

LT and HT end panel walls were opened for external cleaning

The Secondary Reformer

Top cover with Air distributor & Bottom cover were opened for inspection.

Before Shutdown it was decided to provide a sleeve of 6'3" ID and approx. 2'4" height of Incoloy 800 H material inside the circumference of 103-D below Bed support dome. (Ref IFFCO drawing 01-BN-03003 and attached sketch-Detail E below).



Accordingly WO 201004151471 dated 10/03/2015 was placed on M/s. J & J Engineers for carrying out this job along with other fabrication jobs. Prefabrication of the sleeves was made as per IFFCO drawing no.01-BS-03045 for carrying out the job.

After opening of bottom cover, inspection was done. The refractory was found intact and its condition was good. Hence it was decided not to provide the sleeve.

The prefabricated sleeve was returned to store. Top cover with Air distributor & Bottom cover were boxed up with new gasket.

Auxiliary Boiler

Replacement of Refractory of West Side Wall

During operation hot spot was observed on the west side wall panels of Auxiliary Boiler. Hence, it was decided to repair the refractory in this area. The side panels of the Auxiliary Boiler are of bolted construction and have less clearance between the

water wall and the refractory wall (about 6"). Therefore, to carry out refractory repair work panels were removed with the help of crane.

Removed damaged refractory from panels, cleaned it properly, Y-type anchors (SS 304) welded on panels at square pitch length of 140 mm & then 165 mm thick refractory (Insulyte-11) casting done.

Panels fixed back to their respective position with the help of crane after ensuring refractory setting.

Bulged & damaged liner near PRC-23 repaired.

Manhole was closed after putting bricks and ceramic blanket.

HEAT EXCHANGERS AND COOLER JOBS

101-CA, Waste Heat Boiler

Replacement of Outer & Inner Tube bundle Assembly carried out by the help of KOBELCO Crane. We have replaced the Tube bundle of 101 CA during last shutdown SD-2014 after it was damaged due to failure of chain block. The tube bundle installed in 2014 was in service for over a long period and hence it was decided to replace the Tube bundle during this Shutdown SD-2015.

The overhead trolley which was used for shifting of tube bundle by Chain block was removed. The Beam on which the overhead trolley was positioned, was fouling with the crane boom, hence it was also cut and removed. The rigging was carried out by Kobelco Crane

After getting clearance from Production, all steam side flanges i.e. Downcomer flange, T1; Top Channel Cover flange, F1; Riser Flanges, T2A & T2B & gas side flange i.e. Outer Tube Sheet to Shell Flange, F3 were disconnected by opening respective studs.

Down comer elbow of 101 CB and CA was removed from top by Kobelco crane. For fast removal of water from the bundle, 3 nos 1/2 " transparent hose was connected from vacuum blower header and given to Production. Lifting cover was taken to the top by the help of crane & placed over the Top Channel Cover flange, F1 of 101 CA & tightened all the studs.

Tube bundle Assy. was replaced by KOBELCO (135 T) crane with 95 ft boom length & 16.5 Mtr. Boom Radius with 5' sheave assembly.

All flange joint connections boxed up after providing new gaskets & bolts tightened as per respective specified torque values.

The exchanger was boxed up with spare Tube bundle No-2 (Sr. No. 1-72-04-31387-73), which was repaired by M/s. Anup Engineering against WO No.201004150078 dated 23/05/2014.



Tube bundle was lifted and installed by Kobelco crane



The overhead trolley and beam was removed to remove fouling

114-C North side channel cover leak

North side channel cover was opened & removed. Channel cover & shell gasket seating area were cleaned properly and boxed up with new gasket.

115-C tube leakage

115-C was reported to be having tube leakage during normal operation. Helium Test was conducted by M/s. Gulachi Engineers to detect leakage. Channel cover was opened. Blinds fixed on shell side inlet & outlet nozzles. The whole tubesheet face was covered by Tape. Shell was pressurized by air at 3.0 Kg/cm²g & then Helium Gas was injected & shell side pressure was raised to 5.0 kg/cm²g. Removed the tape & Helium gas was checked by Helium detector & marked the leaky area successively. It was observed that there was leakage through tube to tube sheet weld joint. Hence, it was repaired by welding.

OTHER EXCHANGERS

EQP TAG		HYDROJETTING		HYDRO TEST	Remarks
		TUBE SIDE	SHELL SIDE (Tube bundle pull out)		
101-JCA		✓			
101-JCA	I/A COOLER	✓			
101-JCB		✓			
101-JCB	I/A COOLER	✓			
101-JLC1	LUBE OIL COOLER	✓			
101-JLC2	LUBE OIL COOLER	✓			
103-JLC1	LUBE OIL COOLER	✓			
103-JLC2	LUBE OIL COOLER	✓			
103-JBT	GLAND CONDENSER	✓			
104-J	LUBE OIL COOLER	✓			Cleaning done before shutdown
104-JT	LUBE OIL COOLER	✓			
104-JT	GOV OIL COOLER	✓			
104-JA	LUBE OIL COOLER	✓			
104-JAT	LUBE OIL COOLER	✓			
104-JAT	ACTUATOR OIL COOLER	✓			
105-JT	GLAND CONDENSER	✓			
105-CA		✓			
105-CB		✓			
107-JT	LUBE OIL COOLER	✓			
107-JAT	LUBE OIL COOLER	✓			Cleaning done before shutdown
108-C1A		✓		✓	Shell side : 8.0 Kg/cm2g Tube side : 8.0 Kg/cm2g
108-C2A		✓		✓	
109-C1A	SILO SIDE	✓	✓	✓	
109-C2A	SILO SIDE	✓	✓	✓	
110-CA		✓			
110-CB		✓			
114-C					North Side Channel cover Gasket replaced
115-C			✓	✓	Shell side: 2004-J Discharge pressure. Tube to tube sheet welding done
115-JALC1	LUBE OIL COOLER	✓			

EQP TAG		HYDROJETTING		HYDRO TEST	Remarks
		TUBE SIDE	SHELL SIDE (Tube bundle pull out)		
115-JALC2	LUBE OIL COOLER	✓			
115-JBLC1	LUBE OIL COOLER	✓			
115-JBLC2	LUBE OIL COOLER	✓			
116-C			✓		Shell side : 8.0 Kg/cm ² g
117-J	INTERCOOLER	✓	✓	✓	
117-J	1 st STAGE COOLER	✓			
124-C			✓	✓	Shell side : 8.0 Kg/cm ² g
127-CA		✓		✓	Shell side : 26.0 Kg/cm ² g
127-CB		✓		✓	Shell side : 26.0 Kg/cm ² g
128-C		✓			
129-JC	101-J INTERCOOLER	✓			
130-JC	101-J INTERCOOLER	✓			
131-JC	101-J INTERCOOLER	✓			
150-C		✓			
151-C					
173-C		✓			
HE-2	PGR	✓			
HE-4	PGR	✓			

VESSEL INSPECTION / REPAIR JOBS

- 101-EA, CO2 Absorber: 6 nos. Manholes opened, inspection carried out. Loose Raschig ring holding clamps tightened & then boxed up.
- 102-EB, CO2 Stripper: Top Manhole opened, cleaning done, tightening of loose East-North & West-South side U-Clamps of East/West side distribution header done & weld repair of cracked distributor header support plates at marked locations carried out & then boxed up top manhole after inspection.
- 103-E1, HP Flash Vessel: Top manhole opened for inspection and then boxed up. No repair was carried out.
- 103-E2, LP Flash Vessel: In Second from Top Manhole compartment, North-West side 3" line which was found broken and lying on the rectangular riser box repaired by welding. Welded broken End plate of same 3" line which was found lying on the bottom tray. Loose holding bolts of bottom tray tightened.
- 105-E, Dehydrator: Top & bottom Manholes opened & boxed up after inspection. No damage / looseness were observed.

- 101-F, Steam Drum: Side Manholes opened, tightened loose bolts and clamps of Demister Pad holding cover plate & provided new against missing one, 02 nos. loose bolts tightened in flange joint of 6" BFW header. Side Manholes boxed up.
- 102-F, Raw Gas Separator & 103-F, Reflux Drum manholes were opened. Inspection carried out in which. Manholes boxed up.
- 104-F, Synthesis Gas Compressor Suction Drum: Manhole opened & boxed up after inspection & cleaning. No repairing was required.
- 105-F, Synthesis Gas Compressor 1st stage separator: Manhole opened for inspection and then boxed up. No damage / looseness were observed.
- 110-F (1st Stage), 111-F (2nd stage), 112-F (3rd stage) Refrigerant Flash Drum: Manholes opened for inspection, cleaning done and then boxed up. No damage / looseness were observed.

OPEN INSPECTION & HYDROTEST OF BOILERS:

Open inspections as well as hydro test of the following boilers were successfully executed in presence of IBR inspector:

Sr. No.	Tag No.	Identification No.	Hydrotest Pressure (kg/cm²)
1	112-C	Boiler NO GT-1631	15.0
2	101-F	Boiler No. GT-1632	146.0
3	107-C	Boiler No.GT-5217	67.5

RELIEF VALVES OVERHAULING

SAFETY RELIEF VALVES OVERHAULING & SERVICING

The following RVs were overhauled and serviced and tested on test bench:

Sr. No.	RV Tag NO	Valve Size	Set Pressure (kg/cm²) g
1	RV-101-F 1	2.5" X 6" (2.545)	118.80
2	RV-101-F 2	2.5" X 6" (2.545)	117.00
3	RV-101-F 3	2.5" X 6" (2.545)	115.30
4	RV-101-B	3" X (3.6) X 6"	111.70
5	PSV-986 (107-C)	4 L 6	45.00
6	PSV-987 (107-C)	4 L 6	46.30
7	RV-104-D1	6 Q 8	35.00
8	RV-103-J	3 K 4	159.00
9	RV-103-JA	3 J 4	158.90
10	RV-105-D	3 K 4	153.00
11	RV-105-D-A	3 J 4	152.90
12	RV-106-F	1.5" X 2"	157.90

Sr. No.	RV Tag NO	Valve Size	Set Pressure (kg/cm ²) g
13	RV-102-F	6 R 8	30.50
14	RV-123-CA	3 J 6	122.00
15	RV-123-CB	3 J 6	122.00
16	RV-MS-9 (Spare)	4 P 6	42.20
17	RV-BFW-1	1-1/2 G 2-1/2	92.00
18	RV-112-CA	1-1/2 H 3	10.50
19	RV-112-CB	1-1/2 H 3	10.50
20	RV-109-F	6 Q 8	19.00
21	RV-110-F (N)	3 L 4	7.00
22	RV-110-F (S)	3 L 4	7.00
23	RV-111-F	4 P 6	6.30
24	RV-112-F	4 M 6	6.30
25	RV-104-D2	1-1/2 F 2	34.10
26	RV 101-J	4 M 6	36.90

IN-SITU VALVE REPAIRING JOB:

In-situ valve repairing of Isolation valves of PIC-13A & PIC-13B (Valve Size: 6" X 1500#) were carried out by M/s. Flotech Technosmart (India) Pvt. Ltd. against CPA No. 201004151418 dated 05/03/2015.

- Dismantled bonnet assembly.
- Visual inspection of dismantled parts carried out.
- Lapping of seat & seat ring, Cleaning and polishing of bushings, Replacement of gland packing & Cleaning / greasing of all internals carried out.
- Blue matching of trim parts checked.
- Assembly of valves done.


Flange of PIC 13 B was having leakage which was furmanited during normal operation of Plant. Dents observed in flange face was built up by welding and was boxed up.

FABRICATION JOBS:


WO 201004151471 dated 10/03/2015 was placed on M/s. J & J Engineers to carry out following jobs:

- **Replacement of common minimum flow line of semi lean solution pumps, 115-JA & 115-JB and split stream solution pumps, 116-J & 116-JA**


In recent past, frequent aMDEA leakage problem occurred in common minimum flow line of semi lean solution pumps, 115-JA & 115-JB and split stream solution pumps, 116-J & 116-JA where patch plates were welded to arrest the leakage but leakage still persist. Therefore, it was decided to replace the complete line i.e. Line Nos. MDEA 1210.05 6", MDEA 1210.06 6", MDEA 1212.05 12" & MDEA 1212.06 12" by SS304 material.



Isometric Drawing of Line No. : MDEA-1212.05-12" (B24) & MDEA-1212.06-12" (B-24)




Isometric Drawing of Line No. : MDEA-1210.05-6" (B24) & MDEA-1210.06-6" (B-24)



REMARKS :-

- FIELD WELD JOINT
- WELD JOINT

WELD JOINT DETAILS OF NEARBY FABRICATED LINE NO. : MDEA-1212.05-12" (B24) & MDEA-1212.06-12" (B24)



The approximate quantity and material used for fabrication is given in the table below:

SR. NO.	ITEM CODE	STORE DESCRIPTION	UOM	QTY. CONS UMED	TOTAL RATE
1	0000991030118B10	PIPE - SS SEAMLESS ASTM A 312 TP 304 12" NB (300 MM) SCH - 10 PLAIN END (PE)	Meter	46.49	546350
2	0000991030115B20	PIPE - SS SEAMLESS ASTM A 312 TP 304 6" NB (150 MM) SCH - 10 BUTT WELD (BW)	Meter	20	70352
3	0000991041218E20	PIPE - SS ERW / WELDED ASTM A 358 GRADE 304 12" NB (300 MM) SCH-40 BUTT WELD (BW)	Meter	5.45	45407
4	0000991190718B20	ELBOW - SEAMLESS, 90 DEG., LONG RADIUS, ASTM A 182 F304, 12" NB (300 MM) SCH - 10, BUTT WELD (BW)	NO.	9	178092
5	0000991170718B60	ELBOW - SEAMLESS, 45 DEG. LONG RADIUS, ASTM A 182 F304, 12" NB (300 MM) SCH - 10, BEVEL ENDS CONFIRMING TO ANSI B 16.9	NO.	4	44676

SR. NO.	ITEM CODE	STORE DESCRIPTION	UOM	QTY. CONS UMED	TOTAL RATE
6	000991192315B20	ELBOW - SEAMLESS, 90 DEG., LONG RADIUS, ASTM A 182 F304, 6" NB (150 MM) SCH - 10, BUTT WELD (BW)	NO.	3	6945.07
7	0000891192315B20	ELBOW - SEAMLESS, 90 DEG., LONG RADIUS, ASTM A 182 F304, 6" NB (150 MM) SCH - 10, BUTT WELD (BW)	NO.	5	15504
8	0000991702252C20	REDUCER CONCENTRIC, ASTM A 403 WP304, 12" X 6" SCH 40 X SCH 40, BUTT WELD (BW)	NO.	1	7097.21
9	0000991562315B20	TEE EQUAL - SEAMLESS ASTM A 182 F304L 6" NB (300 MM) SCH - 10 BUTT WELD (BW)	NO.	1	5906
10	0000991560718B20	TEE EQUAL - SEAMLESS ASTM A 182 F304 12" NB (300 MM) SCH - 10 BUTT WELD (BW)	NO.	2	48756
11	0000991400718470	FLANGE - SLIP ON (RF) ASTM A 182 F304 12" NB (300 MM) 300 # SLIP-ON (SO)	NO.	2	22440
12	00009914008182A0	FLANGE - SLIP ON (RF) ASTM A 182 F304L 12" NB (300 MM) 150 # SLIP-ON (SO)	NO.	1	9412.12
13	00009914008152A0	FLANGE - SLIP ON (RF) ASTM A 182 F304 6" NB (150 MM) 300 # SLIP-ON (SO)	NO.	2	7202.24
14	0000992190805G20	GATE VALVE ASTM A 182 F 304, 3/4" NB (20 MM) 800 # SCOKET WELD (SW)	NO.	3	15593.3
15	0000991922115E10	NIPPLE - LONG / SHORT ASTM A 312 TP 304L 3/4" X 4" LONG SCH - 40 PLAIN END (PE)	NO.	3	450
16	2010912541102010	FILLER WIRE AWS/DIN ER 308L D&H SIZE : 2.5 MM	KG	26	13809.6
17	2010912523003010	WELDING ELECTRODE AWS TYPE AWS E308L-16 (FOR SS 304L) 3.15MM STANDARD	NO.	300	6398.46
18	2010912523002010	WELDING ELECTRODE AWS TYPE AWS E308L-16 (FOR SS 304 L) 2.5MM MAKE : D&H	NO.	480	7775.38
19	2010912510303010	PARTY'S ARGON GAS CYLINDER	NO.	25	14350
20	2010912510303020	IFFCO'S ARGON GAS CYLINDERS	NO.	15	8086.22
Total: Rs.					1074603

- **Replacement of passing PDR tapping Root valves of 101-CA/CB downcomers and risers.**
 - Valves were cut and removed.
 - 2 nos. New Isolation valves (Gate Valve: 3/4" X 1500#, SW) with threaded Nipple & Tee provided at each & every PDR tapping Root valves of 2 nos. downcomers (each having 2 root valves) and 4 nos. risers (each having 1 root valve). (Total 16 Nos valves).
 - All Socket Weld joints were DP tested.
- **Provision of drain on risers of 101-CA & 101-CB.**
 - Unbolted & removed blind flange from all risers.
 - Hole drilled at centre to accommodate 3/4" X Sch 160 pipe.
 - Pipe with 2 nos. new Isolation valves (Gate Valve: 3/4" X 1500#, SW) provided on all risers (Total 4 nos). (Total 8 Nos valves)
 - Fixed flange at their respective positions.
 - 3/4" X Sch 80 pipe welded at d/s of valves. All riser drain lines connected & routed upto ground floor drain pot.
 - All Socket Weld joints were DP tested.

SR. NO.	FABRICATION JOBS
1	104-JAT steam inlet I/V with counter flanges & bypass valve replaced (Flanged Gate Valve: 8"X 900# , 1-1/2" X 1500#)
2	Extra Flange provision (SORF, Size: 24" X 150# - 2 nos.) made in 115-JBT Exhaust line for easy removal of exhaust line & turbine top casing to carry out turbine overhauling.
3	103-JAT steam Inlet bypass valve gland leak (furmanited) (Globe Valve, SW, Size: 1" X #2500)
4	101-CA/CB DM Water inlet 1 st I/V (SW Gate Valve, 3/4" X 1500#) replaced.
5	111-J discharge to 109-C passing I/V (Gate Valve Size: 2" X 800#) replaced.
6	I/V (SS, SW Gate Valve, Size: 3/4" X 800#) provided in seal flushing line of both pumps, 116-JA/JB
7	HE-1C shell side drain valve replaced
8	Steam inlet to C2 PI root I/V replaced
9	SR-2 outlet Ammonia line FT orifice by-pass valve replaced.
10	BFW to utility line drain valve between both I/V replaced
11	2 nos. valve provided in BFW to utility (FIC-20) bypass line
12	HCV-12 Sealing steam line I/V (3/4"X800# - 1no. SW Gate Valve) replaced
13	THIC 60 bypass valves (3/4"X1500# - 2nos. SW Gate Valve) replaced.
14	103-JBT steam inlet line Trap I/V bonnet leak – valve replaced
15	101-BJT steam inlet vent line valve replaced.
16	I.D. Fan steam inlet TTV drain line elbow leak – Line fabricated & replaced.
17	108-D Platform repaired.

18	Rerouting of instrument air line & RV exhaust line carried out which was fouling during HP cylinder dismantling of 117-J.
19	105-JT Exhaust RV pipe pin hole leak repaired by patch plate welding.
20	115-JB LO Cooler outlet line to filter R.O. Weld joint crack repaired.
21	Provision for transmitter on 101-JCA made by taking 2 nos. ½" tapping on shell top.
22	Blind provided in BFW line near 123-J Pump
23	Sample point tappings taken from all 4 nos. vents of CW jacket of Transfer line 107-D & extended upto the Arch burner floor level.
24	131-JC shell side drain line elbow thickness reduced to 2.0mm. Elbow replaced by new one.
25	Reduction in thickness observed in Line No. A-22-4". As the line is redundant, it was disconnected from Line No. A-20-10" by cutting & blind plate welding done.
26	Reduction in thickness observed in Vent of 130-JC i.e. Line No. A-32-6". Pipe portion with reduced thickness was cut & new pipe piece welded.
27	LP Steam header corroded line with i/v replaced.
28	MP Steam header corroded drain line with I/V & trap at pillar near FSH4 replaced.
29	Plugs of 1" and 1/2" provided in Naphtha line near auxiliary boiler.
30	Provision of vent line with I/V made at 101 BJT LO Cooler inlet line and outlet line
31	Rerouting of 103-J SO pump (Turbine driven) discharge line carried out to make it separate from standby pump (Motor driven) discharge line.
32	Repaired leakage of 103-D TI near FR-33 root I/V.
33	Shed installed over 103-J LO/SO skid.

VALVE GLAND REPACKING JOBS:

Gland packing of the following valves was replaced by new ones:

- All adjoining valves of 101-F & 107-C
- HCV-12 Sealing steam inlet I/V
- FICV-482 bypass valve.
- PT-12 I/V.
- LP steam to 153-C 2nd I/V
- 101-F Blowdown valves near Aux. Boiler (10 nos.)
- 181-C Main I/V. Gland bolts also replaced.
- 112-JAT Steam Inlet I/V.
- PIC-13A & 13B
- SP-5 & its bypass valve
- SP-39
- All adjoining valves of 112-C.

GASKET / VALVE REPLACEMENT & MISCELLANEOUS JOBS:

SR. NO.	JOB
<u>GASKET REPLACEMENT</u>	
1	PIC-13B upstream flange leak (furmanited) – Groove repaired by weld deposition & filing. Gasket (Size: 6" X1500# SW) & Studs (Size: 1-3/8" X 265mm Long) replaced.
2	SP-39 valve flange leak - Gasket (Size: 18" X 300# SW – 2 nos.) replaced.
3	SP-5 valve upstream flange (furmanited) & valve bonnet leak - Groove on flange repaired by weld deposition & filing. Flange gasket (Size: 8" X300# SW) & valve bonnet gasket replaced.
4	103-JAT Steam Inlet Strainer flange leak – Copper Gasket (Size: 342 mm OD X 307 mm ID X 1.5 mm Thk. – 1 no.) replaced.(Store Code: 112540624710)
5	PRCV-25 u/s i/v u/s flange leakage (Furmanited) - Flange gasket (Size: 4" X 400# SW) replaced.
6	107-C South Side LG Top I/V Bonnet Leak – Valve Bonnet gasket replaced.
7	MP Steam to 103-J LO AND SO Turbine Header End Flange Leak – Gasket (Size: 6" X 600# SW – 2 nos.) replaced
8	103-JAT Leak-off line RV u/s flange leak - Flange gasket (Size: 3" X150# SW) replaced.
9	FIC-20 2ND I/V Bonnet Leak(Furmanited) - Valve (Size: 3" X 1500#) bonnet gasket replaced.
10	101-BJT leak-off line flange leak - Groove on flange repaired by weld deposition & filing. Flange gasket (Size: 3/4" X300# SW) replaced.
11	181-C steam inlet I/V bonnet leak - Valve (Size: 4" X 300#) bonnet gasket replaced.
12	103-D air inlet NRV passing – New gasket seat ring made in w/s & new gasket provided.
<u>VALVE REPLACEMENT</u>	
1	105-E Level Gauge I/V (Size: 1-1/2" X 600# - 2 nos.) & drain line 1 st & 2 nd I/V (Size: 3" X 600# - 2 nos.) passing – Replaced Ball valves.
2	121-JA NRV passing – NRV (Size: 6" X 300#) replaced.
3	CW supply to CG Circulator LO system I/V corroded - Gate Valve (Size: 2" X 150#) replaced.
4	RV-141-F with I/V installed .
5	103-J Lube oil coolers cooling water outlet valve non operatable – New Sandwich type Butterfly valve (Size: 4" X 150# - 2 nos.) provided.

<u>MISCELLANEOUS JOBS</u>	
1	115-JA and 115-HT Flushing Fluid Line PCV Bottom Plug Leak - Attended
2	105-CA tube outlet elbow vent line union leak - Attended
3	101-BJT Leak Off Line both union Leak - Attended
4	AMERAL Charging Pot Drain Line Plug Valve leak – Greasing done
5	LPFV 5 th & 6 th LG (from bottom) bottom & top I/V not operatable. 1 no. LG to be fixed at any one point. – Valves made operatable & 1 no. new LG fixed.
6	103- J Lube oil coolers cooling water outlet valve to be make operatable – New Butterfly valve (Size: 4” X 150# - 2 nos.) provided.
7	124-C cooling water inlet I/V (non-operatable) – Valve roused & greasing done.
8	115-JA/JB, 115-HT, 116-JA strainers cleaned.
9	115-HT strainer drain cap leak - Attended
10	ID Fan Overhead Tank Drain Line threaded joints leak - Attended
11	104-JA inboard bearing side seal water line to seal cooler ferrule leak – New ferrule joint made.
12	103-J LO & SO pump filters replaced.
13	115-JA & 115-JB ARV/NRV Overhauling carried out. All O-rings replaced.
14	116-JA ARV/NRV replaced by spare one.
15	C-1 Vessel Drain Valve Wheel Free – Valve bonnet replaced.

UREA PLANT

(MECHANICAL)

ROTATING EQUIPMENT

Hitachi Compressor Train (Q-1801/K-1801):

The following jobs were carried out during the Annual Turnaround 2015.

M/s. BVL Power, H'bad was engaged with our own maintenance group from date 02/04/2014 to 10/04/2014 to complete the job in time.

- Preventive maintenance of steam turbine (Q-1801).
- Preventive maintenance of LP case (K-1801-1).
- Preventive maintenance of HP case (K-1801-2).
- Preventive maintenance of Gear Box (M-1801).
- Overhauling of Pilot valve of main steam (60 ata), extraction steam (23 ata) & (4 ata) induction steam.
- Overhauling of 23 ata extraction check valve (NRV).

Preventive Maintenance of CO₂ Compressor drive Turbine (Q-1801)

Turbine was taken for preventive maintenance. Following activities were carried out:

- Decoupled the Turbine from LP case.
- Alignment of Turbine and LP case was checked and **found ok**.
- Journal bearing assembly on free end side was opened for inspection. Found clearance values within acceptable limit. (Ref Table-1).



- Journal bearing assembly on LP case side was opened for inspection. Found clearance values within acceptable limit. (Ref Table-1).



- Thrust bearing was opened for inspection. Clearance values were found within acceptable limits.
- **Turbine float: 0.21mm; Net float = Total float – Housing play = 0.33mm - 0.12mm (Design float: 0.25mm to 0.35mm)**
- Gauss measurement of Journal and thrust bearing pads, base rings, shaft journal, thrust collar were carried out, found within acceptable limit.
- DP testing of pads, thrust collar and journal shaft was done and the same were found acceptable.
- Final alignment readings were taken and corrected as per protocol readings. Details are given in report.



- LP case and Turbine was coupled at the required tightening torque 53.2 kgf.m (521.36 N. m). The Coupling spacer between LP casing & Turbine was assembled.

Bearing clearance for Turbine

Description	Front End - Journal bearing	Rear End - Journal Bearing
Journal diameter, mm	Ø124.81	Ø159.73
Bearing bore, mm	Ø125.08	Ø160.02
Shell bore, mm	Ø160.00	Ø204.98
Pad thickness, mm	17.46	22.47
Clearance, mm	0.25	0.34
Design Clearance, mm	0.18 to 0.31	0.24 to 0.35
Interference, mm	0.02	0.01

Preventive Maintenance of CO₂ Compressor LP case (K-1801-1)

LP compressor was taken for preventive maintenance. Following activities were carried out:

- Decoupled the LP case from gearbox and Turbine.
- Alignment of LP case with gear box and turbine was checked and **found ok**.
- Journal bearing assembly on GB side was opened for inspection. Found clearance values within acceptable limits (Ref Table-2).
- Journal bearing assembly on Turbine side was opened for inspection. Found clearance values within acceptable limits (Ref Table-2).
- Thrust bearing assembly was opened for inspection. Clearances value found within acceptable limits.
- Axial thrust : **0.36 mm** (design value : 0.28mm to 0.38mm)
- Gauss measurement of Journal and thrust bearing pads, base rings, shaft journal, thrust collar were carried out, found within acceptable limits.
- DP testing of thrust pads, thrust collar and shaft journal was done and the same found acceptable.
- Alignment of Turbine - LP Case and LP case – Gear Box was corrected as per protocol values. Details are given in the report.
- LP case with Gear box was coupled at required tightening torque 20 kgf.m (196 Nm) and with turbine was coupled at the required tightening torque 53.2 kgf.m (521.36 N. m). Finally spacers between Turbine - LP case and LP case - Gear box were assembled after alignment correction.

Bearing Clearances Data Sheet of K-1801-1

Description	Turbine side - Journal Bearing	Gear box side - Journal Bearing
Journal diameter, mm	Ø119.98	Ø119.98
Bearing bore, mm	Ø120.12	Ø120.13
Shell bore, mm	Ø185.00	Ø185.01
Pad thickness, mm	32.44	32.44
Clearance, mm	0.14	0.15
Design Clearance, mm	0.11 to 0.15	0.11 to 0.15
Interference, mm	0.07	0.11

Preventive Maintenance of CO₂ Compressor HP case (K-1801-2):

HP compressor was taken for preventive maintenance. Following activities were carried out:

- Decoupled the HP case from Gear box
- Alignment readings were checked and **found ok**.
- Journal bearing assembly on Gearbox side was opened for inspection. **Found clearance values within acceptable limit (Clearance values measured are given in Table-3).**
- Journal bearing assembly on free end side was opened for inspection. **Found clearance values within acceptable limit (Clearance values measured are given in Table-3).**



- Thrust bearing was opened for inspection. Clearance values found within acceptable limits.
- Axial thrust: **0.32mm** (design value : 0.25 to 0.35)
- Gauss measurement of Journal and thrust bearing pads, base rings, shaft journal, thrust collar were carried out, found within acceptable limit.
- DP testing of thrust pads, thrust collar and shaft journal was done and the same found acceptable.
- Alignment between HP-Gearbox was corrected as per OEM reference values. Details are given in this report.
- HP case and Gear Box was coupled at the required tightening torque 9.7 kgf.m (95.06 Nm).

Bearing Clearance (Diametrical Clearance) Details for HP case

Description	Gear side – Journal bearing	Rear end – Journal bearing
Journal diameter, mm	Ø79.99	Ø132.00
Bearing bore, mm	Ø80.12	Ø131.87
Shell bore, mm	Ø132.00	Ø132.00
Pad thickness, mm	25.94	25.94
Clearance, mm	0.15	0.13
Design Clearance, mm	0.11 to 0.14	0.11 to 0.14
Interference, mm	0.10	0.06

Preventive Maintenance of GEAR BOX M-1801

Gear Box was taken up for major overhauling. Following activities were carried out:

- Decoupled the Gear box from LP case and HP case
- Alignment of Gear box with LP case and HP case was checked and **found ok.**



Low-speed Gear Shaft and Bearings

- Both Low speed shaft bearings (Elliptical Type) were inspected and clearances values found within acceptable limit. (Clearance values measured are given in Table-4).
- Gauss measurement of pads, journal shaft, thrust collar and bearing was carried out by Inspection section **and found ok.**
- DP checking of thrust bearing pads, thrust collar, journal shaft and bearing was done and found satisfactory.

High-speed Pinion Shaft and Bearings

- Both Pinion shaft bearings (Offset Halves Type) were opened for inspection **and found ok.**
- Gauss measurement of shaft journal and bearing was carried out by Inspection section and found within acceptable limits.
- DP testing of shaft journal & bearing was done and the same was found acceptable.
- Assembly was done using the same bearings.
- Alignment between LP case – Gear box and Gear box – HP case was corrected as **per protocol readings.** Details are given in this report.
- Gear Box with HP case was coupled at the required tightening torque 9.7 kgf.m (95.06 Nm) and with LP case was coupled at required tightening torque 20 kgf.m (196 Nm)

Bearing clearance for Gear Box

Description		Before O/H (mm)	Design Value (mm)	After O/H (mm)
Low speed shaft	Journal bearing clearance on LP side (Front)	0.15	0.125 to 0.185	0.15
	Journal bearing clearance on HP side (Rear)	0.15	0.125 to 0.185	0.14
	Thrust bearing clearance	0.40	0.38 to 0.61	
High speed shaft	Journal bearing clearance on LP side (Front)	0.18	0.15 to 0.21	0.20
	Journal bearing clearance on HP side (Rear)	0.24	0.15 to 0.21	0.20
Gear backlash		0.47	0.383 to 0.608	0.43

Overhauling of Pilot valve of main steam (60 ata), extraction steam (23ata) and induction steam (4 ata) and NRV (23 ata)

Main Steam (60 ata) Pilot Valve


- Pilot assembly was dismantled
- All parts were thoroughly cleaned
- Boxed up the pilot valve assembly using new sealing set

Extraction Steam (23 ata) Pilot Valve

- Pilot valve assembly was dismantled. (Drawing no. 0-0006-1910-07)
- All parts were thoroughly cleaned.
- Boxed up the pilot valve assembly using new sealing set.

Extraction Steam (23 ata) NRV


- Top cover of NRV was removed. (Drawing no. 0-0006-2352-04)
- NRV flap (jointing disc) blue matching was checked with seating area. Found satisfactory.
- NRV Condition was checked and found ok.
- All parts were thoroughly cleaned
- Top Cover was boxed up with new serrated gasket.





Induction Steam (4 ata) Pilot Valve

- Pilot valve assembly was dismantled.
- All parts were thoroughly cleaned
- Boxed up the pilot valve assembly using new sealing set.


Alignment between Turbine and LP Case








(Correction : 0.05 sim was added to LP Base)



Alignment between LP Case and Gear Box





Alignment between Gear Box and HP Case





DBSE at outward position of each shaft

Description	DBSE (mm)
Turbine - LP case	737.47
LP case - Gear box	674.54
Gearbox - HP	337.36

Calibration of control valve lift w.r.t secondary oil pressure

After assembly of governing system, calibration of control valve lift for 60 ata, 23 ata & 4 ata steam was done with variation of secondary oil pressure respectively in the presence of production and instrument departments.

Sr. No.	WW-505 DCS out-put in %	60 ata		23 ata		4 ata		Milli Ampere MA
		Secondary oil pressure	Valve Lift (Div)	Secondary oil pressure	Valve Lift (Div)	Secondary oil Pressure	Valve Lift (Div)	
1	0	1.5	0	1.5	0	1.5	0	4
2	10	1.7	4	1.7	1			
3	20	1.94	9	1.94	1.8			
4	30	2.2	12.5	2.2	3	2.15	14.5	8
5	40	2.5	16	2.5	5			
6	50	2.8	19.8	2.8	6.8	2.9	33.5	12

7	60	3.11	23.4	3.11	8.6			
8	70	3.5	28	3.46	10.2			
9	80	3.9	33	3.8	13	3.7	46	16
10	90	4.2	36.5	4.17	15			
11	95	-	-	4.31	17			
12	100	4.6	41	4.51	31	4.58	63	20

Pre - charging of Nitrogen in oil accumulator of control oil system:

Nitrogen pressure was checked in oil accumulator of control oil system of turbine. Pressure was **2 kg/cm² g**. Nitrogen was filled in accumulator bladder up to **2.7 kg/cm² g** with the help of Kit supplied by OEM.

MAJOR OVERHAULING OF LUBE OIL TURBINE (Q-1814)

Lube oil turbine was in service for the last 04 years after major overhauling in 2010. So, it was taken up for major overhauling in 2015 shutdown. Details of turbine are given below:

Make : Coppus
 Model No. : RLA 16E,
 Sr. No. : 96T2398
 Power : 75 KW,
 Speed : 2960 rpm
 OST : 3582 rpm

Governor Details

Make : Woodward
 Model : TG-13
 Part No. : F8516-039
 Serial No. : 11910153
 Speed Range : 2400-4000 RPM
 Direction : CW

(Note: This governor is interchangeable with the governor of 2004 JT)

Following activities were carried out:

Dismantling of Turbine

- Decoupled the turbine with pump. Measured the distance between coupling halves and it was **137.88mm (DBSE: 141.58mm)**.
- Alignment of turbine with lube oil pump was checked in cold condition **and found disturbed with reference to protocol values.**
- Disassembled the Governor & Stop valve assembly and removed the OST assembly.
- Bearing and Gland housing of governor end were removed. Carbon rings were found in good condition.
- Opened the casing and measured the position of sector from casing face & recorded the readings. (Ref. Table 5).
- Removed the bearing and gland housing of coupling end. Carbon rings were found hard.

- Removed the rotor and sector and found good in condition.
- Cleaning of old rotor was carried out with emery paper and Corium Z-97.



View of rotor of turbine

Assembly of Turbine

- Rotor was fitted into casing.
- Sector was placed between the two rows of blades on the wheels of rotor and rotor along with sector was slide into casing.
- Sector cap screws were tightened after ensuring that sector was solidly seated against the casing shoulder.
- Reassembled the gland assembly at coupling end with new carbon ring (Ref. Table 6). Grafoil was provided between gland housing and casing.
- Reinstalled the coupling end bearing 6309 C3 (new bearing) and associated components.
- Reassembled Casing cover with grafoil and bolts of casing were tightened.
- Reinstalled the governor end gland assembly with new carbon rings. (Ref. Table 6). Grafoil was provided between gland housing and casing cover.
- Reinstalled the governor end old bearing, and associated components. Reinstalled mounting housing. Connected the connecting rod to the trip latch. Reinstalled the over speed trip collar assembly and governor. New governor cover was fitted as old one have cracks in its body.
- After final assembly of turbine checked the alignment between turbine and pump and corrected as per protocol value.
- Coupled the turbine with pump. OST was done at **3545** rpm (protocol value – 3582 rpm).

NOTE:

At the time of installation of NEW bearings in housing, it was found that NEW bearing no. 6309 C3 was loosened in housing on both sides (Coupling and Governor side). So, it was decided to do knurling the bearing seating (housing) area as per requirement in workshop. Still, there was problem of looseness in coupling side bearing. So, Old bearing was installed on coupling side and new bearing was installed on Governor side.

Table 6- Clearance Data Sheet of Q-1814

Sr. No.	Description	Required Value	Actual value (Before O/H)	Actual value (after O/H)
1	Carbon Ring to shaft clearance – governor end	0.0025" - 0.005"		0.003" 0.003" 0.0025" 0.0025"
2	Carbon Ring to shaft clearance – coupling end	0.0005" - 0.003"		0.0015" 0.0015" 0.001" 0.001"
3	Position of sector from the face of casing	-	7.80 mm	7.80 mm


ALIGNMENT READINGS: TURBINE TO PUMP

Dial on Turbine Coupling


All values are in mm

Before O/H

RADIAL




AXIAL




Protocol Value


RADIAL



AXIAL




After O/H



REPLACEMENT OF SHAFT OF EXHAUST AIR FAN, K-1702

Frequent failures of Fan Drive End bearing were occurred in the month of Feb & March-2015 and all these failures are mainly due to looseness of Bearing adapter sleeve on the fan shaft. OD of shaft at the bearing portion is damaged and became undersize due to scoring on the shaft surface. (See pictures below)



So it was decided to replace the fan shaft in the shutdown.

For the removal of fan shaft, first it was tried to remove the fan shaft by jacking it towards the derive end side, and for that pulley and drive end side bearing was removed and fan impeller was locked in the casing. Even after heating the fan hub by gas cutting and hydraulic jacking the shaft, it could not moved. So finally it was decided, to lift the complete rotor by removing the fan top casing half and exhaust hood.

So fan exhaust hood and top casing half was removed by lifting with the kobelco crane.



For the easy lifting/removal of Fan rotor, a top segment of suction cone was also cut which was re-welded after positioning of fan rotor which is shown in attached photograph.



After removal of Fan rotor, it was sent to the works of OEM M/s C.B Doctor, Vatva , Ahmedabad for the fixing of new shaft in the rotor and final balancing.

Removal of old damaged fan shaft, fixing of new spare fan shaft, final balancing & polishing of the fan rotor was carried out at M/s C.B Doctor works.

Refurbished rotor of fan was again positioned in the bottom casing and then top casing half and exhaust fan hood was again bolted in the position. Painting of exhaust hood and top casing was done before reinstallation.



During final assembly of Fan rotor drive end side bearing housing, both ends Bearings SKF 22328 CCK C3 W33 along with its adapter sleeve H2328 were replaced.

After assembly of bearings, final clearance was maintained as 0.10-.012 MM.

After assembly of bearing and bearing housing centering of bearing housing and bearings were also carried out with help of dial gauge.

Finally pulley was positioned and alignment was carried out with new installed belts.

Provision for removal of bearing housing back cover bolts was done by cutting the C-sector plate and then fix it at the position by bolts & nuts for its easy removal, which creates sufficient space in the back side of bearing for opening the bearing cover bolts.


HP VESSEL

Autoclave V-1201

Helium Leak detection and repairing

Leak was suspected in Autoclave before shutdown and for the identification of that suspected leak, Helium leak detection method was used.

Observation: In Helium leak detection, a pinhole leak was observed in bottom C-seam of insert liner in the 10th compartment. See photographs below:



Repairing of Pin Hole Leak

Pin Hole was grinded locally and then DP Tested and then repaired by following procedure:

- DP of grinded portion was carried out.
- Welding was done by TIG using 25 -22-2LMn filler wire size - 2.4 mm dia with low heat input.
- Inter pass temperature kept below 150 deg. C.
- It was ensured that no area was left ground without welding
- Final DP was carried out.
- Ferrite content was checked. It was found within acceptable limit (Max 0.6 %) Finally weld was cleaned and passivated by washing with 10 % HNO₃ and rinsing with DM water


Repair of Liner weld joints of Autoclave

Liner welds of each compartment of V-1201 were most affected by corrosion. It was decided to repair liner weld one by one during shutdown.

- During shutdown 2009 liner welds of 1st and 3rd compartment were repaired
- During shutdown 2010, liner welds of 2nd and 4th compartment were repaired
- During shutdown 2011, liner welds of 5th compartment were repaired.

- During shutdown 2012, liner welds of 6th compartment were repaired.
- During shutdown 2014, liner welds of 7th and 8th compartment were repaired.

During shutdown 2015, repairing of liner weld of 9th & 10th compartment was carried out. M/s Shree Ganesh Engineering, Ahmedabad (CPA 201004151419) was engaged along with our own fabrication and inspection group for above job.



The following repair procedure was followed:

- Weld area was cleaned by SS wire brush.
- Welding joint was ground and flushed. Visible pitting / pores were removed with Grinder and surface was made smooth. It was ensured that grinding was not done deeper than 2 mm below the surface of liner.
- Corroded area of Heat Affected Zone of joints was also grinded and removed.
- DP of grinded portion was carried out. Porosity observed was removed. However if the porosity extends deeper than 2 mm below the surface of liner, it was fused while performing welding.
- Welding was done by TIG using 25-22-2LMn filler wire size -2.4 mm dia with low heat input.
- Inter pass temperature kept below 150 deg. C.
- Minimum three layer of weld was required. At some portions where the width was increased due to removal of corroded portion, an additional layer of welding was applied.
- It was ensured that no area was left ground without welding
- Final DP was carried out.
- Ferrite content was checked. It was found within acceptable limit (Max 0.6 %)
- Finally weld was cleaned and passivated by washing with 10 % HNO₃ and rinsing with DM water.

Repairing jobs as per Inspection Report

The following repairing jobs were carried out as per Inspection report:

Compartment No.1 (Top Compartment)

- 1no of missing "J" bolt was provided just near down comer funnel at north side.
- There are few defects which are marked as **D1, D2 and D3** were repaired
- **D1**- In Shell liner South-West side, besides "L" Seam Pits/Localized erosion of 1 to1 .5 mm depth, 10-12 mm in Dia .
- **D2** –another localized pit besides D1.
- **D3** – In East direction near stairs localized pit 5 to 6.0 mm in Dia and 1 to 1.5 mm in depth.

Compartment No.2

- Few nos. of tray holding 'J' bolts, tray segment loose fasteners were tightened
- There are few defects which are marked as **D1 & D2** were repaired.
- **D1** – Noth – West side just above "C" Seam near clit welding localized pit/ erosion of 2" long and 1.0-1.5 mm in depth observed.
- **D2** – In Other side of same clit localized pitting / erosion of 2" long and 1.0-1.5 mm in depth observed..

Compartment No.3

- There are few defects which are marked as **D1, D2 and D3** were repaired.
- **D1** - North side just above “C” Seam near clit welding localized pit/ erosion of 2” long and 1.0-1.5 mm in depth observed.
- **D2** – Besides D1 defect in west direction near clit welding localized pit/ erosion of 1.5” long and 1.0-1.5 mm in depth observed.
- **D3** – In North –West direction one no old clit is not properly removed and its welding has developed crevices with shell liner which is required to be ground / re welded.

Compartment No.4

- There are few defects which are marked as **D1, D2,D3 and D4** were repaired:
- **D1** – North-West side just above “C” Seam near clit welding crevices developed along the clit length.
- **D2** – In East direction besides clit welding localized pit/ erosion of 1.5” long and 1.0-1.5 mm in depth observed.
- **D3** – In South –West direction near “C” Seam in welding cavity / porosity observed which is required to be ground / re welded.
- **D4** – In south direction just above “C” Seam near clit welding localized Pits / Erosion observed along the clit length.

Compartment No.5

- There are few defects which are marked as **D1, D2 and D3** were repaired:
- **D1** – North side just above “C” Seam near clit welding pits & weld cavity observed.
- **D2** – In East direction besides clit welding weld cavity and at bottom side of “C” seam under cuts / crevices observed with liner 1.5” long observed.
- **D3** – In North –West direction near “C” Seam in Clit welding localized Pits / erosion observed which is required to be ground / re welded.

Compartment No.6

- There are few defects which are marked as **D1, D2** were repaired:
- **D1** – North side just above “C” Seam near clit one side welding was flushed out (Missing)..
- **D2** – In west direction long seam in old welding porosity / pinhole observed.

Compartment No.7

- There was a defects which was marked as **D1** was repaired.
- **D1** – In South – West direction approx 1” below “C” Seam localized pitting / erosion of 1” in length and 1 to 1.5 mm depth observed.

No repair work was required in other remaining compartments. All repairing jobs were done using TIG welding method and 25-22-2 L Mn filler wires. Repaired areas were passivated by 10% HNO₃ and washed with DM water.

During removal of ladder and lightening arrangement from the V-1201, all tray segment bolts were tightened. After taking clearance from Production, top cover was boxed up with new Kempchen make gasket (839 mm OD x 800 mm ID x 4 mm thick) with new 0.5 mm thick Teflon envelop.

- Tightening pressure for top cover.

1 st tightening round	300 kg/cm ²
2 nd tightening round	500 kg/cm ²
3 rd tightening round	700 kg/cm ²
Final tightening round /checking round	700 kg/cm ²

HP Stripper (H-1201)

Bottom Dome

- Bottom cover was removed using bolt tensioner at 900 kg/cm².
- The bottom cover was lowered onto the wooden sleepers.
- After inspection, the bottom cover was boxed up.
- No repairs /rectifications were required to be carried out.

Top Dome

- Top cover was removed using bolt tensioner at 900 kg/cm².
- The top cover was shifted below the platform using monorail hoist and chain blocks.
- Ferrules were removed from position. Ferrules were thoroughly cleaned by Production department.
- Eddy current testing was carried out by Inspection Department. No repair work was required to be carried out.
- The ferrules were fixed in position with new PTFE gaskets (2600 nos).
- After the bottom cover was boxed up, pressure drop measurement was carried out by production department for each tube and the same was found within limit.
- Exchanger was thoroughly cleaned with compressed air and then with DM water.
- Top and bottom cover were boxed up with new "Kempchen" gasket (839 mm OD x 800 mm ID x 4 mm thick) with new 0.5 mm thick Teflon envelope.
- Tightening pressure for top and bottom cover.


1 st tightening round	300 kg/cm ²
2 nd tightening round	600 kg/cm ²
3 rd tightening round	900 kg/cm ²
Final tightening round /checking round	900 kg/cm ²

HP Condenser (H-1202)

- Top flange of off gas lines was opened.
- Bottom flange (H-1202 to V-1201 pipe line) was opened.
- Fasteners of Top cover and bottom cover were loosened using bolt tensioner at 700 kg/cm². Bottom covers were shifted using 2 nos. of 3 ton capacity chain block and top cover was shifted using 1 no. of 5 ton chain block.
- Internals from the top dome were removed.

- Leakage was suspected in HPCC before shutdown, so air test was carried out after removing the internals 2.8 kg/cm² and in air test following O₂ tubes was found leaky.

- Row No. 25, tube No. 27
- Row No. 31, tube No. 23




- After that Eddy current testing of tubes was carried out and based on its finding Tube No.31 of Row No. 35 was plugged. In ECT wall loss of 31-40% was observed and internal pitting was also confirmed in boroscopic inspection.
- Based on visual inspection following repairs were also carried out.

- 06 Nos of Marked crevice cavity in top channel head.
- Approx 1.5mm deep dent was observed on shell liner just above the dome to shell liner weld joint in North-West direction in bottom channel head, marked with Yellow chalk, which is shown in below Photograph.



- 02 nos of Crevice/Cavity observed in the I.D. of Gas Outlet Nozzle to elbow weld were repaired.

- Hydrotest of HPCC shell side was carried out at 11 Kg/cm² and one tube was found leaked (Row No. 23, Tube No. 23) which was plugged.
- Hence total 04 tubes were plugged shown in below picture




- Tube layout drawing for showing the plugged tube location is attached in shutdown report of inspection department. The Stamicarbon and actual procedure for tube plugging in top tube sheet is given below.

Sr. No.	Stamicarbon procedure	Actual procedure for Plugging in top tube sheet
1	Puncture the tube. Confirm by DP test. (At top or bottom end)	Punctured at the top end of tube (approx 60mm from the tube end) and marked its location in bottom tube sheet also using wire.
2	Grind and remove the tube end down until 50% of the tube to tube sheet weld metal is removed.	Grinding of tube end was done until 50% of tube using barring cutter in flexible grinder machine.
3	Clean the tube inside by reaming or by grinding at the location where the plug will be positioned.	Cleaning of tube inside was done using barring cutter in flexible grinder machine.
4	Determine the inner tube diameter	Inner tube diameter was 20.00mm
5	Machine the plugs, material quality equal to material of heat exchanger tube. Dimension shall be maintained as per the sketch given below. L= 25 mm.	Machine the plug as show in figure – 19[4]. Dimension ØD was kept 20.00mm and L was 25.00mm
6	Clean and degrease the plug and the	Cleaned the plug and inner tube hole

Sr. No.	Stamicarbon procedure	Actual procedure for Plugging in top tube sheet
	inner tube hole	by acetone
7	Insert the plug	Punched at 7mm from the end of plug in four direction of plug to hold it at tube. Refer figure- 19[3].
8	Protect the surrounding tube ends very carefully with help of the old PTFE bushing.	
9	Weld the plug in two layers, GTAW (material quality filler wire equal to material of heat exchanger tube; rod diameter 1.2 mm to 2.0 mm); start / stop points staggered to each other After each layer of welding perform a penetrate test and a ferrite check	Root welding was done using TIG welding (filler wire 25 22 2 LMn, 2.0mm dia.). DP check and ferrite check of root welding done. Found satisfactory. Further 2 run of welding was done. DP and ferrite check was done, found ok. Passivation was done using 10 %HNO3 solution and rinsing with DM water After welding

Tube Plugging Sketch of HP Condenser



Note: The Procedure for Plugging in bottom tube sheet was similar to that of top tube sheet.

- Finally Confirmation Hydro test of Shell side was carried out at 11 kg/cm² g.
- After inspection, internals were placed on top dome. Top and bottom cover Boxed up with new Kempchen make gasket (839 mm OD x 800 mm ID x 4 mm thick) with 0.5 mm thick Teflon envelop.
- Tightening pressure for top and bottom cover

1 st tightening round	300 kg/cm ²
2 nd tightening round	500 kg/cm ²
3 rd tightening round	700 kg/cm ²
Final tightening round /checking round	700 kg/cm ²

HP Scrubber (H-1203)

Top dome of HP scrubber was lifted and shifted to check the chocking of gas inlet line. For the lifting of top dome cover of HP Scrubber following activities were carried out:

- Removed the insulation for top dome lifting from following portions.
 - Off gas line flange
 - Flange of top dome and shell
 - Steam tracing line
 - Carbamate Inlet flange
 - CO2 purging Inlet
- Cleaned monorail for top dome and applied grease
- Prepared the scaffolding for offgas flange /steam tracing
- Placed the wooden plank on platform for safe working
- Removed the cap of stud of top dome, cleaned by rustolene and wire brush
- Marked the all process and steam line connections and disconnected.
- Disconnected the following flange of top dome
 - Offgas flange (C3-3"x1500#) ** used safety belt
 - Carbamate solution inlet (C6 - 3"x1500#)
 - CO2 purg conn. (1"x1500,3nos.)
- Cut the steam tracing lines wherever required.
- Prepared the lifting arrangement for top dome (2 nos. of monorail, 2 nos. of 10 ton chain blocks, 2 nos. of 5 ton slings & 2 nos. of hook-chuk) . Mounted the these tools on 2 nos. of trunion and tied sling with hook of chain block for safety purpose
- Loosened the nut one by one using bolt tensioner at 750 kg/cm² g and removed all nuts.
- Disconnected the drain line flange (inside shell, 1/2") after lifting top dome upto stud using chain block place sleeper in between studs for safey of flange seating area of shell.



- Shifted the top dome towards K-1403-3 , placed on wooden sleeper .



- Removed the diaphragm for checking the dome internals.



- Departmental inspection was carried out. No repair work was done.
- Refixed the diaphragm on its position in top dome.
- Shifted the top dome and kept it upto the studs to tighten the inside drain flange.
- Kept the top dome on its position with new kempchen make serrated ring gasket with Teflon envelop.
- Tightened the nut as per procedure (In 4 steps at 300 kg/cm² g, 500 kg/cm² g, 700 kg/cm² g pressure and final check round at 700 kg/cm² g using hydraulic bolt tensioner as per sequence)
- Connected the all flange and welded the steam tracing line flange and Insulation was done.

LP Vessel

Repairing was done in following equipments after manhole opening

V-1101 (CO₂ Knock Out Drum)

New epoxy paint inside of the shell was done. 03 nos. of loosened segments of demister pads were tightened.

V-1423 (1st Stage Evaporator Scrubber)

- Demister pads were found slightly damaged, loosened & lifted at several locations which are rectified.
- Support channels and outer ring of demister pads were found lifted in East, direction, tied by metallic wires which are broken and the same are rectified.

V-1811 (1ST STAGE SEPARATOR)

- Demister drain pipe bottom tack weld found broken, which was again tack welded.

Low Pressure Carbamate Condenser, LPCC (H-1205)

Removal of Tube Bundle Assembly and providing the tube bundle baffle locking

The new LP carbamate condenser (H-1205) was procured from M/s Gansons Limited, Nagpur against the PO 201004131373 dated 14 / 03 / 2014 and was installed in Annual shutdown-2014.

Leakage in 01 no of U-tube (R-2,T-25 & R35, T-25) was observed in Oct-2014 and the leaky tube was plugged. It was decided to lift the tube bundle assembly in the shutdown to know the nature of failure i.e tube fretting due to vibration of tube bundle in the bi-phase condition.

It was also decided to make the provision of locking the tube baffles by jack bolts to minimize the vibration in tube bundle.

Before removing the tube bundle assembly, IRIS inspection of tubes were carried out after hydrojetting of tubes.

Based on the result of IRIS inspection following tubes were recommended for plugging.


- **Row-2/Tube-1, Row-35/Tube-1 (57% Reduction)**
- **Row-1/Tube-14, Row-36/Tube-14 (33% Reduction)**

Activities involved in Removing the tube bundle assembly

- To remove the tube bundle assembly, all connected pipe lines and steam tracing lines were removed and cut from suitable locations.
- Top dish end removed from position.
- Platform above LPCC was also removed.
- Specially lifting fixture was fixed in the eye bolt hole of tube bundle to lift it upto the height of 1 feet and the tube bundle was then wooden sleepers was placed under the tube sheet to enable to weld the special lugs to lifting fixture to transfer the load from eyebolt hole threads to fixtures for safe lifting of tube bundle. (See attached photograp)




- The approx weight of tube bundle was 18 Tonnes.
- Finally tube bundle was lifted and placed on prefabricated stand as shown in attached photographs.





During removal of tube bundle it was observed that 12 mm dia ring welded with baffle plate was found rubbed with the tubes and one of the ring attached to bottom most baffle was found broken also.

Due to rubbing of this ring and tubes severe thinning on some tubes were observed and this was the prominent reason for the failure on one U-tube during Oct-2014. See the below attached photographs.



Photographs of Damaged ring are attached below:






One no. of ring was found broken and lying inside the shell. (See attached photographs below)




After removal of tube bundle internal shell was inspected and various rubbing marks of tube baffle and shell were observed. See the below attached pictures:






After the visual inspection of tube bundle at stand one more U-tube

Row-11 / Tube-1, Row-26 / Tube-1 (50% reduction due to abrasion / rub) Was recommended for plugging.



Final rigging arrangement is attached for reference.

IFFCO INDIAN FARMERS FERTILISER CO-OP. LTD. KALOL



	NAME	DATE	TITLE - RIGGING ARRANGEMENT FOR H-1205				EWR No.	
DRN	N.V. PANCHAL	09.07.2013					SCALE : N. T. S.	
CHD			DRAWING No.	PLANT	FROM	NUMBER	SHEET	REV.
APD			CODE UREA-354	P	2	E S	0 4 - -	1 1 0


To arrest the tube bundle vibration and to stop further failure of tubes, following two steps were taken,

- Removed the 12 MM dia ring attached to all baffles, which was the dominant reason for the premature tube failure.



- Tube Baffle locking arrangement was made which restricts the movement of baffle inside the shell.

For this 03 Nos of support plate / lugs were welded on each tube baffle plates and this type of arrangement was done in 03 bottom most tube baffle plates. (See attached photograph)



Similarly socket and stud locking arrangement was made in shell by drilling the holes at 9 location at exactly 03 baffle elevations and then a patch plate with hole and threaded socket was welded on shell at cut hole position.. (03 bottom most baffles).



Elliptical hole cut in the shell plate at baffle location



Pad plate with threaded socket tack welded will shell place from out side

Then tube bundle was again inserted in the shell and checked the alignment of hole of shell with that of tube baffle plate that baffle plate was just in front of cut holes in shell.

Baffle plate was seen aligned in front of cut hole




After confirming the alignment of pad plate and socket hole with baffle plates, all 09 nos of pad plates with threaded sockets were welded and DP tested.

Finally baffles were locked by tightening the threaded stud in sockets and the secured by tightening of caps with Teflon gasket to made the joint leak proof. (See attached photographs)



Schematic arrangement of baffle locking arrangement is shown below:




Attach dimensional drawing of each component

Before taking the hydrotest of tube bundle, following 03 U-tubes were plugged

Row-2/Tube-1, Row-35/Tube-1 (57% Reduction)

Row-1/Tube-14, Row-36/Tube-14 (33% Reduction)

Row-11/Tube-1, Row-26/Tube-1 (50% reduction due to abraision/rub)



Finally hydrotest was carried out at 11 Kg/cm² and and found OK.

Then top dish end and all connected pipe line, other tracing lines and platform which were removed for lifting the tube bundle were fixed/welded and all blinds provided for hydrotest were removed.

VARIOUS FABRICATION JOBS

Following fabrication jobs were carried out during shutdown:

Replacement of Bottom Elbow (Size: 18" X Sch.10) of H-1205


Bottom elbow of H-1205 was leaking due to various pin holes in the elbow area so it was replace in Shutdown-2015.

Ref.: Below Attached drawing

Material of pipe and fittings: SS-304/SS-304L

Joints Involved:

18" NB X sch.10 :- 02 Joints in position



Following activities were carried out

- Cutting of ½" NB X Sch.40 steam tracing lines.
- Cutting of existing 18" NB X Sch.10 Elbow by grinding at marked locations A & B as shown in above sketch.
- Removal of existing 18" NB X Sch.10 Elbow
- Opening of Bottom flange of H-1205 (18" X 150#)
- Removal of 18" Flange with spool piece.
- Weld edge preparation.
- Fitment of New Flange with Spool Piece and elbow in position.
- Root and final welding by GTAW.
- Inspection including Root weld & final weld DP.
- Welding of Steam tracing lines.
- Final tightening of Bottom flange of H-1205 (18" X 150#) with new gasket.

Replacement of steam Condensate lines (up to elevation of 75.0 mtr.) in Urea Plant

Various steam condensate lines near prill tower which were of carbon steel and are leaking frequently were replaced with SS-304 material.

Piping Material: ASTM A312 Gr 304 Sch.10

Size: 3" NB, 2" NB, 1-1/2" NB

Inch Dia welding involved: 300 Inch Dia

Following activities were carried out;

- Cutting and removal of existing pipe lines by grinding.
- Prefabrication, Fabrication and erection of New SS-304 pipe line in the position.
- Weld edge preparation and fitment of New SS-304 pipe lines.
- Root & final welding by GTAW.
- Inspection including Root weld & final weld DP by IFFCO.

Replacement of existing corroded CS steam tracing lines of High Pressure Lines

- Various corroded steam tracing lines along with valves and traps were replaced with new CS lines.
- Various steam tracing lines were replaced near HP Scrubber.

Steam Tracing Line details:

Seamless Pipe: ½”x Sch 40, Carbon Steel ASTM A106 Grade B

Coupling (Socket weld): ½” x 3000#

Gate Valve: ½” x 800#

Steam Trap: ½’ x 800#


Fabrication and welding of SS-316L liner plate in Dust Silo.

Ref.: IFFCO Drg. No. P2-BS-17024 & P2-BS-17025 (V-1703)

Material of Plate/Liner: SS 316L, Thickness:2 MM

The following activities were carried out during replacement;

- Opening of Dust Silo and removal of old UHD Liner.
- Cutting off SS-316L plates in the required shape and size as per the requirement.
- Fit up and welding of SS-316L plates by arc welding followed by DP Test.



Replacement of valves in Ammonia Lines

Two nos of old flanged globe valves of 4" X 900# rating in Ammonia Pump P-1102/B discharge line and P-1102/C recycle line were replaced by new flanged globe valves of 4" X 1500 rating.

Material of Pipe Line: ASTM A106 Gr.B

Material of Flange: ASTM A 105


Size of New Flange: 4" NB X 1500#. Sch.160

Sketch of valves replaced in P-1102/C recycle line is attached below.

The following activities were carried out;

- Opening and removal of existing 4" NB X 900# flanged valve.
- Cutting of Existing 4"NB X 900# flanges (A & B as shown in the fig.)
- Weld edge preparation and fitment of New 4" NB X 1500# flanges in position considering flange to flange distance of new valve.
- Root welding of New flanges by TIG Welding followed by Root DP and radiography.
- Fill up and final welding by Tig followed by Root DP and Radiography.

Sketch and photograph of valves replaced in P-1102/C recycle line and P-1102/B discharge line is attached below.



P-1102/C Recycle Line Valve



P-1102/B Disch. Line Valve


Replacement and modification in CCS-I line at First Floor

Complete Existing loop of CCS-I line is of carbon steel. In last year we have faced a leakage problem in CCS-I line at first floor and the repairing of that leak was very difficult due to space problem. So it was decided to replace and modify the existing CS loop at first floor with SS-304 material.

Size of Line: 14" NB, 12" NB, 10" NB and 8" NB, Sch.10

MOC: ASTM A 312 TP 304

Refer: Attached Sketch



CCS-1 Modified line at first floor




CCS-1 Modified line at first floor

The following activities were carried out;

- Removal of existing CS, CCS-1 line.
- Fabrication and Erection of new SS-304, CCS-1 line at 1st Floor in Urea Plant
- Inspection including final weld DP by IFFCO.

Modification in Ammonia Supply Line Loop at 1st Floor

Liquid Ammonia is supplied at a pressure of 14-16 Kg/cm² from Ammonia plant to Urea Plant battery limit. The pressure drop in Ammonia supply system was around 1.5-2.0 kg/cm². Due to this pressure drop vaporization of Liquid ammonia may occur at pump suction which is causing the knocking sound in P-1102/C. So a EWR was raised to study and simplify the Ammonia supply loop at 1st floor. Based on the study following sketch of existing and modified sketch was prepared and the line was modified as per modified sketch.



In final modification scheme, following components were removed:

- Vapour Eliminator
- Suction strainers provided at upstream of mass flow meters.
- Only one mass flow meter will remain in line.

The scheme for the EWR U-268 was approved vide note dated 27/03/2015 by competent authority to reduce the pressure drop in Ammonia Supply System of Urea Plant. The scheme was implemented in April 2015 Plant turn around as per the details given below:

- Vapor eliminator was removed from ammonia supply system.
- Strainers provided at upstream of ammonia mass flow meters were removed.
- Associated pipes & fittings were also removed.
- New mass flow meter (FS-1101A) was removed and only one old mass flow meter (FS-1101) is kept for operation.

Process parameters (before and after modification)


After the plant turn around 2015, Urea production has started on 12/04/2015 and plant is under stabilization.

Process parameters before and after modification are given below.

Sr. No.	Description	Unit	Before Modification	After Modification (16/04/2015)
1	Ammonia draw as per mass flow meter	t/h	42.5	42.6
2	Ammonia supply temperature at Urea Plant	Deg C	28	27
3	Ammonia supply pressure at Urea Plant Battery Limit	kg/cm2g	17.4	17.5
4	Ammonia supply pressure at suction vessel	kg/cm2g	15.6	16.4
5	Pressure drop in the ammonia supply system	kg/cm2	1.8	1.1
6	Reduction of pressure drop	kg/cm2	0.7	

With implementation of above modification, the pressure drop in ammonia supply system in urea plant has reduced by about 0.7 kg/cm2.

Final modified and implemented scheme is attached below:



Modification in Off Gas RV Platform and Platform behind the HP Scrubber

Existing platform at Off gas RV's (RV-1201 A/B/C) was of CS structure and is very congested and was very unsafe also. So this RV platform was modified with SS Material I,e with SS 304 railing pipes and gratings and also size of platform was increased for easy in mechanical jobs at RV station.

Photographs of new modified SS platform are attached below:






In addition to that the ms checkered plates in platform of HP scrubber was also replaced with SS-304 gratings.

Fabrication jobs based on thickness report by inspection section:

Replacement of some portion of Line No. SC-1212-10"-C2

During thickness survey of line no. SC-1212-10"-C2, thickness loss was observed on some locations as marked in the attached sketch.





So the line portion from Equal tee of 10"X10" (Connected to HICV-1221A) to TRCV bottom flange was replaced with new one as shown in attached photograph.



Thickness loss in Reducer of Line No. **ST-1502-4",8",2"**

Thickness loss in Eccentric reducer of 12" X 6" and 6" X 4" was observed in line No. ST-1502-4",8",2" i.e line from ST-1116 TO PICV 1502 AND TO V-1503 as shown in the attached report and pictures.





Since the major thickness loss was observed on the top half portion of 12"x6" and 6"x4" reducers and also new reducers of required sizes were not available with us , so patch plate in top half of both the reducers was welded.

Fabrication Jobs related to Instrumentation Section

TAG No. FRCV-1202 (CO2 to HP Scrubber)

Existing angel type control valve replaced with new valve of same size, type and rating. (1" X 1500 #, SS-316L)

TAG No. FI-1204 (Carbamate Solution Flow to P-1201 A/B/C suction at 2nd Floor

Prill Cooling System

Inlet Air Fan (K-1701)

- Visual inspection of both bearing was done. Oil flushing of both bearing was done.
- Alignment of both pulleys was done, Belt replaced by new one and guard was provided.
- Casing and structure of Fan was painted with M/s Mohan Paints on trial basis.

Conveyor System

Prill Tower Conveyors (M-1403-12/3)

M-1403-1 conveyor

- All damaged carrying rollers and return rollers were replaced.
- Alignment was done between gear box to motor and from gearbox to pulley.

M-1403-2 conveyor

- All damaged carrying rollers and return rollers were replaced.
- Gear box oil was flushed. Coupling bush were checked. Greasing of chain and sprocket was done.
- Alignment was done between gear box to motor and from gearbox to pulley.

M-1403-3 conveyor

- All damaged carrying rollers and return rollers were replaced.
- Gear box oil was flushed.
- Coupling bush were checked.
- Alignment was done between gear box to motor and from gearbox to pulley.

Link Conveyor (M-1419)

- All damaged carrying rollers and return rollers were replaced.
- Gear box oil was flushed.
- Greasing of chain and sprocket was done.
- Alignment was done between gear box to motor and from gearbox to pulley.

Prill Cooling System Link Conveyor (M-1421):

- All damaged carrying rollers and return rollers were replaced.
- Gear box oil was flushed.
- Greasing of chain and sprocket was done.
- Alignment was done between gear box to motor and from gearbox to pulley.

Dust Conveyor System (M-1702):

- Gear box oil was flushed.
- Greasing of chain and sprocket was done.
- Alignment was done between gear box to motor and from gearbox to pulley.

Prill Tower Scraper (M-1402-1/2)

Scraper (M-1402)

Scraper oil was flushed.

Fluid Coupling

- Oil of both fluid coupling M-1402-1/2 was flushed.
- Alignment of motor and coupling was done.

Gear Box of Scraper, M-1402-1/2

- Oil flushed.

Prill Tower ID Fan K-1401-1/2/3/4

K-1401-1/2/3/4

- Both fixed and free end bearings of M/s Cooper make were replaced in K-1401/1, K-1402/2 and K-1401/4.
- Belts were replaced in K-1401/2 and K-1401/4

- Alignment of motor and fan pulley was corrected.

V-1501 (4 ATA STEAM DRUM) (GT-1664)

On 09-04-2014, Hydrotest of V-1501 was carried out at 11.10 Kg/Cm²g in presence of Boiler Inspector.

RELIEF VALVE OVERHAULING AND TESTING

Overhauling and testing of RV's were carried out through M/s Flotec Technosmart (India) Private Limited, Surat . Testing of RVs was done on test bench at Urea mechanical works.

Following RV's were removed, overhauled and tested on valve test bench: It was jointly decide by production and maintenance that only critical RV's shall be overhauled every year and non-critical RV's shall be overhauled and tested once in 4 years.

Sr. No.	RV No.	Description	Test Medium	Set Pressure Kg/cm² g	Reset Pressure Kg/cm² g
1	RV-1201 A	V-1201 off gas line	Nitrogen	165	150
2	RV-1201 B	V-1201 off gas line	Nitrogen	165	150
3	RV-1201 C	V-1201 off gas line	Nitrogen	165	148
4	RV-1205	P-1201 A discharge	Water	165	148
5	RV-1206	P-1201 B discharge	Water	165	148
6	RV-1208	P-1201 C discharge	Water	170	148
7	RV-1103 A	P-1102 A discharge	Water	150	135
8	RV-1103 B	P-1102 B discharge	Water	150	135
9	RV-1103 C	P-1102 C discharge	Water	150	135
10	RV-1181	K-1801 final discharge	Nitrogen	177	159
11	RV-1903	K-1801 3 rd stage discharge	Nitrogen	111	100
12	RV-1202A	V-1202 off gas line LP System	Nitrogen	6	5.5
13	RV-1202B	V-1202 off gas line LP System	Nitrogen	6	5.5
14	RV-1202C	V-1202 off gas line LP System	Nitrogen	6	5.5
15	PSV-1201A	P-1201 A Suction line	Water	8.5	7.5
16	PSV-1201B	P-1201 B Suction line	Water	8.5	7.5
17	PSV-1201C	P-1201 C Suction line	Water	8.5	7.5
18	RV-1102 A	Ammonia Suc. Vessel (V-1103)	Water	31	29
19	RV-1901	1 st stage discharge of K-1801.	Nitrogen	7	6.7
20	RV-1902	2 nd stage discharge of K-1801	Nitrogen	27	25.1
21	RV-1501	4 ata Steam Drum	Nitrogen	7.5	6.8
22	RV-1502	4 ata Steam Drum	Nitrogen	7.5	6.6
23	RV-1506	4 ata Steam Main	Nitrogen	6	5.4
24	RV-1221 (CCS-II)	P-1204 disch. To H-1203	Water	16.5	15
25	RV-1916	23 ata Steam extraction	Nitrogen	28	26
26	RV-1917	4 ata Steam exhaust	Nitrogen	4	3.6
27	RV-1130	24 ata steam header	Nitrogen	26	22.5

CLEANING AND HYDROJETTING OF HEAT EXCHANGERS

The Hydrojetting job was awarded to M/s. Hydrojetting Services, Following heat exchangers were opened for cleaning by hydrojetting. After cleaning, exchangers were boxed up with new gaskets.

- Surface Condenser (H-1815)
- Main Lube Oil Coolers (H-1814-A/B)
- Condenser Pre-evaporator (H-1419)
- Flash Tank Condenser (H-1421)
- First Evaporator (H-1422) with DM water.
- First Evaporator Condenser (H-1423)
- Second Evaporator (H-1424) with D.M. water
- Second Evaporator I Condenser (H-1425)
- Second Evaporator II Condenser (H-1426)
- First Evaporator Final Condenser (H-1420)
- Recirculation Heater (H-1204) with D.M. Water
- L.O. Coolers of P-1102-A/B/C
- L.O. Coolers of P-1201-A/B
- Reflux Condenser (H-1352)
- CCS - II cooler (H-1207)
- Hitachi Compressor First stage Intercooler (H-1811)
- Hitachi Compressor Second stage Intercooler (H-1812)
- Hitachi Compressor Third stage Intercooler (H-1813)

NRV Inspection

Following NRVs in Urea Plant were opened, inspected and boxed up.

- CO₂ to H-1201
- NH₃ to H-1202
- NH₃ to V-1201
- Carbamate to H-1202
- Carbamate to H-1203
- CO₂ to H-1203
- 4 ata steam to V-1352
- 23 ata steam to V-1351
- 4 ata steam to V-1301
- Condensate to melt return line
- P-1201 A/B steam injection to discharge RV
- 9 ata steam injection to offgas line of V-1203/V-1207
- 9 ata steam injection to off gas line of V-1205
- NH₃ water to V-1352
- CO₂ to 1st Desorber V-1352
- P-1351 A/B discharge
- Final discharge of K-1801 to H-1201
- NH₃ water to V-1203 top
- NH₃ water to V-1207

Process and Steam leak Jobs

Process Jobs

Sr. No.	JOB DESCRIPTION	TAG NO	REMARKS
COMPRESSOR			
1	MOV-1201 1st I/V D/S Drain line 1st fermanited -To be replaced	1	1 "X1500# Globe Valve Replaced
2	CO2 to H-1201 HPF drain I/V passing Near FIC-1202 Transmitter	2	1" BEL valve bonnet replaced
3	LIC-1807 U/S I/V gland leak	3	1 "X1500# Globe Valve Replaced
4	FR-1201 HP Tapping I/V to be replaced	31	1/2 "X1500# Globe Valve Replaced
GROUND FLOOR			
1	P-1204B suction flange gasket to be replaced as it was damaged	4	10" X 150# gasket replaced
2	P-1352B dis. Drain I/V wheel to be replaced for broken	5	¾" X 150# flanged valve replaced
3	P-1352 A suction I/V and its cond. Flushing I/V to be attended for passing	6,7	Valve Replaced
4	H-1201 sample poin both I/Vs are passing to be attended	8,9	BEL Valve cutting and lapping done
5	P-1102C 1st Discharge I/V gland is leaking , when it is open/close condition	10	Valve replaced
6	P-1102B 1st Dishcharge Valve to be attende as it was fermanited	11	Valve Replace with 4" X 1500 #
7	P-1102C 1st recycle valve to be serviced /reconditioned	12	Valve reconditioned
8	P-1102B recyle line close darin I/V bush broken to be attended	13	Valve replaced
9	P-1102B 1st suction I/V defectctive locking screw to be replaced & valve to be reconditioned/serviced	14	Valve reconditioned
10	P-1401 A/B both discharge I/V is hard to operate	15,16	Valve reconditioned
11	P-1305 B discharge I/V bush broken	17	Valve replaced
12	P-1302D Dis. Bypass of H-1208 I/V to be replaced for bush broken	18	Valve replaced
13	P-1302C discharge interconnection I/v is hard to operate	19	Valve replaced
14	P-1351A/B dis. Drain I/V wheel to be replaced for broken	20,21	Valve Wheel replaced
15	H-1301 B Steam IV Flange gaskets Fermanited- To be replaced	22	Valve replaced
16	P-1201A Suction line drain i/v	52	Valve replaced
17	P-1201B suction line drain i/v	53	Valve replaced
FIRST FLOOR			
1	H-1205 -gas inlet line pin hole leakages	23	Bottom Elbow replaced
2	P-1201A 2nd Dis. I/V is passing and suction	24,25	

Sr. No.	JOB DESCRIPTION	TAG NO	REMARKS
	I/V is hard to operate		
3	N/C ratio meter sample 1st I/V is not operable(its bush welded)	26	BEL Valve bonnet replaced
4	H-1204 hydro jetting to be carried out		Hydrojetting done
5	V-1409 A/B drain I/Vs gland / bonnet leaking and poor performance	32	Valve replaced
	of its cond. Flushing ball valve ,to be replaced	27	Bonnet gasket replaced
6	V-1202 bottom steam tracing trap feramanited to be replaced	33	Trap replced
7	LIC-1282 U/S drain I/V hard to operate and gland leak	34	Gland repacked
8	Pre-Evapor outlet to T-1401A I/V is hard to operate	35	Ball valve and handle provided
10	Condensate to P-1304 C/D suction line I/V gland leak & hard to operate	36,37	Valve Replaced
11	P-1305 A/B to H-1205A I/V gland leak	38,39	Gland attended
12	V-1201 sample point darin & U/S of Monoblock valve of N/C ratiometer all three valves to be replaced for hard to operate & passing		BEL valve Bonnet replaced
13	MOV -1101 D/S I/V is hard to operate	40	Valve reconditioned
14	P-1102A/B/C,C.W sprinkler individual I/Vs behind N/C ratiometer hard to oper	41,42,43	BEL valve reconditioned
15	P1210 A/B both dis. & cooler bypass I/V gland leak	44-47	Gland Attended
16	P-1201A 2nd Dis. I/V is passing and suction I/V is hard to operate	48-49	Valve attended
17	P-1201A/C dishcharge RV's gland leak		
18	F-1206 B IN I/V is not properly operable (valve flapper probl.)	50	Valve reconditioned
19	D water to bagging plant 1st I/V hard to operate		
20	V-1409B suction / discharge both main and their drain I/V 's gland leak	28-29	Valve Replaced
21	V-1409A 1st discharge drain I/V gland leak	30	Bonnet gasket replaced
22	V-1201 sample point drain both I/V s are passing to be replaced		Instrument Job
23	P-904A casing leaks ,when it was put on cond. Flushing		Instrument Job
24	N/C ratio density transducer inlet RV is passing (inside cabin)		Instrument Job
25	P-1210B suction I/V to be relocated for obstacle	54	Valve orientation changed
26	V-1301 LG Bottom IV is Not operable	55	Valve replaced
27	F-1206 A/B I/V bush broken	51	Valve replaced

Sr. No.	JOB DESCRIPTION	TAG NO	REMARKS
SECOND FLOOR			
1	H-1207 Shell drain I/V is passing	56	Valve replaced
2	DM to P-1211 root I/V bush broken (above H-1502)	58	Valve Replaced
3	PCV -1502 U/S I/V gland leak	60	Valve replaced
4	H-1421 to P-1305 I/V flange leak	59	Flange gasket replaced
5	P-1352 to H-1205A I/V gland leak	61	Valve replaced
6	P-1211 DM inlet I/V wheel is free&valve bush broken(above H-1502)	57	Valve replaced
7	H-1421 Leg I/V flange leak	62	Valve replaced
8	LIC-1203 D/S drain I/V is passing (dropwise)	63	Valve replaced
THIRD FLOOR & 3 1/2 floor			
1	V-1201 steam passivation 2nd I/V bonnet leak (bonnet lock welding done at bottom of autoclave)	64	Valve reconditioned
2			
3	V-1201 1st unloading valve bonnet leaking	65	Valve reconditioned
4	H-1205 CCS-I outlet flange gsaket to be replaced as it was damaged	67	Gasket replaced
5	Pre-Evapor.Drain I/V gland leaking (LIC-1282 U/S)	34	
6	H-1424 manhole to be opened for removal depositions/inspection	68	
7	FIC-1204 U/S I/V hard to operate & passing	77-78	Valve reconditioned
8	V-1201 top unloading I/V bonnet leak		
9	V-1201 both passivation or seal fill up I/Vs bonnet /gland leak (welded temp)	69	Valve reconditioned
10	PICV -1201 D/S 2nd I/V hard to operate	70	Valve reconditioned
11	PRC-1201 Pressure sensing root I/V bonnet leak	71	Valve reconditioned
12	NH3 to H-1202 start up by pass I/V of FRC-1201 to be replaced (wheel is welded)	76	
13	NH3 to V-1201 D/S 1st & 2nd inbetween both HPF I/Vs are not operable	72-74	Valve bonnet replaced
14	To Re-route Pre-evaporator bleeder control Valve (HICV-1481) vent direction	75	
15	V-1201 i/v gland leak	66	Gland repacked
FOURTH FLOOR			
1	LIC-1501 D/S I/V is passing & hard to operate , to be reconditioned / replaced	80	Valve reconditioned
2	4 ata sample point at V-1501 top I/V hard to operate	79	Valve replaced
FIFTH FLOOR			
1	Scrubber drain both I/V s are hard to operate, to be serviced/reconditioned	81,83	Valve bonnet replaced

Sr. No.	JOB DESCRIPTION	TAG NO	REMARKS
SIXTH FLOOR			
1	V-1207 , LIC-1235 bypass I/V gland leak and hard to operate	82	Valve replaced
2	CO2 to Scrubber drain I/V hard to operate	84	Valve reconditioned
3	PT top HPF bleeder drain I/V hard to operate		Wheel replaced
4	Prill bucket rotating assembly is very hard to operate, to be checked		Greasing done
HYDROLISER			
1	H-1303 by pass I/V hard to operate Nr. Control room staircase	91	Valve replaced
2	P-1351A/B dis. I/V bottom flange leak	90	Flange gasket replaced
3	H-1352 C.W inlet I/V hard to operate	89	Valve replaced
4	FIC-1351 U/S & D/S I/V hard to operate	87-88	Valve replaced
5	FIC-1352 D/S and by pass I/V gland leaking	86	Calve replaced
6	H-1301 bypass I/V not proper closed	22	Valve replaced
PCS/NEEM OIL			
1	P-1901 A/B is poor pumping to be attended or replaced		Pump replaced
2	Silo No : 1 base bolts are looseness and correded to be replaced	94	Bolts replaced
3	T-1901 A Recycle IV to be replaced	92-93	Globe valve replaced
4	K-1702 Duct Drain Ivs to be replaced	95-96	Valve replaced
5	To Repair FCS bed for missing bolts and damages		Bolts replaced/provided

Steam / Condensate Jobs

Sr. No.	DESCRIPTION	TAG NO	REMARK
1	Density meter condensate flushing 2nd I/V gland leak	107	Gland replaced
3	TRC-1201 U/S drain I/V is hard to operate	109	Gate valve replaced
3	Steam tracing lines corroded/leak Nr Piller Beside F-1206 at 1st flr	99	Line replaced
4	Melt pump jacket Steam header to PT top inlet I/V and its drain I/V is hard to operate at 3rd floor.	113	Gate valve replaced
5	Melt pump dis .line jacket inlet steam I/V hard to operate at 2nd flr	106	Gate valve replaced
6	FT-1502 root I/V pin hole leaking to be replaced(23 to 9 ata)	108	Gate valve replaced
7	HICV-1422A steam tracing leak (insulation to be removed)	103	Gasket replaced

Sr. No.	DESCRIPTION	TAG NO	REMARK
8	V-1200 off gas line steam tracing to be provided for choking	105	Steam tracing tube provided
9	Pre evaporator outlet to T-1401 steam tracing is not working	102	Steam trap and gate valve replaced
10	Melt returns to T-1401 steam tracing is not working	101	Steam trap replaced
11	P-1352 A/B suction line cond. Flushing I/V passing & hard to operate	7,97	Valve replaced
12	4 ata steam to rectifying column offgas both I/Vs are passing & HTO	120	Valve replaced
13	TRC-1422 D/S I/V gland leak and hard to operate (HTO)	121	Gland replaced
14	TRC-1421 U/S I/V gland leak and hard to operate	122	Gland replaced
15	4 ata to H-1301 A/B back flushing both I/V s gland & flange leak	22	Valve replaced
16	Bucket room steam trap is not working ,its line corroded and I/V to be replaced as not operable	128-130	Valve and trap replaced
17	H-1203 bottom steam tracing pin hole leak Nr. Hand railing	133	Valve and trap replaced
18	4 ata drum B/D I/V to be replaced as it was fermanited Nr C.R	127	Valve replaced
19	4 ata steam Tracing main I/V is passing Nr HICV-1210	126	Valve replaced
20	4 ata steam tracing Main I/V is passing Nr. FR-1504(piller side)	112	Valve replaced
21	P-1425 (II nd Evapor. Final Ejector) vent drain to be extended to floor	111	Line extended
22	TIC-1481 U/S darin I/V whell is free	110	Valve replaced
23	V-1202 bottom trap fermanite repaired-To be replaced	100	Valve, line and steam trap replaced
24	23 ata to Hydrolyser	98	Valve replaced
25	V-1430 Cond pot LG leak	104	Gasket replaced

OFFSITE & UTILITY PLANT

(MECHANICAL)

PREVENTIVE MAINTENANCE OF ROTARY EQUIPMENTS

COOLING TOWER AREA

Preventive Maintenance of CW Pump, P-4402

Following activities were carried out during PM

- Coupling between the pump and motor was decoupled.
- Both the journal bearings were opened, checked & found OK.
- Bearing clearances were checked & and recorded.
- During assembly correct positioning of oil splash ring in the bearing housing was ensured.
- Gland cooling water lines was opened, cleaned and boxed up
- After alignment gland was repacked with new 25 MM Sq PTFE gland packings.
- Finally new oil was filled in both bearing housings.
- Free rotation of the pump after coupling was ensured.
- Final Clearance chart is as under:

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Front end journal clearance (by lead wire)	0.20-0.30	0.22 – 0.24
2	Rear end journal bearing clearance (by lead wire)	0.2-0.30	0.25 – 0.26
3	Front end journal bearing interference	0.02-0.05	0.05
4	Rear end journal bearing interference	0.02-0.05	0.05

- Final alignment between pump to motor was done by laser alignment machine. Readings are as under

Alignment between Pump to Motor, P-4402

Position	Parallel Offset	Angular Offset	Correction Required	
			Foot-1	Foot-2
Horizontal (H)	0.01	0.01/100	0.07	0.15
Vertical (V)	-0.01	0.01/100	-0.02	-0.10
All readings are in MM.				

Preventive Maintenance of CW Pump, P-4403 Train

CW Pump P-4403

Following activities were carried out during PM

- Coupling between the pump and GB was decoupled.
- Both the journal bearings were opened, checked & found OK.
- Bearing clearances were checked & and recorded.
- During assembly correct positioning of oil splash ring in the bearing housing was ensured.
- Gland cooling water lines was opened, cleaned and boxed up
- After alignment gland was repacked with new 25 MM Sq PTFE gland packings.
- New oil was filled in both bearing housings.
- Free rotation of the pump after coupling was ensured
- Final Clearance chart is as under:

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Front end journal clearance (by lead wire)	0.20-0.30	0.22 – 0.23
2	Rear end journal bearing clearance (by lead wire)	0.20-0.30	0.25 – 0.28
3	Front end journal bearing interference	0.02-0.05	0.05
4	Rear end journal bearing interference	0.02-0.05	0.06

Turbine, Q-4403 (Triveni make)

Following activities were carried out during PM

- Coupling between the Turbine and G.B. was decoupled.
- Both sides of the turbine journal bearings were opened & cleaned.
- Bearing clearances of both sides were measured & found higher than design value. Bearing condition was found ok, therefore boxed up using same bearing.
- Axial thrust of the turbine was measured & found higher than design value. Bearing condition was found ok, therefore boxed up using same bearing.
- Complete governor removed from position and then again fixed after complete overhauling.
- Fresh oil was charged in the governor
- Oil console was properly cleaned and charged with fresh oil.
- All connected oil pipe lines were also cleaned.
- Oil cooler was opened, cleaned and boxed up.
- Oil strainer was cleaned & replaced the oil filter.
- Oil filter cleaned.
- Gland steam leak off port and lines cleaned.
- Final alignment readings were checked with laser alignment machine.
- Final clearance chart is as under:

Sr. No.	Description	Design Value (mm)	Value after PM
1	Axial thrust	0.25-0.30	0.35
2	Front end journal bearing clearance (by lead wire)	0.127-0.18	0.20 – 0.25
3	Rear end journal bearing clearance (by lead wire)	0.127-0.18	0.23 – 0.24

Gear Box (GB-4403)


During Preventive maintenance following activities were carried out:

- Gear top cover was opened. GB internals were checked and found OK.
- Bearings of gear box was opened, cleaned, checked and found ok.
- Bearing clearances of gear box were measured & found higher than design value. Bearing condition was found ok, therefore boxed up using same bearing.
- Gear wheel thrust was measured & recorded.
- Pinion wheel float was also measured.
- All oil lines checked and cleaned.
- Duplex oil filter cleaned.
- Final clearance chart is as under

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Pinion front bearing clearance	0.15 - 0.20	0.22 – 0.24
2	Pinion rear bearing clearance	0.15 – 0.20	0.21 – 0.23
3	Gear wheel front end bearing clearance	0.20 – 0.30	0.22 – 0.24
4	Gear wheel rear end bearing clearance	0.20 – 0.30	0.24 – 0.25
5	Gear wheel axial thrust	0.50 – 0.60	0.20
6	Gear backlash	0.40 – 0.45	0.42

- Final alignment between turbine to gear box was done by dial gauge. Readings are as under

Turbine to Gear Box



Dial on Gear Box

View from turbine front

All readings are in mm

Preventive Maintenance of CW Pump, P-4401/B Train

CW Pump, P-4401/B

Following activities were carried out during PM

- Coupling between the pump and GB was decoupled.
- Both the journal bearings were opened, checked & found ok.
- Bearing clearances were checked & and recorded.
- During assembly correct positioning of oil splash ring in the bearing housing was ensured.
- Gland cooling water lines was opened, cleaned and boxed up.
- After alignment gland was repacked with new 25 MM Sq PTFE gland packings.
- Finally new oil was filled in both bearing housings.
- Free rotation of the pump after coupling was ensured
- Final Clearance chart is as under

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Axial thrust		0.30
2	Front end journal clearance (by lead wire)	0.20-0.30	0.21 – 0.22
3	Rear end journal bearing clearance (by lead wire)	0.2-0.30	0.20 – 0.23
4	Front end journal bearing interference	0.02-0.05	0.05
5	Rear end journal bearing interference	0.02-0.05	0.05

Turbine, Q-4401/B (Triveni make)

Following activities were carried out during PM

- Coupling between the Turbine and GB was decoupled.
- Both sides of the turbine bearings were opened, cleaned, checked, found OK and boxed up.
- Turbine Bearing Clearances were checked & found higher than design value. Bearing condition was found ok therefore boxed up using same bearing.
- Axial thrust of the Turbine was measured and recorded.
- Complete governor removed from position and then again fixed after complete overhauling.
- Fresh oil was filled in the governor.
- Oil console was properly cleaned and charged with fresh oil.
- All connected oil pipe lines were also cleaned.
- Oil cooler was opened, cleaned and boxed up.
- Oil strainer was cleaned & replaced the oil filter.
- Oil filter cleaned.
- Gland Steam leak off port and lines cleaned.


- Final Alignment Readings were checked with laser alignment tool.
- Final Clearance chart is as under:

Sr. No.	Description	Design Value (mm)	Value after PM
1	Axial thrust	0.25-0.30	0.39
2	Front end journal bearing clearance (by lead wire)	0.127-0.18	0.25 – 0.26
3	Rear end journal bearing clearance (by lead wire)	0.127-0.18	0.24 – 0.25


During start-up of turbine, leakage was observed from the one no. of bolt of steam chest flange to turbine (shown in figure below). Nut of same bolt was removed with the help of pneumatic tool. Copper washer was provided and bolt was tightened using pneumatic tools. Steam was charged in turbine, no leakage observed from the bolt, but there was heavy leakage from the steam chest body through the pin hole. To attend the leakage from the steam chest body, assembly of governor, quick shut-up & isolation valve were removed. Both flange bolts of steam chest were loosened using pneumatic tool. Connecting steam drain line was removed from its position. Steam chest was lifted using kobelco crane and shifted to workshop. Grinding was done in chest body throughout the pin hole. DP test was done to check the extent of pinhole. Pinhole repaired by TIG welding using 70S2 filler wire. Finally boxed up the dismantled assembly. Turbine was checked by steam charging no leakage was found.



Steam leakage through the bolt



Pinhole in steam chest body



Quick shut-off valve assembly



Governor valve assembly



Isolation valve

Gear Box, GB-4401/B


During Preventive maintenance following activities were carried out:

- Gear top cover was opened. GB internals were checked and found OK.
- Bearings of gear box was opened, cleaned, checked and found ok.
- Bearing clearances of Gear Box was checked.
- Gear wheel thrust was measured.
- Pinion wheel float was also measured.
- All oil lines checked and cleaned.
- Duplex oil filter cleaned.
- Final clearance chart is as under

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Pinion front bearing clearance	0.15 - 0.20	0.13 – 0.14
2	Pinion rear bearing clearance	0.15 – 0.20	0.13 – 0.25
3	Gear wheel front end bearing clearance	0.20 – 0.30	0.24 – 0.25
4	Gear wheel rear end bearing clearance	0.20 – 0.30	0.24 – 0.25
5	Gear wheel axial thrust	0.50 – 0.60	0.20
6	Pinion axial thrust		0.82
7	Gear backlash	0.40 – 0.45	0.44

- Final alignment between turbine to gear box was done by dial gauge. Readings are as under

Turbine to Gear Box



Dial on Gear Box
View from turbine front
All readings are in mm

Preventive Maintenance of CW Pump, P-4401/A Train

CW Pump, P-4401/A

Following activities were carried out during PM

- Coupling between the pump and GB was decoupled.
- Both the journal bearings were opened, checked & found ok.
- Bearing clearances were checked & and recorded.
- During assembly correct positioning of oil splash ring in the bearing housing was ensured.
- Gland cooling water lines was opened, cleaned and boxed up
- After alignment gland was repacked with new 25 MM Sq PTFE gland packings.
- Finally new oil was filled in both bearing housings.
- Free rotation of the pump after coupling was ensured
- Final Clearance chart is as under:

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Front end journal clearance (by lead wire)	0.20-0.30	0.15 – 0.16
2	Rear end journal bearing clearance (by lead wire)	0.2-0.30	0.20 – 0.25
3	Front end journal bearing interference	0.02-0.05	0.06
4	Rear end journal bearing interference	0.02-0.05	0.06

Turbine, Q-4411 (Elliot make)

Following activities were carried out during PM

- Coupling between the Turbine and GB was decoupled.
- Turbine bearings were opened & cleaned
- Both turbine journal bearing clearances were measured higher than design value. Bearing condition was found ok therefore boxed up using same bearing.
- Axial thrust of turbine was measured and recorded.
- Governor was cleaned, checked and fresh oil is filled in it.

- Governor linkages were also made free.
- Oil console was drained; cleaned and fresh oil charged (SERVO PRESS T-32)
- Main oil pump & Auxiliary oil pump suction strainers were cleaned & boxed up.
- The surface condenser was opened. Hydro jetting was carried out & then boxed up.
- Gland steam leak off port and line cleaned.
- All oil lines cleaned and flushed.
- Oil sump cleaned.
- Oil cooler tubes cleaned by hydrojetting.
- Oil filter replaced.
- Fresh oil servo Press T-32 filled in oil sump.
- One coupling bolt of the coupling between turbine to Gear box was found damaged which was replaced from the spare coupling.
- Final Alignment readings from Turbine to Gear Box was checked with laser alignment tool and alignment report is attached below:
- Final clearance chart is as under:

Sr. No.	Description	Design Value (mm)	Value after PM
1	Axial thrust	0.25-0.30	0.41
2	Front end journal bearing clearance (by lead wire)	0.127-0.18	0.25 – 0.28
3	Rear end journal bearing clearance (by lead wire)	0.127-0.18	0.24 – 0.25

Gear Box, GB-4411


During Preventive maintenance following activities were carried out:

- Gear box top cover removed.
- All the bearing top half's were removed.
- Cleaning of journal on both gear wheel & pinion wheels.
- Cleaning of bearings is carried out.
- Cleaning of bearings covers is carried out.
- Bearing clearances are measured using lead wire.
- Bearings are assembled back and checked the bearing clearances which were given in below table.
- Top covers are assembled back.
- Main Oil Pump drive coupling checked and found ok.
- All oil lines were cleaned and flushed.
- Oil sump was cleaned.
- Oil cooler tubes were cleaning by hydrojetting.
- Duplex Oil Filters were cleaned.
- New Oil filled in oil sump
- Final clearance chart is as under:

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Pinion front bearing clearance	0.15 - 0.20	0.16 – 0.20
2	Pinion rear bearing clearance	0.15 – 0.20	0.20 – 0.21
3	Gear wheel front end bearing clearance	0.20 – 0.30	0.27 – 0.30
4	Gear wheel rear end bearing clearance	0.20 – 0.30	0.28 – 0.30
5	Gear wheel axial thrust	0.50 – 0.60	0.54
6	Pinion axial thrust		0.70
7	Gear backlash	0.40 – 0.45	0.48

- Final alignment between turbine to gear box was done by dial gauge. Readings are as under

Turbine to Gear Box



Dial on Gear Box

View from turbine front

All readings are in mm

- Final alignment pump to gear box was done by laser alignment machine. Readings are as under

Pump to Gear box				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	0.00	0.03/100	0.09	0.16
Vertical (V)	0.01	0.04/100	0.11	0.20
All readings are in mm.				

Preventive Maintenance of CW Pump, P-4401/C

Following activities were carried out during PM

- Coupling between the pump and motor was decoupled.
- Both the journal bearings were opened, checked & found OK.
- Bearing clearances were checked & and recorded.
- During assembly correct positioning of oil splash ring in the bearing housing was ensured.

- Gland cooling water lines was opened, cleaned and boxed up
- After alignment gland was repacked with new 25 MM Sq PTFE gland packings.
- Finally new oil was filled in both bearing housings.
- Free rotation of the pump after coupling was ensured.
- Final Clearance chart is as under:

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Front end journal clearance (by lead wire)	0.20-0.30	0.25
2	Rear end journal bearing clearance (by lead wire)	0.2-0.30	0.25 – 0.26
3	Front end journal bearing interference	0.02-0.05	0.05
4	Rear end journal bearing interference	0.02-0.05	0.05

- Final alignment pump to motor was done by laser alignment machine. Readings are as under

Pump to Motor				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	-0.05	0.01/100	0.00	0.11
Vertical (V)	-0.05	0.01/100	0.02	0.14
All readings are in mm				

Preventive Maintenance of CW Pump, P-4401/D

Following activities were carried out during PM

- Coupling between the pump and motor was decoupled.
- Both the journal bearings were opened, checked & found OK.
- Bearing clearances were checked & and recorded.
- During assembly correct positioning of oil splash ring in the bearing housing was ensured.
- Gland cooling water lines was opened, cleaned and boxed up
- Alignment of motor with pump was checked. Pump level was found 3.0mm down with reference to motor level (without shims). Pump was lifted by 5.00mm using 10 ton hydraulic jack. 5.00 mm SS304 plate was provided in pump foundation. Again alignment was checked and corrected.



Lifting pump using hydraulic jack

- After alignment gland was repacked with new 25 MM Sq PTFE gland packings.
- New oil was filled in both bearing housings.

- Free rotation of the pump after coupling was ensured.
- Final Clearance chart is as under:

Sr. No.	Description	Design Value (MM)	Value after PM (MM)
1	Front end journal clearance (by lead wire)	0.20-0.30	0.22 - 0.25
2	Rear end journal bearing clearance (by lead wire)	0.20-0.30	0.22 – 0.23
3	Front end journal bearing interference	0.02-0.05	0.05
4	Rear end journal bearing interference	0.02-0.05	0.05

- Final alignment pump to motor was done by laser alignment machine. Readings are as under

Pump to Motor				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	0.01	0.00/100	0.03	0.05
Vertical (V)	-0.03	0.01/100	-0.07	-0.13
All readings are in mm				

BOILER AREA

PREVENTIVE MAINTENANCE OF BFW PUMP, P-5111 (TURBINE DRIVEN)

BFW Pump (P-5111)

Following activities were carried out during PM

- All the oil pipe lines were disconnected.
- Both the end covers of the pump were removed
- Bearings were removed on both the sides
- Cleaning of journal on both sides of the pump was carried out.
- Cleaning of bearings and bearing covers was carried out
- DP test was conducted on all the journal bearings & thrust pads and found ok.
- Checked the bearing clearance and found ok.
- Rear side thrust bearing was removed
- Thrust pads were found ok.
- Both the sides bearings and bearing covers were assembled back
- Strainer was removed, cleaned and assembled back.

Sr. No.	Description	Design/ Recommended Value (MM)	Value after PM (MM)
1	Axial thrust	0.28-0.33	0.18
2	Front journal bearing clearance	0.13-0.18	0.14
3	Rear journal bearing clearance	0.13-0.18	0.13
4	Front journal bearing interference	0.02-0.05	0.05
5	Rear journal bearing interference	0.02-0.05	0.05

- Thickness of thrust pads were also checked and recorded as

Thrust Pads thickness

Sr. No	Active	Inactive
1	22.16	22.19
2	22.16	22.19
3	22.19	22.22
4	22.19	22.18
5	22.19	22.18
6	22.20	22.19

- Residual Magnetism (Gauss) at bearing journals and bearing were checked.
- All oil lines cleaned and flushed.
- Oil sump cleaned.
- Oil cooler tubes cleaning done.
- Oil Filters cleaned.
- Fresh oil filled in oil sump.

Drive turbine (Q-5111)

Following activities were carried out during PM

- Decoupled the turbine
- Instruments probes were removed
- Governor top cover and giver or are removed
- Thrust bearing & journal bearings top half's were removed.
- Cleaning of rotor shaft was carried out.
- Governing components were removed and found ok.
- Checked all bearing clearances and found ok.

Sr. No.	Description	Design/ Recommended Value (MM)	Value after PM (MM)
1	Axial thrust	-	0.27
2	Front journal bearing clearance	-	0.14
3	Rear journal bearing clearance	-	0.15
4	Front journal bearing interference	-	0.05
5	Rear journal bearing interference	-	0.05

- Final alignment pump to turbine was done by laser alignment machine. Readings are as under

Turbine to pump				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	-0.22	0.08/100	-0.90	-1.35
Vertical (V)	0.12	0.01/100	0.23	0.30
All readings are in mm				

PREVENTIVE MAINTENANCE OF BFW PUMP, P-5112 (MOTOR DRIVEN)

BFW Pump, P-5112

Following activities were carried out during PM:

- All the oil pipe lines were disconnected.
- Both the end covers of the pump were removed
- Bearings were removed on both the sides
- Cleaning of journal on both sides of the pump
- Cleaning of bearings and bearing covers was carried out
- DP test was conducted on all the journal bearings & thrust pads and found ok.
- Checked the bearing clearance and found ok.
- Rear side thrust bearing was removed
- Thrust pads were found ok
- Both the sides bearings and bearing covers were assembled back.
- Strainer was removed, cleaned and assembled back.

Sr. No.	Description	Design/ Recommended Value (MM)	Value after PM (MM)
1	Axial thrust	0.28-0.33	0.25
2	Front journal bearing clearance	0.13-0.18	0.14
3	Rear journal bearing clearance	0.13-0.18	0.15
4	Front journal bearing interference	0.02-0.05	0.05
5	Rear journal bearing interference	0.02-0.05	0.05

- Thickness of thrust pads were also checked and recorded as

Thrust Pads thickness

Sr. No	Active	Inactive
1	22.18	22.19
2	22.19	22.19
3	22.18	22.18
4	22.19	22.19
5	22.19	22.19
6	22.19	22.19

- Residual Magnetism (Gauss) at bearing journals and bearing were checked.
 - All oil lines cleaned and flushed.
 - Oil sump cleaned.
 - Oil cooler tubes cleaning done.
 - Oil Filters Cleaned.
 - Fresh Oil filled in oil sump.
- Alignment readings after preventive maintenance were checked with laser alignment tool and laser alignment report is attached below

Gear Box for BFW Pump, GB-5112

Following activities were carried out during PM

- All the oil pipe lines are disconnected and oil drained from Gear Box.
- Gear Box end covers and MOP removed.
- Gear Box top cover opened and removed.
- Condition of Gear and pinion checked and found OK.
- Bearings of Gear and pinion removed, cleaned, checked and found OK.
- DP test was conducted on all the journal bearings.
- Checked the bearing clearance and found ok.

Sr. No.	Description	Recommended	Value after PM (MM)
1	Pinion, front journal bearing clearance	0.15 – 0.20	0.17
2	Pinion, rear journal bearing clearance	0.15 – 0.20	0.16
3	Gear wheel, front journal bearing clearance	0.15 – 0.20	0.17
4	Gear wheel, rear journal bearing clearance	0.15 – 0.20	0.17
5	Pinion, front journal bearing interference	-	0.05
6	Pinion, rear journal bearing interference	-	0.05
7	Gear wheel, front journal bearing interference	-	0.05
8	Gear wheel, rear journal bearing interference	-	0.05
9	Gear backlash	-	0.20

- DP test was conducted on all the journal bearings.
- Checked the bearing clearance and found ok.
- Residual Magnetism (Gauss) checked and recorded.
- Main Oil Pump cleaned, checked and boxed up.
- All oil lines cleaned and flushed.
- Oil sump cleaned.
- Oil cooler tubes cleaning done

- Duplex Oil Filters cleaned/Replaced.
- New Oil filled in oil sump.
- Final alignment motor to gear box was done by laser alignment machine. Readings are as under

Motor to Gear Box				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	-0.01	0.03/100	0.17	0.54
Vertical (V)	0.05	0.00/100	0.07	0.12
All readings are in mm				

PREVENTIVE MAINTENANCE OF FD FAN (K-5113) / DRIVE TURBINE (Q-5113)

Following activities were carried out during PM :

- Decoupled the turbine
- Decoupled Fan from Turbine
- Removed oil lines & Governor
- Gearbox cover was opened and checked the condition of Gears. The same was cleaned; DP test was carried out and assembled back.
- Backlash between gear wheel to pinion was checked.
- Cleaned the Radial bearings.
- Dimensional Inspection, DP test & Gauss measurement of Journal bearings were done. Results were found satisfactory.
- Main oil console was cleaned and recharged with new oil (SERVO PRIME 68).
- MOP was removed from its position & cleaned. Coupling Bush of MOP was replaced.
- Oil cooler was opened and cleaned by Hydro jetting.
- Cleaned Duplex oil filter & replaced O-ring.
- The air dampers were attended for proper working. The Fan inlet air mesh screen was changed.
- Sentinel valve was passing during operating condition. The same was replaced with new one.
- Between turbine and fan coupling rubber pads were replaced
- The clutch oil (Servo Trans fluid-A) was replaced.
- The clearances were checked & following are the readings



Sentinel valve

- Final alignment motor to clutch was done by laser alignment machine. Readings are as under

Motor to Clutch				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	-0.36	0.03/100	-0.23	-0.08
Vertical (V)	1.68	0.18/100	2.36	3.18
All readings are in mm				

- Final alignment fan to clutch was done by laser alignment machine. Readings are as under

Fan to clutch				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	-0.09	0.02/100	-0.07	0.03
Vertical (V)	-0.20	0.06/100	-0.14	0.08
All readings are in mm				

- Final alignment gear box to clutch was done by laser alignment machine. Readings are as under

Gear box to clutch				
Position	Parallel offset	Angular offset	Correction required	
			Foot-1	Foot-2
Horizontal (H)	0.09	0.05/100	0.19	0.39
Vertical (V)	0.13	0.01/100	0.16	0.21
All readings are in mm				

BHEL BOILER JOBS

BHEL BOILER INSPECTION/HYDROTEST

Boiler was inspected by Boiler Inspector in open condition on 05/04/2015 & Hydro test was carried out at 89.0 kg/cm² pressure on 09.04.2015 and witnessed by Boiler Inspector

TESTING OF BOILER RV'S

Critical boiler RV's were removed, overhauled and then tested on test bench. RV testing readings are as under:

Description		Set pressure (Kg/cm ² g)	Reset pressure (Kg/cm ² g)	Seat tightness test pressure (Kg/cm ² g)	Remarks
Boiler Drum Front RV Tag no. RV-F-5111-2 Make : Crosby Model : HCL-56-IBR-IFN-SPL Size : 2" x J x 4"	On Valve testing Machine	69.00	-----	62.10	
Boiler Drum Rear RV Tag no. RV-F-5111-1 Make : Crosby Model : HCL-56-IBR-IFN-SPL Size : 2.5" x K x 6"	On Valve testing Machine	72.00	-----	64.80	
Boiler Super Heater RV Tag no. RV-16126 Size : 1.5" X 3" Model: 1717 WD	On Valve testing Machine	64.60	-----	58.14	Seat insert & nozzle ring locking screw replaced
	Online Floating	64.70	62.20	-----	
Tag no. RV-Q-5111 Size : 4" x 6" Model : SL-131	On Valve testing Machine	5.00	-----	4.50	
Tag no. RV-Q-5111 Size : 3" x 4" Model : 3SL-131	On Valve testing Machine	4.50	-----	4.00	

STEAM DRUM

One no. of U-clamp of feed water inlet header (4") was found in damaged condition. The same was repaired shown in below figure. Two nos. of clamps of phosphate dozing line (1") were also found in damaged. New clamps were welded with pipe line and tightened it with fasteners.



Repaired U-Clamp

DEAERATOR

Bottom two tray segments were found displaced from its position. All tray segments were removed one by one from the top by cutting tack welding. From bottom, each tray segment was placed its position one by one. Tack welding of fasteners of each tray was also done for strengthening.



Tray position inside dearator

APH

All manway covers of APH were opened. Some portion of Flue gas outlet chamber was found rusted and corroded. Rusting was cleaned by power tools and 2 coat of epoxy coating was applied after primer. Remaining portion of duct of flue gas and air was found satisfactory. Plates were cleaned by water nozzle spray.

Light leak detection was carried out to check welding. At two portions, pinhole leak was detected. The same was repaired by weld filling. After getting clearance from production department all manway covers were box-up



Corrosion and rusting area in flue gas outlet chamber

FIXING OF CAP ON TOP PILOT BURNER

During previous shutdown-2014, a fabricated cap with clamp type arrangement was provided on bottom burner tip to prevent the direct impinging of air. After satisfactory performance of this modification, similar cap with clamp type arrangement was fabricated and provided on top burner tip.



Top burner from outside



Top burner - After removal from its position



Cap with clamping arrangement



Cap fixed on top burner at its position

OTHER BOILER JOBS

- All inspection window glasses were checked & cleaned. Broken window glasses were replaced. Gaskets of all window glasses were also replaced.
- SSH top coil (no. 36) Old Ceramic fiber blanket got replaced by new one
- Insulation replaced at several place based on thermography survey report.
- PSH & SSH header drain 2nd isolation valve (Globe valve, 1" x 1500#, IBR) was passing. The same was replaced with new one.
- Steam drum rear side Hydrastate 1st steam side (Fermanited) valve (Globe valve , 1" x 2500#, IBR) got replaced with new one.
- Opening / box up of steam / mud drum (both side)
- Opening / box up of manway cover of boiler furnace wall.

COOLING TOWER AREA JOBS

Welding of SS304 Patch Plate on Jump over line of CW supply header to ammonia CW circuit

SS 304 patch plate was welded on u/p & d/s line of NRV of CW supply header to ammonia CW circuit

Header size: 36" NB Sch. STD, MOC: CS

Patch Plate: SS 304, 3 mm Thick X 1500 MM Approx.

This job involves:

- Excavation work in u/s and d/s of NRV was done by civil section
- Removing the wrapping coating with gas burning upto approx 1 mtr depth.
- Cutting of SS-304 patch plate in required quantity and sizes to suit the profile of the pipe.
- Welding of patch plate upto 1 mtr depth on CW headers.
- Inspection including final weld DP.
- Wrapping coating of exposed CS pipe surface of CW header.
- Spark testing of wrapping coating.






SS 304 Patch plate

INSTALLATION OF SINTEX MAKE PARTITION PANEL IN AMMONIA COOLING TOWER


During previous shutdown-2014, old wooden damaged partition panels of old ammonia cooling tower cells A1-A2, A2-A3 and A3-A4 were replaced by new sintex make PVC section partition panels. After finding satisfactory performance of new PVC partition panel, during shutdown 2015, existing wooden partition panels of remaining cooling tower cells A4-A5 & A5-A6 were also replaced with the same.

In addition of above job, all wooden doors of old ammonia cooling tower, urea cooling tower and new cooling tower were replaced with PVC panels.

Job was awarded to M/s Abhay Fabricators, Kalol against the WO 6535/201004150939 & dated 02-DEC-14.



New PVC partition panel installation-1



New PVC partition panel installation-2



New PVC partition panel installation-3



New PVC door



Old wooden door

REPAIRING OF COOLING TOWER

- Committee comprising members from Mech Maint, Inspection, Civil and Utility Production inspected all the cooling towers and recommended the necessary repairs.
- Based on the committee recommendations, Structural members of the cooling towers were checked and replaced the defective members.
- Corroded fasteners were replaced with new SS304 bolts with SS 304 Square washers.
- Leakages attended from end wall & louvers using mastic (STP make Tarplastic Sealant).
- Repaired stair case
- Replaced on cracked Base casting (Towards admin side) of Old Urea Cooling Tower.
- Fill area of all cooling towers were also inspected for any damage on sampling bases by providing outside scaffolding and removing louver sheet to enter in the fill area. All fill area components and structural members found in good condition, however some PVC V-bars are found dislocated and the same was rectified



Timber block missing



Repairing of water distribution of box-1



Leakage from end wall



Damaged deck ply



Repairing of water distribution of box-2



Repairing of water distribution of box-3

- Above Job was carried out through M/s Paharpur cooling tower against the WO no. 201004151204 dated 09/01/2015 for the repairing of cooling towers

During preventive maintenance of CT fan K-4401-7, both side drift eliminator of CT was found damaged in condition. The same was repaired by M/s Paharpur cooling tower, Vadodara.



Damaged drift Elinimator

OVERHAULING OF CHECK VALVE FOR COOLING WATER PUMP, P-4411 E

During running condition, check valve (Size: 28" x 150#) of cooling water pump, P-4411E was found passing. Job was awarded to M/s Flotec Technosmart (India) Private Limited, Surat against the contract no. 6535 /201004151202, dated 28/01/2015.

Check valve was dismantled. Corrosion & pitting observed along the disc seat portion, which seems unable to refurbishing. Body seat of valve is having heavy corrosion & pitting. Finally check valve was boxed up after using new gland packing and it is decided to procure new valve to replace existing one during next shutdown-2016.



Check valve parts after dismantling

REPLACEMENT OF CS COVER OF COOLING WATER SUMP INTO SS 304

CS covers (6 nos.) of cooling water sump basin were found corroded condition. All new SS304 covers were fabricated and provided on its position.



SS304 Cover

REFURBISHING OF JASH MAKE SLUICE GATE (1/2/3/4/5/6) OF COOLING WATER PUMP SUMP

Following activities were carried out.

- Stem : cleaning & greasing
- Shutler Seat / Frame seat facing : cleaning & greasing
- Gate no.1: Gear box was opened. Bearing was found in satisfactory condition. Small wear marks observed in gear teeth. Gear box operation was satisfactory.
- Gate no.3: Bottom wedge block was not found.
- Gate no. 4: Bottom wedge block was found in damaged condition.
- Full operation (open / close) of all gate was checked & found satisfactory.



Jash make Sluice Gate

The above job was carried out under the supervision of OEM's Engineer (M/s Jash Engg Ltd., Indore) against the WO no. 6535/ 201004151080 dated 26/12/2014.

OTHER COOLING TOWER JOBS:

- Raw water to cooling tower line (8" x 20 sch, CS) was punctured at two points. Clamp with gland packing was provided on the same to reduce leakage during operating condition. Total 80 meter long pipe covering both punctured points, was removed from its position by gas cutting. Prefabrication was done for replacement of existing pipe before shutdown. Only three field weld joints were done after installation of new pipe with the help of Kobelco crane (100 ton).
- Drain valve (Gate valve, 12" x 150#) of ammonia cooling tower sump basin was passing. The same was replaced with one.
- Narmada header to new IG header , a new interconnection line with valve (gate valve, 4" x 150#) was provided
- I/V (Gate valve, 4" x 150#) of interconnection line from raw water header to cooling tower, was passing. The same was replaced with new one.
- Seal ejector line of Q-4411 (Elliot turbine) was creating hurdle near platform. As the safety of personnel, the same was rerouted.
- Weld joint pitting of 52" NB cooling water interconnection line of P-4405 to P-4401 C/D, were repaired by using Stanvac make steel putty "Z370 steel weld".
- In situ refurbishment of following gate valve was carried out due to passing
 - Gate valve, 900mm NB x 150#, at Pump P-4403 common discharge line (towards Urea plant)
 - Gate valve, 700mm NB x 150#, at Pump P-4403 common discharge line (towards ammonia plant)

The above job was awarded to M/s Flotec Technosmart (India) Private Limited, Surat against the contract no. 6535 /201004151202, dated 28/01/2015.

- Cooling tower to distribution valve overhauling job.

DM PLANT

RERUBBER LINING OF STRIPPED PROCESS CONDENSATE (SPC) UNIT

Rerubber lining of SPC unit was done based on the inspection report. Job was awarded to M/s Conveyor Rubber Industries, Ahmedabad against the rate contract 6535/ 201004150938 dated 24/11/2014.

Following activities were carried out to execute the job

- Manhole cover opening / connected flange loosened / Resin unloading
- Lifting of vessel from its position and placing at rollers
- Removal of old rubber lining / scrapping
- Cleaning by shot blasting
- Visual inspection of bare surface & repair , if any
- Primer application
- New rubber lining
- Steaming for curing
- Inspection (Visual / Spark test / Hardness test) & repair , if any
- Re-installation of vessel on its position.
- box - up / Resin loading

To check the leakage, resin was filled up to bottom manhole and the water was filled from the top manhole. Resin was found on drain due to leakage between slit nozzle and perforated hole. Again resin was removed, All slit nozzle was removed from the its position. New Teflon threaded bushes were provided in the place of loosed PVC threaded bush. Araldite compound was applied in gap between all loosed threaded bushes and respected perforated holes. Again leakage was tested similar way. No resin was found in drain

Finally job handed over to production department.



Before rerubber lining



New rubber lining on perforated plate



Steam curing after new rubber lining

Other DM Plant Jobs:

- All existing FRP open channel with drain pit were replaced by fabricated SS304 open channel and drain pit. Job was executed by workshop department. To prevent the chloride corrosion, in three nos. of drain pit a special corrosion resistance coating (Valancy 314) were applied on trial basis.



Corrosion Resistance Coating (Valancy 314)

- I/V (Gate valve, 1-1/2" x 800#) was provided on main instrument header to DM control room.

I G Plant

- In new IG cracker, fire observed under the retort no.1 flange joint (from K-5301 towards offsite maint office side). The same was attended by replacing gasket with new one after IG purging. Again fire observed on same joint & DP test was carried out. A crack was observed in weld joint of crack gas inlet line to header (to combustion chamber). The same was repaired after grinding and welding.



Cracked area

- DM water to polisher unit (Ammonia plant) lifted by 6” to facilitate the flooring work by civil section.

Narmada Plant

In Clariforculator sump, 8 nos. of bottom rubber scrapper were found in damaged condition. The same were replaced with one. Bottom bush of paddle-B was also found corroded condition. New bush was provided



Bottom rubber scrapper



Bottom bush

B & MH PLANT
(MECHANICAL)

PLANT TRANSFER CONVEYOR - M-2110

Following jobs were carried out.

- Repairing of damaged vulcanized joint of conveyor belt.
- Head pulley, Tail Pulley, Bend pulley, Gravity pulley and Snub pulley were inspected and greasing done.
- Provided new rubber lagging on Gravity pulley, Tail pulley and Snub pulley.
- Two Nos of new Tega make Tru- Trac- Trough rollers were installed for arresting sway of conveyor belt.
- Preventive maintenance of Gear Box carried out & coupling done after proper alignment with new rubber bushes.
- Gear box oil was replaced.(Servo system-460)
- Brush pulley was serviced.
- All damaged and noisy carrying rollers, Return rollers, Self alignment carrying roller frames, Self alignment return roller frames and Tracking rollers were replaced.
- New Kaveri make skirt rubber were provided.

TWO WAY FEED HOPPER CHUTE - M 2111

- Servicing of two way discharge flap valve.
- Greasing of bearings

FRESH UREA SHUTTLE CONVEYOR - M-2112

Following jobs was carried out.

- Modified inlet chute of M-2112 conveyor and provided new kaveri make skirt rubbers.
- Rubber lagging done in both bend pulley and snub pulley.
- Preventive maintenance of Gear Box carried out & Coupling done after proper alignment with new rubber bushes.
- Gear box oil was replaced.(Servo system-460)
- All noisy and damaged carrier, guide and return rollers replaced with new rollers.
- Greasing done in all bearings of head pulley, tail pulley, snub pulley and gravity pulley.
- Tripper Gear box oil replaced.
- New Three Nos Tega make tru Track Trough rollers provided on carrying side for arresting sway of conveyor belt

RECLAIM CONVEYOR - M-2117

Following jobs were carried out

- Preventive maintenance Gear Box and Coupling done after proper alignment with new rubber bushes.
- Gear box oil was replaced.(Servo Mesh SP-320)
- All noisy and damaged carrying, guide and return rollers were replaced with new rollers.
- Greasing done in all bearings of head pulley, tail pulley, snub pulley and gravity pulley.
- Rubber lagging done in snub pulley & both bend pulley.

BAGGING BUILDING FEED CONVEYOR - M-2121

Following jobs were carried out

- Replaced the complete length of conveyor belt with new oil and Heat resistance conveyor belt NN630/800 mm width (M/s Sempertrans Nirlon make)
- Preventive maintenance of Gear Box carried out and Coupling done after proper alignment with new rubber bushes.
- Complete skirt board sealing system skirt blocks were replaced with new one.
- Replaced all damaged and noisy Carrying, Return, Impact and guide rollers with new rollers.
- Complete greasing of all pedestal bearings done.
- New rubber lagging provided on Bend pulley, Tail pulley, Snub pulley and Gravity pulley.
- Rubber lagging done in snub pulley pulley.
- New bend pulley (2 Nos) provided with new bearings.

BAGGING BUILDING HOPPER CONVEYOR - M-2122

Following jobs were carried out

- Replaced all damaged and noisy Carrying, return and guide rollers with new rollers.
- New Kaveri make skirt rubber were provided.
- Complete greasing in all pedestal bearings done.
- Take up studs were serviced.
- Replaced complete Gearbox with another overhauled Gearbox and Coupling done after proper alignment with new rubber bushes.
- Rubber lagging done in tail pulley.

BAGGING BUILDING HOPPER CONVEYOR - M-2122 A1

Following jobs were carried out

- Preventive maintenance of Gear Box carried out and Coupling done after proper alignment with new rubber bushes.
- Replaced all damaged and noisy Carrying, return and guide rollers with new rollers
- Rubber lagging done in Snub pulley.
- Take up studs were serviced.

BAGGING BUILDING HOPPER CONVEYOR - M-2122 A2

Following jobs were carried out

- Preventive maintenance of Gear Box carried out and Coupling done after proper alignment with new rubber bushes.
- Replaced all damaged and noisy Carrying, return and guide rollers with new rollers
- Take up studs were Serviced.

FLAT CONVEYOR BELT - M-2142

Following jobs were carried out

- Preventive maintenance of Gear Box carried out and Coupling done after proper alignment with new rubber bushes.
- Replaced all damaged and noisy Carrying and return rollers with reconditioned rollers.

DUST & UREA LUMPS BELT CONVEYOR - M-2137

Following jobs were carried out

- Reduce the length of conveyor as per requirement of Technical department for commissioning of new vibrating screens.
- Complete greasing of all bearings done.
- Replaced Tail end pedestal bearing 75 mm dia.
- Coupling done after proper alignment with new rubber bushes.

BAGGING MACHINE - M-2101/1, 2, 3, 4, 7, 8, 9A, 10A, 10B

Following preventive maintenance jobs were carried out

- Overhauling of gate assembly.
- Overhauling of bucket assembly.
- Overhauling of sack grip assembly.
- Servicing of all cylinders.
- Alignment of stabilizer plate.
- Calibration of packer scales.

SLAT CONVEYOR - M-2124 /1, 2, 3, 4, 7, 8, 9, 10A, 10B

- All gearbox oil was replaced.(Servo system-460)

STITCHING MACHINE - M-2102 /1, 2, 3, 4, 7, 8, 9, 10A, 10B

- All stitching machines and spare machines were overhauled with M/s gabber engg.

AIR BLOWER - K-2161

- All lines were removed, cleaned and boxed up.

AIR BLOWER - K-2704

- All lines were removed, cleaned and boxed up.

CYCLONE SEPARATOR - V-2704

- Separator was opened, cleaned and boxed up.

UREA SOLUTION TANK - T-2704

- Tank was opened, cleaned and boxed up.

VIBRATING SCREEN - M-2136/A, B, C, D

- All screens were removed, cleaned and boxed up.
- Replaced screen of M-2136 A , as it was found in damaged condition.

RECLAIM MACHINE - M-2116 A

Following jobs were done

- Preventive maintenance of Scrapper and Bucket elevator mechanism.
- Checking of complete slewing ring mechanism.
- Checking of upper and lower kingpost.
- Inspection of Tie Rod, Tie Rope and Pivot assembly.
- Checking of complete central Greasing mechanism.
- Complete Greasing of reclaim machine
- Replacement of lubricating oil of all Gearboxes (Servo mesh SP-320)
- Checking of Thruster and break shoes

INSPECTION

AMMONIA PLANT

(INSPECTION)

The following major inspection activities were performed in Ammonia Plant.

- Inspection of primary reformer, catalyst tubes and risers with various NDT Techniques including Automatic Reformer Tube Inspection System (**ARTIS**) by M/s TCR ADVANCED ENGINEERING LTD. Details are given at **Annexure-1 to 5.**
- Visual inspection of equipment.
- Ultrasonic flaw detection on selected weld joints and parent metal of elbows of New Converter(S-50) loop and other critical pipelines was carried out .Details are given at **Annexure- 6.**
- Thickness measurement of various equipment and HT/LT Convection coils of primary reformer were carried out .Details are given at **Annexure-7.**
- Thickness measurement of various pipelines was carried out. Details are given at **Annexure-8.**
- Measurement of residual magnetism at various parts of rotating equipment and de - magnetization of the same wherever required. Details are given at **Annexure-9.**
- In-situ Metallography of selected equipment and pipelines were carried out. Detailed summary of observations and microstructure analysis is given at **Annexure-10.**
- Inspection of newly fabricated pipelines and fabrication jobs carried out departmentally by Maintenance and Technical department.
- NDT's viz. DP, RT and UFD was carried out in the converter loop to assess the condition of weld joints & Elbow parent metal for any deterioration. The details are attached at **Annexure-11.**
- Qualification tests of welders employed by contractors.
- The detailed observations and recommendations for corrective actions required on individual equipment are given below. All the observations were recorded during inspection and were handed over to concerned Maintenance and Operation group for necessary corrective action.

PRIMARY REFORMER 101-B

RADIANT ZONE

VISUAL INSPECTION

Visual inspection of the entire furnace radiant zone, including harp assemblies, refractory and insulation, burner-blocks, etc. was carried out. The detailed report on observations made is enclosed herewith at **Annexure-1.**

OTHER NDT ACTIVITIES

Automatic Ultrasonic Scanning of 194 Catalyst tubes out of 336 and 8 Riser tubes were carried out during ARTIS by TCR. All 194 tubes & All 8 Risers are placed in grade II. Details are attached at **Annexure-2**.

Following inspection activities includes in the ARTIS.

- Visual inspection of catalyst tubes for general assessment and bowing.

In general all the tubes are found with grayish brown coloration with some of them showing reddish coloration. All the tubes appear straight and free from any significant abnormalities.

Bowing:

No apparent bowing is observed on any of tubes visually; the value as measured by ARTIS system was found less than 5mm for most of the tubes, however 03 tubes had recorded it as 7.6mm, 28.3 mm and 31.5 mm.

Baldness:

Surface of most of the tubes appear to be rough. However few tubes showing smoothening tendency (baldness) as listed as under:

- Row-1 tube no. 19, 26, 28
- Row-2 tube no. 12, 15, 18, 21, 22
- Row-3 tube no. 15, 27, 42
- Row-5 tube no. 1, 31
- Row-6 tube no. 23
- Row-7 tube no. 36
- Row-8 tube no. 5, 6, 21, 36

- Dye penetration testing of bottom 1st weld joints of 04 catalyst tubes & 16 nos. weldolet to catalyst tube weld joints.

Tube to weldolet joint:

- Row-1 tube no. 15, 27
- Row-2 tube no. 16, 28
- Row-3 tube no. 15, 27
- Row-4 tube no. 16, 28
- Row-5 tube no. 15, 27
- Row-6 tube no. 16, 28
- Row-7 tube no. 15, 27
- Row-8 tube no. 16, 28

Tube to tube 1st weld joint from bottom:

- Row-1 tube no. 21
- Row-1 tube no. 22
- Row-1 tube no. 22
- Row-1 tube no. 21

No significant discontinuity observed with respect to area tested in DPT.

- OD measurement by manual method at about 2 meter height from bottom.

Manual diameter measurement was carried out on tubes at 2 meter height from bottom. Minimum and maximum diameter observed in 114 mm and 116 mm, respectively against the design value of 113.6-115.2 mm. Maximum creep was found to be 1.39% considering average diameter of 114.4 mm.

- Magnetic permeability measurements at about 2 meter height from bottom.

Permeability measurement has been carried out on catalyst tubes and riser tubes at 2 meter height from bottom. Minimum and maximum values observed are 1.18 – 1.57 u for catalyst tubes and 1.05 – 1.49 u for riser tubes respectively.

- Microstructural examination by replication Metallography on 16 nos. catalyst tubes and 4 nos. of riser tubes was carried out along with hardness measurements on all Metallography spots.

Observations:

No indication of micro cracks and creep fissures is observed anywhere. Microstructural condition was found satisfactory.

Hardness was found in the range of 151-181 BHN and 159-175 BHN for catalyst tube and riser tube respectively.

- Ultrasonic attenuation and OD measurement carried out by ARTIS and detailed report is attached in annexure 2 and grades marked as per following guidelines:

Grade class: Attenuation (dB)	Condition of tube
New Material Grade I : 30 – 55	New tubes (Variation depends on chemical composition, casting process leading to difference in ration of equiaxed to dendritic structures)
Grade II : 45 – 62	Tubes put in operation, without any significant creep voids, but likely carbide coarsening.
Grade III : 62 – 70	Probability of tube affected with creep void and requires to be correlated with microstructural examination and OD measurements. Tube may be subjected to radiographic examination for evaluation on creep.
Grade IV : >70	Indication of aligned creep cavities. To be correlated with microstructural examination and increase in OD. Tube may be removed for further destructive tests for remnant life assessment (RLA) study.

- Ultrasonic thickness measurements at one location on tubes at about 2 meter height from bottom.

Thickness of the catalyst tubes and risers tubes was measured by ultrasonic A-scans technique by specially fabricated shoe. Minimum and maximum thickness observed was 12.2 mm and 13.6 mm respectively for catalyst tubes against minimum required thickness of 11.0 mm.

DP test of all riser tube to weldolet weld-joints was carried out. NO service defects were revealed

DP test of random catalyst tube to weldolet weld-joints was carried out. NO service defects were revealed.

Creep measurement of all the catalyst tubes was carried out using GO-NOGO Gauge at tunnel slab level. Creep was found in the range of 0 - 0.17 % for 335 nos. of tubes and between 0.17 to 0.70 % in 01 nos. of tubes. Creep measurement of the riser tubes at tunnel slab level was also carried out using digital micrometer. Creep was found of Riser tube in the range 0.33 – 1.10 % in 06 nos. tubes & 1.10 – 1.44 %. In 02 nos. of Riser tube. The report is attached at **Annexure 3.**

In-situ Metallography on Catalyst tube parent metal, Riser tube parent metal, Catalyst tube to weldolet weld & Riser tube to weldolet weld joint. The detailed report is attached in **Annexure-10.**

Radiography of all 08 nos. weldolet to riser weld joints was carried out. No significant defect was observed.

CONVECTION ZONE

Visual inspection of HT convection zone from top and bottom manhole and Auxiliary boiler furnace was carried out. The observations made are as under:



H.T. CONVECTION SECTION

From Top Manhole:

- Air pre heater coil was found sagged up to 300 mm downward direction at south side.



- South side all support found cracked/damaged. (1st support from of East side)



- South side 01no. Support found cracked/damaged. (2nd support from of East side)



- HT and LT super heater coils were found in satisfactory condition.
- Supports of LT/HT steam super heater coils were found in satisfactory Condition.
- 6" to 8" gap found between insulation protection sheets at East side just above partition wall.
- HT steam super heater top coil tube fins found damaged in approx. 100 mm length for 02 nos. of tube at East end.
- 02 nos. of thermo well near damper of PRC-23 found bent downward.
- Insulation covering sheet found distorted and bounding with wire.

From Bottom Manhole

- Hard scaling was observed on all the tubes of Mixed Feed Coil.
- Bottom most part of Insulation covering plate was found burnt off at most of the locations. This was observed in previous inspection also.
- Refractory at the ceiling found superficially cracked at few locations.
- Peeling off of top layer of casting was observed on first two rows of east side anchor supports of mixed feed coils. Refer attached photographs.





- Tunnel thermo well pipes were found slightly bent, scaled and eroded. Same was observed during previous inspection.
- Bottom floor refractory found loosens at some places and flooring found sagged at some location. Same was observed during previous inspection.
- Insulation of East, West and South wall was found satisfactory.
- Mixed Feed coil found sagged in South-West segment compared to North-East Segment.
- Some Brick walls were found bent and some of the top layer of bricks of brick walls were found loose.

VESSELS & OTHER EQUIPMENT

PRIMARY WASTE HEAT BOILER (101-CA) SHELL

Visual inspection of Primary Waste Heat Boiler shell liner was carried out after removal of its tube bundle. Following observations were made:

1st Liner Piece from top

- 1st course was found satisfactory except metal dusting was observed at scattered locations which have resulted in pitting of 1-1.5 mm depth at few locations. This was also observed during previous inspection.
- Superficial abrasion marks were observed on liner segments.
- Gas outlet nozzle liner was found in satisfactory condition, however a fine crack of approx. 400 mm was observed at its weld junction with shell liner. Same was observed during previous inspection also. Refractory behind it was found intact as seen through gap.
- 2nd course was found to have metal dusting attack resulted in approx. 1-3 mm deep pitting in approx. 40 % surface area of liner segment and erosion of its longitudinal weld seam by approx. 2-3 mm in its complete length below the liner surface. Its circumferential weld was found slightly eroded in approx. 80% of its length. This was also observed during previous inspection also.
- Uniform gap was observed between the 1st & 2nd pieces of the liners.

2nd Liner Piece from top

- Surface Abrasion marks were observed approx in 150mm circumferential length in South-East side due to rubbing of the tube bundle.

- Minor metal dusting attack observed on shell liner resulted in pitting of approx. 1.0 mm depth at few locations in approx. 5 % of the liner surface area. This was also observed during previous inspection.
- Inward bulging of approx. 300 mm was observed at South-West and South-East side.
- Long seam weld was found slightly eroded in approx. 250 mm length.
- A gap of approx. 10mm to 60mm observed east side between loose liner and 3rd shell liner piece in entire circumference, causing exposure of refractory. However, condition of the refractory exposed in between seems to-be intact and observed to same as during previous inspection.

3rd Liner Piece from top

- Uneven gap observed on expansion joint. East half has 2-4 mm gap between liner segments where as 15-20 mm gap was observed in remaining half. The same was also observed in previous inspection also.
- Inward bulging approx 3"X3" observed at West side of the shell.

4th Liner Piece from top

- Circumferential weld joint just at the level of the gas distributor bulged and cracked in approx. 60% of its length.

Gas Distributor

- Gas distributor was found deformed inwards from both the sides.
- Gas distributor header found chocked by alumina bolls at few perforated holes.

115-C, METHANATOR EFFLUENT COOLER

- Helium leak detection of tube sheet area was carried out by M/s. Gulachi Engg to find out the leak.
- Details of Helium Leak detector used by M/s Gulachi Engineers
Make: Adixen ASM 310, Germany.
Sr. No. HLD 1302640



- Complete tubesheet weld joints were masked by Aluminum Tape.



Tube sheet masking by Aluminum tape.

- Initially shell side was pressurized by air at 3.0 kg/cm² and then helium was injected till the pressure reached at 5.0 kg/cm².
- Leak detection was carried out by puncturing the Masking tape and checked by Sniffer to locate the point of leakage.



Leak detection in progress.

- Total 88 nos. tube sheet welding were found defective in helium leak testing. The same were repaired by grinding and welding.

103-D, SECONDARY REFORMER

TOP AIR AND GAS ENTRY:

Visual inspection was carried out from outside and observations are as under:

- Appx 1" Gap was observed between shift liners of top shell to transfer line in complete circumference.
- Crack observed on the weld joint of patch liner to transfer line liner in approx. 4" length.



- Bulging of shift liner of top shell in appx 1 ' height was observed at appx 1 mt from bottom .

BOTTOM DOME :

- The refractory around the 101-CA/CB gas inlet nozzles (approx half of the top circumference) was found eroded and loosened.




101 CA Nozzle View




101 CB Nozzle View

- Gap was observed between the 101-CA/CB gas inlet nozzle liner and the shell refractory joint. Gap of approx 2" was observed towards the 101-CB nozzle.

The same was observed in previous inspection also.



- The liners inside the 101-CB gas inlet nozzle were slightly buckled /distorted. Condition of the thermo-wells was satisfactory. The same was observed in previous inspection also.
- Longitudinal weld of one of the liner pieces of 101 CA gas inlet nozzle was found opened hence exposing the refractory as shown in the attached fig.



AIR MIXTURE of 103-D

- Scattered cracks were observed at refractory around nozzle holes.
- Straightening vanes and its support ring found slightly distorted.
- Refractory found fallen around the nozzle.



- Some Partition plate of nozzle holes found partially burnt and some found with crack at its centre & end welds.



- Insulation cover weld with top cover liner found eroded.



- Circumferential crack was observed at the top cover liner welding.



- 02 nos. cracks of approx 15mm length were observed on conical surface as shown below.



101- EA ,CO₂ Absorber


(Manhole no. counting from top of the vessel)

From Manhole- 1

- Demister pad was found intact in its position.
- Bubble caps as well as all the fittings were found satisfactory.
- Brownish black coloration was observed in shell where as dish end was found grey in colour with yellow patches over it.
- Black deposits were found in dished end area.
- Weld joints were found satisfactory.
- aMDEA liquid was lying on the bubble cap tray.

From Manhole- 3

- 01 no. Rasching ring holding clamp was found loose at south side



- Brownish grey coloration was observed on the shell as well as on all the gas risers.
- Sample collectors were found intact in its position.
- Condition of the gas risers was found satisfactory.

From Manhole- 4

- Excessive gap as compared to others was observed in several rasching ring holder.(between two half of holder)
- 01 no. rasching ring holding clamp was found loose at west side.
- Condition of liquid distributor was found satisfactory.
- Brownish grey coloration was observed on the shell as well as on all the fittings.
- Corrosion cavities and holes were observed on South most liquid distributor collector plate, located just below the liquid distributor. (Visible just from M/H)



- Gas riser holding plate was found eroded/damaged from top edge at west side.



- Sample collector was found twisted.



- Debris was found lying on the gas riser holding plate.



From Manhole- 5

- Excessive gap as compared to others was observed in several rasching ring holder. (Between two half of holder).
- Grey coloration was observed on the shell.
- Sample collectors were found intact in its position.

From Manhole- 6 (Inspected from outside)

- Condition of gas distributor was found satisfactory.
- Grey coloration was observed on the shell.

102-EB, CO₂ STRIPPER

FROM TOP MANHOLE

- Demister pads were found slightly shifted in middle portion.
- Demister pad supporting strips and rods were found satisfactory.
- All the bolts of liquid inlet nozzle flange were found in position & intact.
- West side distributor header was found rubbing with the shell plate in S-W direction causing dent in the shell plate. Same was also observed in previous inspections.
- U-Clamps of East-North and West-South side distribution header were found loose.
- West-North side distributor header support found cracked.
- West-South side distributor header found rubbing with U-clamp support causing dent in cap of header.
- East-South side distributor header support plate found cracked/detached from shell in approx length of 8".
- East-North side distributor header found rubbing with U-clamp support plate causing dent/slot of 100 mmX20 mm area in cap of header. At same location U-clamp support & header support plate found cracked.

PRIMARY WASTE HEAT BOILER (101-CA) SHELL

Visual inspection of Primary Waste Heat Boiler shell liner was carried out after removal of its tube bundle. Following observations were made:

1st Liner Piece from top

- 1st course was found satisfactory except metal dusting was observed at scattered locations which have resulted in pitting of 1-1.5 mm depth at few locations. This was also observed during previous inspection.
- Superficial abrasion marks were observed on liner segments.
- Gas outlet nozzle liner was found in satisfactory condition, however a fine crack of approx. 400 mm was observed at its weld junction with shell liner. Same was observed during previous inspection also. Refractory behind it was found intact as seen through gap.
- 2nd course was found to have metal dusting attack resulted in approx. 1-3 mm deep pitting in approx. 40 % surface area of liner segment and erosion of its longitudinal weld seam by approx. 2-3 mm in its complete length below the liner

surface. Its circumferential weld was found slightly eroded in approx. 80% of its length. This was also observed during previous inspection also.

- Uniform gap was observed between the 1st & 2nd pieces of the liners.

2nd Liner Piece from top

- Surface Abrasion marks were observed approx in 150mm circumferential length in South-East side due to rubbing of the tube bundle.
- Minor metal dusting attack observed on shell liner resulted in pitting of approx.1.0 mm depth at few locations in approx. 5 % of the liner surface area. This was also observed during previous inspection.
- Inward bulging of approx. 300 mm was observed at South-West and South-East side.
- Long seam weld was found slightly eroded in approx. 250 mm length.
- A gap of approx. 10mm to 60mm observed east side between loose liner and 3rd shell liner piece in entire circumference, causing exposure of refractory. However, condition of the refractory exposed in between seems to-be intact and observed to same as during previous inspection.

3rd Liner Piece from top

- Uneven gap observed on expansion joint. East half has 2-4 mm gap between liner segments where as 15-20 mm gap was observed in remaining half. The same was also observed in previous inspection also.
- Inward bulging approx 3"X3" observed at West side of the shell.

4th Liner Piece from top

- Circumferential weld joint just at the level of the gas distributor bulged and cracked in approx. 60% of its length.

Gas Distributor

- Gas distributor was found deformed inwards from both the sides.
- Gas distributor header found chocked by alumina bolls at few perforated holes.

103-E2 LP, LP FLASH VESSEL

SECOND MANHOLE COMPARTMENT (FROM TOP)

- Rectangular riser box and other fittings found intact in position.
- Holding bolts of bottom tray found loose and bent at many locations. 02 nos. bolts are missing from at north side.



- Silver coloration observed at scattered locations. Weld joints observed as if etching has occurred resulting in slightly differing color in comparison to adjacent shell surface.
- 01. no. 3" bubble cap tray drain line was found broken at North-West side and same was lying on the rectangular riser box. End plate of same 3" line was broken and found lying on the bottom tray.



- 01. no. 3" bubble cap tray drain line was found having crack in the 75% of the circumference weld.



BOTTOM MANHOLE COMPARTMENT (FROM OUTSIDE)

- Vortex plate of the header found intact in position.
- Silver coloration observed at scattered locations.

105-E, DEHYDRATOR (FROM OUTSIDE)

FROM BOTTOM DOME

- Bubble cap holding plate found satisfactory.
- Bubble cap surface found oily.
- Distribution header flange bolt found intact.

FROM TOP DOME

- Bubble cap holding plate found satisfactory.
- Demister pads found intact in position.
- Loose scaling found at bottom of the manhole manway.
- Debris was found lying on the bubble cap plate.
- Oily surface found on bubble cap.
- Brownish coloration observed inside the shell.

STEAM DRUM (101-F)

- Grayish black coloration was observed inside the drum.
- All Cyclone Separators were found intact in position.

- Demister pads were found intact in position.
- Minor pitting of approx. 0.5 to 1.0 mm depth was observed at scattered locations.
- One of the holes at south end of phosphate dozing line (1" NB) was found enlarged.
- Few bolts and clamps of Demister Pad holding cover plate were found loose/missing.
- Grill covering the Down Comers were found bent at few locations.
- 6" BFW header found bent from centre and nut-bolts found missing at the same location.
- 02 nos. bolts found loose at flange joint of 6" BFW header.
- 01 no. cap nut chocked in 1" blow off line at bottom of the shell.

102-F , RAW GAS SEPARATOR

- Epoxy paint found peeled off/cracked on few locations at north side of shell.
- Epoxy paint found peeled off on vertex plate of condensate outlet.
- Demister pads were found intact in position.
- Putty applied on the circumferential weld joint of manhole nozzle with shell from inside was found detached at one location in East side.
- Condition of Gas inlet nozzle located at East side was found satisfactory.

103-F, REFLUX DRUM

- Demister pads were found intact in its position.
- Epoxy paint/primer was found peeled off from the few small scattered locations at the dish end and bottom half of the vessel.
- Scales of epoxy paint were found sticking with Mesh of Demister pads.

104-F, SYNTHESIS GAS COMPRESSOR SUCTION DRUM

- Grayish black coloration was observed on bottom area, whereas brownish Coloration was observed on remaining surface.
- Condition of weld joints was found satisfactory.
- Thin scales were observed at bottom dish end.
- Condition of demister pad was found satisfactory.
- Blackish coloration was observed inside the inlet hood baffle.
- Condition of the inlet hood baffle was found satisfactory.
- Condition of the nozzle weld joints was satisfactory.
- Bottom vortex breaker was clear and its welds were found intact.

105-F, SYN. GAS COMPRESSOR 1ST STAGE SEPARATOR

- The coloration of vessel was brownish black from inside.
- Demister pads were found intact in position.

Annexure – 3(5/5)

CREEP MEASUREMENT OF PRIMARY REFORMER RISER TUBES AT SLAB LEVEL:

Riser No.	N- S	E- W	Creep in Percentage		
			0 – 0.33	0.33 – 1.10	1.10 – 1.44
1	125.64	125.80			X
2	125.41	125.09		X	
3	125.48	125.45		X	
4	125.57	125.48		X	
5	125.76	125.69			X
6	125.57	125.50		X	
7	125.41	125.38		X	
8	125.28	125.31		X	

* Design O.D. of Riser = 124.44^{+1}_{-0}

GAUSS MEASUREMENT

Measurement of residual magnetism (Gauss) on rotary and stationary parts of BFW pump (P-5111) and its drive turbine bearings was carried out. Wherever residual magnetism was higher than acceptable limits, same was demagnetized and brought down within acceptable limits.

GAUSS MEASUREMENT OF EQUIPMENT

BFW Pump Drive turbine (Q-5111)		
Journal Bearing Coupling Side	Top	0.4
	Bottom	0.7
Journal Bearing Governor Side	Top	0.6
	Bottom	0.7
Shaft Journal	Thrust End	1.5
	Non Thrust End	1.3
BFW Pump (P-5111)		
Journal Bearing Free End	Top	0.9
	Bottom	1.0
Journal Bearing Coupling side	Top	1.2
	Bottom	0.9
Thrust Bearing Pads	Active	0.7
	Inactive	0.4
	Inactive	0.6
Thrust Collar		0.9
Shaft Journal	Thrust End	1.2
	Non Thrust End	0.9

INSTRUMENTATION

- A new logic was defined for operation of TY-142A, now if TRC-142 MV > 25% then TY-142A MV=100.
- Data was collected for all HIS & FCS in Project backup for reference.
- All Operator stations & engineering station Anti-virus software was updated.
- Control room dust level & temperature was observed & found within limit.
- Cooling fan for HIS 0157 was replaced with new one.

PROSAFE-RS ESDS

- For Prosafe-RS ESD following shutdown/ preventive maintenance activities were carried out as per the AMC procedure :
- Cleaning of filters, fans, cabinets etc. was carried out for all the three SCS.
- Redundancy of all the CPU, PS, V net / IP Bus and IO cards was checked and found ok.
- Latest Back up was taken on DVD media.
- New DI Card SDV141 was defined in SCS0107 at node-2 slot-3 & slot-4.
- New tags PSH73B & PSH79C were defined in SCS0107, also new 2oo3 logic was made for low vacuum trip of 101-J/103-J/105-J in SCS0107 & SCS0108.
- In SCS0107 PH Value of ANLG_S block for tag LI472-A, B & C was changed from 90 to 100.
- Fuse TB of ESD Marshalling cabinet C-273, C-274 & C-275 was replaced with new one.

FUJI UPSS

Servicing of UPSS was carried out. Air filters of all the cabinets were cleaned and the exhaust/cooling fans were checked. Voltage on all the test points were measured. Both UPSS Power supply was switched off & total load was taken on battery bank for one & half hours. Before load transfer voltage was 229 V at 52 A & after load transfer, voltage was 209 V at 52 A. Also load was transferred on AVR & change-over was found ok. After one hour power for both UPSS were switched on & found ok. Battery cleaning, cell voltage measurement & electrolyte level checking were done.

Electrolyte level top-up was done for battery cells wherever required. Alarm & trip setting for UPSS were checked & found ok. Software data were checked by UPS Loader & the same was found ok. Tightening of all control cables & sockets were done.

ON LINE GAS ANALYZER

- Preventive maintenance of CH₄ analyzer AR-2 and Hydrogen analyzer ARC-3 was carried out. Cleaned sample path by flushing it with air jet. Cleaned sample conditioning system.
- Manual Calibration of both the analyzers were performed & found ok.

CAPITAL JOBS CARRIED OUT IN ANNUAL TURNAROUND

FICV-20 : New control valve was installed in line. Stroke checked, found ok.

TRCV-142A : Control valve was replaced with new one. Related cabling & tubing jobs were carried out. Control valve operation logic was developed in DCS. Stroke was checked, found ok.

LCV-16, LCV-18 & LCV-19 : Old control valves were replaced with new control valves. Related signal cable & air supply tubing work was carried out. Finally control valve stroke was checked and found ok.

EWR / SUGGESTION SCHEME / RECOMMENDATION COMMITTEE AND TECHNICAL DEPT. RELATED JOBS:

MIC-10 : Old control valve was replaced with new control valve. Related signal cable & air supply tubing work was carried out. Finally control valve stroke was checked and found ok.

HIC-435A : A new control valve was installed in parallel with HICV-435 for operation flexibility.

VS-203A : A new On-Off control valve was installed in line. A new Solenoid valve was also installed for its operation. Related cabling & tubing jobs were carried out. Logic was prepared for it's operation. Checked & found ok.

CONTINUAL IMPROVEMENT

LT-471 : New RADAR Level transmitter was installed in CO2 Absorber, related fabrication work was done, cable laying, dressing & termination work was also done in field side & marshalling cabinet end.

LCV-16 : Old control valve was replaced with new control valve. Related signal cable & air supply tubing work was carried out. Finally control valve stroke was checked and found ok.

LCV-18 : Old control valve was replaced with new control valve. Related signal cable & air supply tubing work was carried out. Finally control valve stroke was checked and found ok.

LCV-19 : Old control valve was replaced with new control valve. Related signal cable & air supply tubing work was carried out. Finally control valve stroke was checked and found ok.

UREA PLANT
(INSTRUMENTATION)

CONTROL VALVES MAINTENANCE JOBS

HICV-1421 : Valve was dropped from the line and was replaced by spare overhauled valve. Valve was boxed up with new teflon seat and checked for operation. Also replaced its SOV, HCO-1423 with a new one. After mounting the proximity switches for ON and OFF position sensing, checked valve operation.

HICV-1201 : Valve was opened from the bonnet and overhauled the trim parts. All other parts were cleaned & overhauled. Replaced the pneumatic positioner and position transmitter with new one. Provided new gland packing and seal rings. The valve was installed back in the line then carried out control valve stroke checking and calibration of position transmitter.

LRCV-1201 : Valve was dropped from the line. Replaced its damaged plug and seat of MOC: Safurex with that of MOC: HVD1. Provided new gland packing set and sealing rings for seat and bonnet. All parts were cleaned & overhauled. The valve was installed back in the line then carried out control valve stroke checking and calibration of position transmitter.

FRCV-1201 : The control valve was opened from the bonnet. Valve was found stuck up due to metal chips trapped in between plug and seat, and due to which plug and seat got damaged. Replaced the damaged plug and seat with spare one. Also replaced seat and bonnet gaskets. The valve was boxed up with new gland packing set and then control valve operation and stroke checking were carried out.

PICV-1128 : The control valve was opened from the bonnet. To solve passing problem machining was done over its trim parts after which lapping and blue test of seating area was performed. Boxed up the valve with new seat and bonnet gaskets and provided new gland packing set. Also replaced air pressure regulator of valve positioner and overhauled valve positioner. Finally the valve was assembled and operation and stroke checking were carried out.

FICV-1303 : Valve was opened from bonnet. Machining was done over its trim parts. All parts were cleaned & overhauled and provided new gland packing. Finally the valve was assembled and operation and stroke checking were carried out.

PICV-1202 : Valve was dropped from the line. Lapping was done on plug and seat. Provided new flange gasket & gland packing. All parts were cleaned & overhauled. Finally control valve was boxed up and checked valve operation and valve stroke.

FICV-1281 : Valve was dropped from the line. Overhauled the trim parts, provided new gland packing and flange gaskets. Box up the, control valve mounted it in line and checked control valve operation and valve stroke.

HICV-1206 : Valve was opened from bonnet. All parts of valve were cleaned and overhauled. Boxed up the valve with new gland packing set. Finally control valve operation and valve stroke were checked.

HICV-1207 : Valve was dropped from the line. Replaced the plug and seat with new one. Also replaced its actuator diaphragm. Provided new flange gaskets and gland

packing. All parts were cleaned & overhauled. Hydro test was carried out and valve was installed back in the line. Finally control valve operation and valve stroke were checked.

LICV-1351 & LICV-1352 : Valves were dropped from the line. The plug stems found broken. Replaced plug, seat and guide bush with new one. General cleaning & overhauling of its internals was done. Valves were boxed up with new gland packing set and operation and stroke were checked.

LICV-1502A : Valve was opened from the bonnet. All parts were checked, cleaned and overhauled. Replaced its gland packings. Valve was assembled and its operation and stroke were checked.

PICV-1130 & PICV-1181 : General checking of control valves, actuators and valve positioners were carried out. Valve stems were taken down for tight shut-off. Then control valve operation and stroke checking were carried out for both control valves.

PRCV-1201 & HICV-1202 : General checking of control valves, actuators and valve positioners was carried out. Valve positioner was overhauled and stroke checking was done.

CICV-1422 : Control valve was removed from line and checked operation of inside ball during ON /OFF condition. Boxed up valve with new flange gaskets.

PRCV-1481 : Overhauled the valve positioner and its pneumatic relay was replaced with new one. Also provided new air pressure regulator and booster relay. The current to pneumatic (I to P) converter was calibrated and then valve operation and stroke checking were carried out.

LICV-1807 : Control valve was removed from line for clearance to Mech. maint section. Same was fixed back in line after overhauling. General operation and stroke checking were carried out.

Replaced the gland packings for the following control valves :

FICV-1351, TRCV-1422, FRCV-1421, HICV-1211, , LICV-1203 , PICV-1979A & PICV-1979B

General cleaning & stroke checking of following control valves was carried out.

PICV-1129, FICV-1102, PRCV-1202 , FICV-1204, PICV- 1502A/B, LICV1502A/B, TRCV-1202, HICV-1221A/B, TRCV-1102, HICV-1222A/B

COMPRESSOR HOUSE JOBS

- All the temp. and pressure gauges were removed to facilitate mechanical jobs. Same were checked and fixed back after completion of jobs. Faulty temp. and pressure gauges were replaced with new one.
- All bearing RTDs in turbine, HP case, LP case & Gear Box were removed to facilitate mechanical jobs. Same were checked and re-fixed after the completion of jobs. One simplex RTD for TI-1829 and one duplex RTDs for TI-1827 and TI-1828 were replaced with new one.
- All vibration probe for Radial, Axial and key-phaser points in turbine, HP case, LP case and Gear Box were removed to facilitate mechanical jobs. After completion of jobs, the same were re-fixed. Gap voltage adjustments for radial, axial and

keypads probes were carried out. Replaced the axial vibration probe XE-1808A and its housing/head type junction box by new one. Extension cables were replaced for vibration probes XE-1804A and XE-1804B.

- The faulty DPM on local control panel for TI-1803(2nd stage suction temperature) was replaced with new OMRON make DPM and its configuration was done.
- Following pressure switches for two out of three trip logic function for CO₂ compressor trip logic I-1800 were replaced with Pressure transmitters thereby providing live readings and switching actions through DCS to improve reliability of trip logic.

PSLL-1801A, PSLL-1818A, PSLL-1838A, PSHH-1839A, PSHH-1843A
PSLL-1801B, PSLL-1818B, PSLL-1838B, PSHH-1839B, PSHH-1843B

- Following pressure switches for Alarm and Trip functions were cleaned, checked and their settings were checked.

PSLL-1801C, PSLL-1818C, PSLL-1838C, PSHH-1839C, PSHH-1843,
PSL-1816, PSL-1812, PSL-1813, PSLL-1844

- Following low level and high level switches of separators & surface condenser were cleaned, checked and calibrated.

LSHH-1804, LSHH-1806, LSHH-1808, LSL-1824, LSHH-1822 & LSL- 1823.

- Following leveltrols for separators & surface condenser were cleaned, checked and calibrated.

LICT-1803, LICT-1805, LICT-1807 & LICT-1821

- Following old trip Solenoid valve were replaced with new ASCO make solenoid valves for reliability improvement.

HV-1801, HV-1803 and PV-1810 respectively for HICV-1801, HICV-1803 and PICV-1810.

- All the field Junction Boxes, Local Control Panel and turbine local control boxes were cleaned and all wiring connections were tightened.

- Mock up test was carried out for Woodward governor for CO₂ Compressor for HP and LP Valves stroke checking. Also checked the stroking for admission steam valve. Calibration of all three I to H converter (HP valve, LP valve and admission steam valve) was also checked.

- General cleaning & stroke checking of following control valves was carried out.

HICV-1801, HICV-1802, HICV-1803, PICV-1810, LICV-1803, LICV-1805,
LICV-1807, LICV-1821A/B, PICV-1979A/B

FIELD JOBS

- HP Stripper's and Autoclave's Pressurised as well as empty count readings for LRC-1201 & LR-1201 detectors were taken and recorded.

- Radioactive source of LR-1201 was removed from its mounting at Autoclave to facilitate mechanical maintenance jobs. This decayed radioactive source of Autoclave was shifted and stored in underground pit made for the purpose. After

pHICV-4401 & pHICV-4402 : Cooling tower Ammonia & Urea side NaOH dosing pH control valves were replaced with new one. Related signal cable & air supply tubing work was carried out. Finally control valve stroke was checked and found ok.

CONTINUAL IMPROVEMENT

MCC interface Relay Box Replacement Job

Following are the details of jobs carried out for Relay box replacement :

- Existing old relay box was removed from its location. Cables were removed from old relay box & interfacing JB inside MCC-15.
- New relay box was installed in place of old one. Fabrication work was carried out for new mounting frame for relay box.
- Cable glanding, wiring, ferruling & termination work was done.
- New ferruling, lugging & termination work was carried out in MCC-15 interfacing junction box as well as Marshalling cabinet end.
- Finally all tags (MOV, Selector Switches) operation were checked from control room & found ok.

ELECTRICAL

Non plant

Preventive maintenance of transformer: Preventive maintenance of TR-10A, 10B, T/S-1 and T/S-2 was carried out as per detail given below

Common activity carried out during transformer maintenance is as under:

- Isolation of transformer from both side (LT & HT)
- Dismantling of HV & LV terminal box.
- Visual inspection about any leakage of oil from any part and any heated terminal.
- Measurement of earthing resistance, IR value, PI value and oil BDV.
- Testing of Buchholz relay about its function of tripping and alarm.
- Condition of silica gel was checked. Accordingly discharged silica gel was replaced
- Tightening of loose parts.
- Cleaning and washing.

Preventive maintenance of MCC

Preventive maintenance of all the feeder compartment fire MCC was carried out.

Common activity carried out during MCC maintenance:

- Isolation of MCC from power source.
- General cleaning of all feeders.
- Tightness checking of all power and control cable connection.
- Checking & cleaning of contactors.
- Checking of operation of breaker in test position.
- Checking continuity and IR value of bus bar.
- Lamp test.
- Normalization of MCC.

CIVIL

TECHNICAL

BAR CHART

